## UI ID STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM	( APP	RO'	VΘ
OMB !	No. I	004	013
Expire	s July	31.	199

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				LC 029405B		
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or CA	VAgreement, Name and/or No.		
I. Type of Weil  Oil Weil  Gas Well	Other Injection	on Well		8. Well Name :	and No.	
Name of Operator Conoco, Inc.				M.C.A  9. API Well No	. Unit #256	
3a. Address 3b. Phone No. (include area code)			30-02	5-23509		
10 Desta Dr St.100W Midland TX 79705 915-686-5424  Location of Well (Footage, Sec., T., R., M., or Survey Description)				ol, or Exploratory Area nar GB-SA		
Un. Ltr. "I", 29 Section 20, T-1		10' FEL		11. County or Pa	urish, State Dunty, New Mexic	
12. CHECK AP	PROPRIATE BOX(ES) T	O INDICATE NA	TURE OF NOTICE, F	REPORT, OR O	THER DATA	
TYPE OF SUBMISSION			TYPE OF ACTION			
Notice of Intent  Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construct	Production (State Reclamation Recomplete		Water Shut-Off Well Integrity Other	
☐ Final Abandonment Notice	Change Plans Convert to Injection	Plug and Aban Plug Back	don			
2. Spot 25 sxs of 3. Spot 25 sxs of 4. Perforate the 5. Set a cement at 800'. A 6. Perforate the 7. Circulate 80 8. Install dryho	ctionally or recomplete horizont ne work will be performed or prolived operations. If the operational Abandonment Notices shall for final inspection.)  2. at 3525'. Comment on top of the comment on top of the comment plug 220's for final inspection.  2. at 3525'. Comment on top of the comment of the comment plug 220's for final inspection.  3. at 3525'. Comment of the comment plug 220's for final inspection.	tally, give subsurface I rovide the Bond No. of con results in a multiple be filed only after all circulate he f. C.I.B.P.  0'-2450'.  at 800'.  5' and sque at 300'.  u perfs at	requirements, including recompletion requirements, including recompletion at 3525'.—  Tag Plug.  Deze 35 sxs ce	ement thru	MISSION MUST BE CONTINUED TO SHALL BE CONTIN	
14. I hereby certify that the foregoin Name (Printed/Typed)	(Kes		Sr. Stoff Regu	Llatory As	st·	
Signature Rillsa Wi	lkas	Da	8-25-00	·		
	THIS SPACE	FOR FEDERAL	OR STATE OFFICE US	E		
Approved by			Title	Date		
Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant to	al or equitable title to those rig					

## CURRENT WELLBORE 8/7/00 Elev. = 4007' GL +8' KB\_T.O.C. © 28' Packed w/Pea Gravel to Surface 748' - 8 5/8" Casing. Cemented w/300 sxs. . T.O.C. @ 2400' (Temp. Survey) Perfs 3579'-3588' Sqz'd Perfs 3597'-3603' Perfs 3686'-3704' Perfs 3808'-3821' Sqz'd Perfs 4026'-4066' Perfs 4084'-4087' Sqz'd w/150 sxs 4145' - 5 1/2", 14#, Casing. Cemented w/300 sxs T.D. @ 4145' CONOCO, INC. M.C.A. Unit #256 2590' FSL & 1310' FEL

Sec. 20, T-17S, R-32E

Lea County, NM

## PROPOSED PLUG AND ABANDONMENT 8/7/00 Elev. = 4007' GL + 8' KB\_T.O.C. © 28' Packed w/Pea Gravel to Surface PERFORATE 5 1/2" CASING AT 300' CIRCULATE 80 SXS CEMENT THRU PERFS AT 300' AND FILL HOLE TO SURFACE MUD SET A CEMENT RETAINER AT 675' SQUEEZE 35 SXS CEMENT THRU PERFS AT 800' 748' - 8 5/8" Casing. Cemented w/300 sxs. PERFORATE THE 5 1/2" CASING AT 800' MUD SPOT 25 SXS CEMENT 2200'-2450' (TAG PLUG) T.O.C. © 2400' (Temp. Survey) MUD SPOT 25 SXS CEMENT ON TOP OF C.I.B.P. SET A C.I.B.P. AT 3525' Perfs 3579'-3588' Sqz'd Perfs 3597'-3603' Perfs 3686'-3704' Perfs 3808'-3821' Sqz'd Perfs 4026'-4066' Perfs 4084'-4087' Sqz'd w/150 sxs $4145' - 5 \frac{1}{2}$ ", 14#, Casing. Cemented w/300 sxs T.D. @ 4145' CONOCO, INC.

M.C.A. Unit #256

Lea County, NM

2590' FSL & 1310' FEL Sec. 20, T-17S, R-32E