#### N.M. OIL CONS. COMMISSION P.C VOX 1980 HODES, NEW MEXICO 88240

Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Serial No.
		6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals		
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Well Other		89200034/0
Well Well Other  2. Name of Operator		MCA Unit #262
Conoco Inc.  3. Address and Telephone No.		9. API Well No.
10 Do Star Dr. Ste 100 w Midland Tx  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		30 - 025 - 23660  10. Field and Pool, or Exploratory Area
	= 015-686-5425 = WL	Maljamor Coryb-SF  11. County or Parish, State
Sec. 21, T-175, R-32E		Lea NM
12. CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion Plugging Back	New Construction Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing Other	Conversion to Injection Dispose Water
		(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)
Describe Proposed or Completed Operations (Clearly state a give subsurface locations and measured and true verti	  Il pertinent details, and give pertinent dates, including estimated date of starting   cal depths for all markers and zones pertinent to this work.)*	
give subsurface locations and measured and true verti	cal depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled
give subsurface locations and measured and true verti	cal depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled
give subsurface locations and measured and true verti	cal depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled
give subsurface locations and measured and true vertice.  1. Pull RBP.  2. Set CIBP a  3. Load hole with	3550 w/5 SXS cement to this work.)	any proposed work. If well is directionally drilled,  ton top.  ud  between
give subsurface locations and measured and true vertice.  1. Pull RBP.  2. Set CIBP D  3. Load hole with the control of the co	3550 w/5 SXS cement to this work.)*  3550 w/5 SXS cement to this work.)*  th 10 ppg brine gel m  830 Circulate ceme  eave 100 inside 5/2"	any proposed work. If well is directionally drilled.  I on top.  ud  between
give subsurface locations and measured and true vertice.  1. Pull RBP.  2. Set CIBP a  3. Load hole with the set of the s	3550 w/5 SXS cement  th 10 ppg brine gel m  830'. Circulate ceme  eave 100' inside 5/2"  s Surface Pug	any proposed work. If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,
give subsurface locations and measured and true vertice.  1. Pull RBP.  2. Set CIBP a  3. Load hole with the set of the s	3550 w/5 SXS cement  th 10 ppg brine gel m  830'. Circulate ceme  eave 100' inside 5/2"  s Surface Pug	any proposed work. If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,
give subsurface locations and measured and true vertice.  1. Pull RBP.  2. Set CIBP a  3. Load hole with the set of the s	3550 w/5 SXS cement to this work.)*  3550 w/5 SXS cement to this work.)*  th 10 ppg brine gel m  830 Circulate ceme  eave 100 inside 5/2"	any proposed work. If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,
give subsurface locations and measured and true vertice.  1. Pull RBP.  2. Set CIBP a  3. Load hole with the set of the s	3550 w/5 SXS cement  th 10 ppg brine gel m  830'. Circulate ceme  eave 100' inside 5/2"  s Surface Pug	any proposed work. If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,
give subsurface locations and measured and true vertice.  1. Pull RBP.  2. Set CIBP a  3. Load hole with the set of the s	3550 w/5 SXS cement  th 10 ppg brine gel m  830'. Circulate ceme  eave 100' inside 5/2"  s Surface Pug	any proposed work. If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,  the ontop.  If well is directionally drilled,
give subsurface locations and measured and true vertice.  1. Pull RBP.  2. Set CIBP and  3. Load hole with the formula of the second of the state of the second of the sec	3550' w/5 SXS cement  th 10 ppg brine gel m  830'. Circulate ceme  eave 100' inside 5/2"  s Surface Ping  ker and clean location	any proposed work. If well is directionally drilled.  I on top  we have en  Date 11/1/0/94

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED

NOV 23 1994 OCD HOBBS OFFICE

## <u>CURRENT</u> (11/94) MCA NO. 262

85/8", 2780' W/350 ses Circulated

T.DC. 2900' Temp. Survey

Perfs 3595-3605' 592'd

Perfs 3709'-3754'

Perfs 3823'-3839' 592'd

5/2", 14# @ 4145 w/250 sxs

TD 4145'

# MCA NO. 262 10 sxs Surface Plug

730'

85/8" 2780' w/350 &s Circulated
Perforate at 830' and circulate

Cement between 5/2 and 85/8

to surface

T.OC. 2900' Temp. Survey

CIBPO 3550' W/5 sxs coment

Perfs 3595-3605' 59z'd Perfs 3709-3754' Perfs 3823'-3839' 59z'd

51/2", 14# @ 4145' w/250 sxs

TD 4145'

### BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

#### Permanent Abandonment of Wells on Federal Lands

#### Conditions of Approval

- 1. Approval: Plugging operations shall commence within 90 days from the approval date of plugging procedure.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Eddy County call (5Ø5)887-6544; for wells in Lea County call (5Ø5) 393-3612.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

- 6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show <u>date</u> well was plugged.

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

RECEIVED

NOV 7 3 1994

CEFICE