. C COPIES RECEIVED		Form C-103
TRIBUTION		Supersedes Old
CT ~ FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
U.S.G.S.	-	5a. Indicate Type of Lease
	-	State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		<u> </u>
DO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS IOPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT -*** (FORM C-101) FOR SUCH PROPOSALS.)	
	TION FOR PERMIT OF (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL	OTHER-	Not required
Name of Operator		8. Farm or Lease Name
Anderson 011 & Gas	s Company, Inc.	Garrett State
. Address of Operator		9. Well No.
250 Mid-America B	uilding, Hidland, Texas 79701	1
. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER N. 2080 FEET FROM THE West LINE AND 560 FEE		Undesignated
THE South LINE, SECT	ION 31 TOWNSHIP 16-5 RANGE 30-0 NN	мем. <u>АШШШШШ</u>
	15. Elevation (Show whether DF, RT, GR, etc.) GL 3734	12. County
		Lea
	Appropriate Box To Indicate Nature of Notice, Report or	
NOTICE OF I	SUBSEQUI	ENT REPORT OF:
	PLUG AND ABANDON REMEDIAL WORK	
PERFORM REMEDIAL WORK		
		ALTERING CASING
EMPORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING Plug and Abandonment
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	L L
EMPORARILY ABANDON	COMMENCE DRILLING OPNS.	L L
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Completed O work) SEE RULE 1103. 5/72 Plugged an	CHANGE PLANS COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB OTHER perations (Clearly state all pertinent details, and give pertinent dates, included ad abandoned well w/cement nlyze out	PLUG AND ABANDONMENT
TEMPORARILY ABANDON DULL OR ALTER CASING OTHER 7. Describe Proposed or Completed O work) SEE RULE 1103. 5/72 Plugged an @12,200'; @6600' 40 between pl 0/72 Cut off br too wet to mately 6 w 5/72 Broke out 1/74 Moved in C surface pl 5/74 Shot 8 5/8 up 2 3/8" 1080' to 9 446' to 32 from 15' t 8.115' t	CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB OTHER other perations (Clearly state all pertinent details, and give pertinent dates, include ad abandoned well w/cement plugs set as 25 sx. (75') 910,000': 25 sx. (75') 98 sx. (120') 95200' and 10 sx. (30') 9 s ugs 9.8#/gallon. aden head and installed well location break out at present time, will be br ks. pits. Cleaned and levelled location. asing Pullers Inc. removed well marker ug, and worked 8 5/8" casing. " casing 9 1033' and pulled 1033' of 8 tubing and ran in well to 1080', spott 53'. Pulled tubing to 446' and spotte 3'. Laid down remainder of tubing and o the surface. All plugs separated w	PLUG AND ABANDONMENT ing estimated date of starting any propositions follows: 25 sx. (? 900': 40 sx. (120') surface; mud weight marker. The pits are oken out in approxi- . Drilled out the 5/8" casing. Picked id 60 sx plug from spotted 10 sx plug 9.8# mud.
TEMPORARILY ABANDON Pull OR ALTER CASING OTHER 7. Describe Proposed or Completed O work) SEE RULE 1103. 5/72 Plugged an 012,200'; 06600' 40 between pl 0/72 Cut off br too wet to mately 6 w 5/72 Broke out 1/74 Moved in C surface pl 5/74 Shot 8 5/8 up 2 3/8" 1080' to 9 446' to 32 from 15' t 5/74 Reinstaller up location	CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER OTHER OTHER Derations (Clearly state all pertinent details, and give pertinent dates, include ad abandoned well w/cement plugs set as 25 sr. (75') 310,000'; 25 sr. (75') 35 sr. (120') 35200' and 10 sr. (30') 3 s ugs 9.8#/gallon. The head and installed well location break out at present time, will be br break out at present time, will be br break. Pullers Inc, removed well marker ug, and worked 8 5/8" casing. " casing 3 1033' and pulled 1033' of 8 tubing and ran in well to 1080', spott 53'. Pulled tubing to 446' and spotte 3'. Laid down remainder of tubing and o the surface. All plugs separated w d well location marker and cutoff surf n, filled and levelled pits. Location above is true and complete to the best of my knowledge and belief.	PLUG AND ABANDONMENT ling estimated date of starting any propose s follows: 25 sr. (7) 900': 40 sr. (120') surface; mud weight marker. The pits are oken out in approxi- . Drilled out the 5/8" casing. Picked sed 50 sr plug from spotted 10 sr plug 9.8# mud. ace anchors. Cleaned ready for inspection
TEMPORARILY ABANDON Pull OR ALTER CASING OTHER 7. Describe Proposed or Completed O work) SEE RULE 1103. 5/72 Plugged an 012,200'; 06600' 40 between pl 0/72 Cut off br too wet to mately 6 w 5/72 Broke out 1/74 Moved in C surface pl 5/74 Shot 8 5/8 up 2 3/8" 1080' to 9 446' to 32 from 15' t 5/74 Reinstaller up location	CHANGE PLANS CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Derations (Clearly state all pertinent details, and give pertinent dates, include abandoned well w/cement plugs set as 25 sr. (75') 310,000': 25 sr. (75') 35 sr. (120') 35200' and 10 sr. (30') 3 s ugs 9.8#/gallon. The head and installed well location break out at present time, will be br ks. pits. Cleaned and levelled location. asing Pullers Inc. removed well marker ug, and worked 8 5/8" casing. " casing 3 1033' and pulled 1033' of 8 tubing and ran in well to 1080', spott 53'. Pulled tubing to 446' and spotte 3'. Laid down remainder of tubing and o the surface. All plugs separated w d well location marker and cutoff surf n, filled and levelled pits. Location	PLUG AND ABANDONMENT ling estimated date of starting any propose s follows: 25 sr. (7) 9,900': 40 sr. (120') surface; mud weight marker. The pits are oken out in approxi- . Drilled out the 5/8" casing. Picked sed 50 sr plug from spotted 10 sr plug 9.8# mud. ace anchors. Cleaned ready for inspection
TEMPORARILY ABANDON Pull OR ALTER CASING OTHER 7. Describe Proposed or Completed O work) SEE RULE 1103. 5/72 Plugged an 012,200'; 06600' 40 between pl 0/72 Cut off br too wet to mately 6 w 5/72 Broke out 1/74 Moved in C surface pl 5/74 Shot 8 5/8 up 2 3/8" 1080' to 9 446' to 32 from 15' t 5/74 Reinstaller up location	CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER OTHER OTHER Derations (Clearly state all pertinent details, and give pertinent dates, include ad abandoned well w/cement plugs set as 25 sr. (75') 310,000'; 25 sr. (75') 35 sr. (120') 35200' and 10 sr. (30') 3 s ugs 9.8#/gallon. The head and installed well location break out at present time, will be br break out at present time, will be br break. Pullers Inc, removed well marker ug, and worked 8 5/8" casing. " casing 3 1033' and pulled 1033' of 8 tubing and ran in well to 1080', spott 53'. Pulled tubing to 446' and spotte 3'. Laid down remainder of tubing and o the surface. All plugs separated w d well location marker and cutoff surf n, filled and levelled pits. Location above is true and complete to the best of my knowledge and belief.	PLUG AND ABANDONMENT ling estimated date of starting any propose s follows: 25 sr. (7 3,900'; 40 sr. (120') surface; mud weight marker. The pits are oken out in approx1- . Drilled out the 5/8" casing. Picked sed 50 sr plug from spotted 10 sr plug 9.8# mud. ace anchors. Cleaned ready for inspection