				30-025-2395
Form 3160-5 November 1983) Formerly 9-331)	UNITED DEPARTMENT OF BUREAU OF LAN	THE INTERIO	3UBMIT IN TRIPLICAT (Other Instructions on verse side)	C. LEASE DESIGNATION AND BEEN
	NDRY NOTICES AN	D REPORTS ON		0. IN INDIAN, ALLOTTEE ON THIS
1. OIL GAN WELL WELL	🗆 отнака 🗙 Х. Ree	ntry		7. UNIT AGRELMENT NAME
2. NAME OF OPERATOR MANZAN	NO OIL CORPORATION			B. FARM ON LEASE NAME Winn Federal
3. ADDRESS OF OPERAT		swell New Movi		9. WELL NO.
4. LOCATION OF WELL (See also space 17 be At surface	Treport location clearly and in a	accordance with any Stat	e reguirements.*	1 10. FIELD AND POOL, OF WILDCA
1980' Uni	FNL and 660' FEL			Garrett - Drenk 11. BBC., T., B., M., OB BLE. AND HDEVET ON AREA
14. PERMIT NO.		NS (Show whether Dr. RT.	GE etc.)	Sec. 29, T 16S, R 12. COUNTY OF PARIANI 13. 6TA
		<u>5' GR</u>		Lea NM
16.	Check Appropriate B	ox To Indicate Natu	re of Notice, Report, or	ينسن بينجي بيرج سواني معان بجمعه فكالمناف والمتعالية والمتعاد والمتعاد والمتعاد والمتعاد والمتعاد والمتعاد والم
	NOTICE OF INTENTION TO :		5U 365	QUENT REPORT OF :
TEST WATER SHUT- Practur, treat Sngut or acidize Repair well	OFF FCLL OR ALTER MULTIPLE COMI ABANDON* CHANGE FLANS		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	ABANDONMENT*
(Other)				ts of multiple completion on Well
12-28-89 Rec	eived verbal approv		alls, and give pertisent date and measured and true verti	n. to plug and abandor
12-28-89 Rec 01-03-90 TA Spo Tag Spo	eived verbal approv to P&A t 80 sacks Class C cement top @ 690'. t 26 sacks Class C	val from Adam ø and 3% CaCl @ . Spot 51 sack neat from 60'	Alls, and give perturned date and measured and cove verti Salameh @ 1:35 p.1 TD of 852'. s Class C neat (1) back to surface.	metion Report and Log form.) a, including estimated date of start cal depths for all markers and gone m. to plug and abandon 00') from 446' to 346' Have 10.4 lbs. mud
12-28-89 Rec 01-03-90 TA Spo Tag Spo b	eived verbal approv to P&A t 80 sacks Class C cement top @ 690'.	val from Adam ø and 3% CaCl @ . Spot 51 sack neat from 60' down. Set dry	Alls, and give perturned date and measured and covered Salameh @ 1:35 p.1 TD of 852'. s Class C neat (10 back to surface. hole marker. We	metion Report and Log form.) M. Including estimated date of start cal depths for all markers and gone m. to plug and abandon 00') from 446' to 346' Have 10.4 lbs. mud 11 P&A. Plugging
12-28-89 Rec 01-03-90 TA Spo Tag Spo b	to P&A to P&A t 80 sacks Class C cement top @ 690'. t 26 sacks Class C etween plugs. Rig	val from Adam ø and 3% CaCl @ . Spot 51 sack neat from 60' down. Set dry	Alls, and give perturned date and measured and covered Salameh @ 1:35 p.1 TD of 852'. s Class C neat (10 back to surface. hole marker. We	m. to plug and abandon m. to plug and abandon m. to plug and abandon Have 10.4 lbs. mud ll P&A. Plugging
12-28-89 Rec 01-03-90 TA Spo Tag Spo b	to P&A to P&A t 80 sacks Class C cement top @ 690'. t 26 sacks Class C etween plugs. Rig	val from Adam ø and 3% CaCl @ . Spot 51 sack neat from 60' down. Set dry	Alls, and give perturned date and measured and covered Salameh @ 1:35 p.1 TD of 852'. s Class C neat (10 back to surface. hole marker. We	m. to plug and abandon m. to plug and abandon m. to plug and abandon Have 10.4 lbs. mud ll P&A. Plugging
12-28-89 Rec 01-03-90 TA Spo Tag Spo b	to P&A to P&A t 80 sacks Class C cement top @ 690'. t 26 sacks Class C etween plugs. Rig	val from Adam ø and 3% CaCl @ . Spot 51 sack neat from 60' down. Set dry	Alls, and give perturned date and measured and covered Salameh @ 1:35 p.1 TD of 852'. s Class C neat (10 back to surface. hole marker. We	m. to plug and abandon m. to plug and abandon m. to plug and abandon Mave 10.4 lbs. mud ll P&A. Plugging
12-28-89 Rec 01-03-90 TA Spo Tag Spo b	eived verbal approv to P&A t 80 sacks Class C cement top @ 690'. t 26 sacks Class C etween plugs. Rig itnessed by Jack Jo	val from Adam ø and 3% CaCl @ . Spot 51 sack neat from 60' down. Set dry ohnson with BLM	Alls, and give perturned date and measured and covered Salameh @ 1:35 p.1 TD of 852'. s Class C neat (10 back to surface. hole marker. We	m. to plug and abandon m. to plug and abandon m. to plug and abandon Have 10.4 lbs. mud ll P&A. Plugging
12-28-89 Rec 01-03-90 TA Spo Tag Spo b W	to P&A to P&A t 80 sacks Class C cement top @ 690'. t 26 sacks Class C etween plugs. Rig itnessed by Jack Jo the foregoing is true and corre	val from Adam g and 3% CaCl @ . Spot 51 sack neat from 60' down. Set dry ohnson with BLM	Alls, and give perturned date and measured and covered Salameh @ 1:35 p.1 TD of 852'. s Class C neat (10 back to surface. hole marker. We	m. to plug and abandon m. to plug and abandon m. to plug and abandon m. to plug and abandon have 10.4 lbs. mud ll P&A. Plugging
12-28-89 Rec 01-03-90 TA Spo Tag Spo b W V	to P&A to P&A t 80 sacks Class C cement top @ 690'. t 26 sacks Class C etween plugs. Rig itnessed by Jack Jo the foregoing is true and corre	val from Adam g and 3% CaCl @ . Spot 51 sack neat from 60' down. Set dry ohnson with BLM	Alls, and give pertioent date and measured and crue vert Salameh @ 1:35 p.1 TD of 852'. s Class C neat (1) back to surface. hole marker. We	m. to plug and abandon m. to plug and abandon m. to plug and abandon Have 10.4 lbs. mud ll P&A. Plugging