		N.M. Oil Con.		
Form 3160-5 (June 1990)	UNITED STATES DEPARTMENT OF THE INTERIO	P.O. X 1980	FORM APPROVED	
	BUREAU OF LAND MANAGEMEN	Unhha NM 00044	Budget Bureau No. 1004-0135 Expires: March 31, 1993	
			5. Lease Designation and Senal No.	
CUNDER NOTICES AND DEPOSTS OF HEILS		LC 057210		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			6. If Indian, Allottee or Tribe Name	
	roposals to drill or to deepen or reentry to a d "ION FOR PERMIT " for such proposals	ifferent reservoir.		
1. Type of Well	SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation	
Cil Ges X			8 Y	
2. Name of Operator			MCA Unit, Well #302	
CONOCO, INC. 3. Address and Telephone No.			9. API#	
10 Desta Dr., Suite 100W, Midland, Texas 79705-4500,915 686-5424 915 684-6381 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			30 025 24298 10. Field and Pool, or Exploratory Area	
			Maljamar Grayburg San Andres	
Surface: 510 FSL & 51 TD: Sec 27, 1175			11. County or Parish, State	
			Lea, NM	
12. CHECK APPROPI	RIATE BOX(s) TO INDICATE NATURE (OF NOTICE, REPORT, OR	OTHER DATA	
TYPE OF SUBA	lission	TYPE OF ACTION		
X Notice of Inten	t 📃	Abandonment	Change of Plans	
		Recompletion	New Construction	
Subsequent Repo	eport	Plugging Back	Non-Routine Fracturing	
	×	Casing Repair	Water Shut-Off	
Final Abandon	ment Notice	Altering Casing	Conversion to Injection	
	X	MIT test	Dispose Water	
directionally drilled, give sub	d Operations (Clearly state all pertinent detaits, and give perti- surface locations and measured and true vertical depths for a	nent dates, including estimated date of st	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Serre) Arting any proposed work. If well is	
directionally drilled, give sut Proposal for casing 2. Get off on/off too 3. POOH w/injectio 4. Run csg. inspect 5. Upon findings, s 50' below t 6. POOH w/tubing. 7. Pressure csg. to 8. Drill out cement. RIH w/on-o MIT and re	d Operations (Clearly state all pertinent details, and give perti-	nent dates, including estimated date of st al markers and zones pertinent to this wor er to get base line. 32, I.I% FL-62, 2/105 SMS, 5 IS. pplying pressure while cern 10 minute MIT test @ 500#, on-off tool, latch onto pkr, pt	Plans: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) anting any proposed work. If well is fc.)* 5% KCL from ent thickens. if chart holds will ull plug, run	
directionally drilled, give sut Proposal for casing 2. Get off on/off too 3. POOH w/injectio 4. Run csg. inspect 5. Upon findings, s 50' below t 6. POOH w/tubing. 7. Pressure csg. to 8. Drill out cement. RIH w/on-o MIT and re	d Operations (Clearly state all pertinent details, and give perti- surface locations and measured and true vertical depths for a p integrity testing procedure: Presuure test tub and casing. b), place frac sand on top of packer. In tbg, run 30 minute MIT @ 500# in order tion log from pkr to surface. pot cmt, CI C w/low fluid loss, 3/10% CD- ad casing to 100' above bad casing depth 600# & monitor. Continue monioring & a Pressure test and compare to previous 3 ff tool & injection tbg, circulate sand off of turn well to injection. If test failure: will re-	nent dates, including estimated date of st al markers and zones pertinent to this wor er to get base line. 32, I.I% FL-62, 2/105 SMS, 5 IS. pplying pressure while cern 10 minute MIT test @ 500#, on-off tool, latch onto pkr, pt	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form: arting any proposed work. If well is fc)* 5% KCL from ent thickens. if chart holds will ull plug, run using CI C SUBJECT TO LIKE APPROV	
directionally drilled, give sut Proposal for casing I. Set profile plug. 2. Get off on/off too 3. POOH w/injectio 4. Run csg. inspect 5. Upon findings, s 50' below t 6. POOH w/tubing. 7. Pressure csg. to 8. Drill out cement. RIH w/on-o MIT and re neat cemen	d Operations (Clearly state all pertinent details, and give perti- surface locations and measured and true vertical depths for a p integrity testing procedure: Presuure test tub and casing. b), place frac sand on top of packer. In tbg, run 30 minute MIT @ 500# in order tion log from pkr to surface. pot cmt, CI C w/low fluid loss, 3/10% CD- ad casing to 100' above bad casing depth 600# & monitor. Continue monioring & a Pressure test and compare to previous 3 ff tool & injection tbg, circulate sand off of turn well to injection. If test failure: will re-	nent dates, including estimated date of st al markers and zones pertinent to this wor er to get base line. 32, I.1% FL-62, 2/105 SMS, 5 is. pplying pressure while cern 0 minute MIT test @ 500#, on-off tool, latch onto pkr, pu apeat cementing procedure i	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form: arting any proposed work. If well is fc)* 5% KCL from ent thickens. if chart holds will ull plug, run using CI C SUBJECT TO LIKE APPROV	
directionally drilled, give sut Proposal for casing I. Set profile plug. 2. Get off on/off too 3. POOH w/injectio 4. Run csg. inspect 5. Upon findings, s 50' below t 6. POOH w/tubing. 7. Pressure csg. to 8. Drill out cement. RIH w/on-o MIT and re neat cement 4. I hereby certify that the foregoing Signed (This space for Federal or State of the second state of the secon	d Operations (Clearly state all pertinent details, and give perti- surface locations and measured and true vertical depths for a g integrity testing procedure: Presuure test tub and casing. b), place frac sand on top of packer. In tbg, run 30 minute MIT @ 500# in order tion log from pkr to surface. pot cmt, CI C w/low fluid loss, 3/10% CD- had casing to 100' above bad casing depth 600# & monitor. Continue monioring & a Pressure test and compare to previous 3 off tool & injection. If test failure: will re turn well to injection. If test failure: will re it w/2% NaCI.	nent dates, including estimated date of st al markers and zones pertinent to this wor er to get base line. 32, 1.1% FL-62, 2/105 SMS, 5 is. pplying pressure while cern to minute MIT test @ 500#, on-off tool, latch onto pkr, pu epeat cementing procedure	And Providence of multiple completion on Well Completion of Recompletion Report and Log form.) anting any proposed work. If well is fc.)* 5% KCL from ent thickens. if chart holds will uil plug, run using CI C SUBJECT TO LIKE APPROV BY STATE Date 2-24-98 MAD 1 6 1998	
directionally drilled, give sut Proposal for casing I. Set profile plug. 2. Get off on/off too 3. POOH w/injectio 4. Run csg. inspect 5. Upon findings, s 50' below t 6. POOH w/tubing. 7. Pressure csg. to 8. Drill out cement. RIH w/on-o MIT and re neat cement 4. I hereby certify that the foregoing Signed (This space for Federal or State of the second state of the secon	d Operations (Clearly state all pertinent details, and give perti- surface locations and measured and true vertical depths for a g integrity testing procedure: Presuure test tub and casing. b), place frac sand on top of packer. In tbg, run 30 minute MIT @ 500# in order tion log from pkr to surface. pot cmt, CI C w/low fluid loss, 3/10% CD- had casing to 100' above bad casing depth 600# & monitor. Continue monioring & a Pressure test and compare to previous 3 off tool & injection. If test failure: will re turn well to injection. If test failure: will re it w/2% NaCI.	nent dates, including estimated date of st al markers and zones pertinent to this wor er to get base line. 32, I.1% FL-62, 2/105 SMS, 5 is. pplying pressure while cern 0 minute MIT test @ 500#, on-off tool, latch onto pkr, pu apeat cementing procedure i	And Providence of multiple completion on Well Completion of Recompletion Report and Log form.) anting any proposed work. If well is fc.)* 5% KCL from ent thickens. if chart holds will uil plug, run using CI C SUBJECT TO LIKE APPROV BY STATE Date 2-24-98 MAD 1 6 1998	
directionally drilled, give sut Proposal for casing I. Set profile plug. 2. Get off on/off too 3. POOH w/injectio 4. Run csg. inspect 5. Upon findings, s 50' below t 6. POOH w/tubing. 7. Pressure csg. to 8. Drill out cement. RIH w/on-o MIT and re neat cement 4. I hereby certify that the foreforth Signed (This space for Federal or State of Conditions of approval, if any: the 18 U.S.C. Section 1001, makes	d Operations (Clearly state all pertinent details, and give perti- surface locations and measured and true vertical depths for a g integrity testing procedure: Presuure test tub and casing. b), place frac sand on top of packer. In tbg, run 30 minute MIT @ 500# in order tion log from pkr to surface. pot cmt, CI C w/low fluid loss, 3/10% CD- had casing to 100' above bad casing depth 600# & monitor. Continue monioring & a Pressure test and compare to previous 3 off tool & injection tbg, circulate sand off c turn well to injection. If test failure: will re- the w/2% NaCl.	nent dates, including estimated date of st at markers and zones pertinent to this wor er to get base line. 32, 1.1% FL-62, 2/105 SMS, 5 as. pplying pressure while cem- to minute MIT test @ 500#, on-off tool, latch onto pkr, pu apeat cementing procedure to appeat cementing procedure to the second appeat cementing procedure to the second appeat cementing procedure to the second appeared to the second se	Mate: Report results of multiple completion on Net Completion or Recompletion Report and Lag term.) anting any proposed work: If well is fc.)* 5% KCL from ent thickens. if chart holds will uil plug, run using Cl C SUBJECT TO LIKE APPROV BY STATE Date MAR 1 6 1998 Date	
directionally drilled, give sut Proposal for casing I. Set profile plug. 2. Get off on/off too 3. POOH w/injectio 4. Run csg. inspect 5. Upon findings, s 50' below t 6. POOH w/tubing. 7. Pressure csg. to 8. Drill out cement. RIH w/on-off MIT and re neat cement 4. Thereby certify that the foreforth Signed (This space for Federal or State of poroved by OR II) Conditions of approval, it any:	d Operations (Clearly state all pertinent details, and give perti- surface locations and measured and true vertical depths for a g integrity testing procedure: Presuure test tub and casing. b), place frac sand on top of packer. In tbg, run 30 minute MIT @ 500# in order tion log from pkr to surface. pot cmt, CI C w/low fluid loss, 3/10% CD- had casing to 100' above bad casing depth 600# & monitor. Continue monioring & a Pressure test and compare to previous 3 off tool & injection tbg, circulate sand off c turn well to injection. If test failure: will re- the w/2% NaCl.	nent dates, including estimated date of st at markers and zones pertinent to this wor er to get base line. 32, 1.1% FL-62, 2/105 SMS, 5 is. pplying pressure while cem to minute MIT test @ 500#, on-off tool, latch onto pkr, pu espeat cementing procedure to esent SENT ROLEUM ENGINEEF	Mate: Report results of multiple completion on Net Completion or Recompletion Report and Lag term.) anting any proposed work: If well is fc.)* 5% KCL from ent thickens. if chart holds will uil plug, run using Cl C SUBJECT TO LIKE APPROV BY STATE Date MAR 1 6 1998 Date	
