

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

SUBMIT IN TRIPLICATE
(Other instructions)
Form 316-45

FORM APPROVED
Budget Bureau No. 1004-0135
Expires August 31, 1985

LEASE DESIGNATION AND SERIAL NO.

LC-057210

INDIAN ALLOTTEE OR TRIBE NAME

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CONOCO INC.

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface Unit 0

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA Unit 32y 3

9. WELL NO.

332

10. FIELD AND POOL, OR WILDCAT

Maljamar 6/5A

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28 - 175 - 32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

14. PERMIT NO.

30-025-24349

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PLUG OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① MIRU. POOH w/ rods, pump, & tbg. Scrape csg to PBTD (4189')
- ② Perf @ 850' w/ 2 JSPF. Set RBP @ 1650'. Spot 2sxs sand on RBP. Set pkr @ 750'. Establish circ. until all returns are clean.
- ③ POOH w/ pkr & tbg Pump 225 sxs Class "H" w/ 2% CaCl₂.
- ④ Displace down csg with up to 16 bbls fresh wtr. Shut in w/ 500 psig on csg.
- ⑤ Tag TOC & drill out. Press. test sqz'd perfs w/ 500 psig. Circ. sand off RBP & POOH.
- ⑥ GPH w/ tbg, pump & rods. Hang well on & rig down.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Administrative Supervisor

DATE

9-16-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

9-24-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side