

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24801

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
ELK OIL COMPANY

3. Address of Operator
Post Office Box 310, Roswell, New Mexico 88202-0310

4. Well Location
Unit Letter L : 810 Feet From The West Line and 1880 Feet From The South Line

Section 5 Township 15 South Range 34 East NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4126.3 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug and Abandon as follows:

- (1) Set CIBP @ 10,050' with 35' cement on top.
- (2) Set 100' plug inside 4½" casing @ 7300'.
- (3) Set 100' plug inside 4½" casing @ 4500'.
- (4) Cut and pull 4½" @ 4000'.
- (5) Set 100' plug in and out of 4½" casing stub.
- (6) Set 20 sx plug inside 8 5/8" casing @ 2600'.
- (7) Cut and pull 8 5/8" casing @ 1500'.
- (8) Set 100' plug in and out of 8 5/8" casing @ 1500'.
- (9) Set 100' plug @ base of 13 3/8" casing @ 400'.
- (10) Set 10 sx plug @ surface.
- (11) Place 4'X4' dry hole marker @ surface.

Hole filled with gel between plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joseph J. Kelly TITLE President DATE 04/16/92
TYPE OR PRINT NAME Joseph J. Kelly TELEPHONE NO. (505)623-3190

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE APR 20 1992

CONDITIONS OF APPROVAL, IF ANY: