• •	- +		
NO. OF COPIES RECEIVED]		Form C-103
DISTRIBUTION			Supersedes Old
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	•		
U.S.G.S.	1		Sa. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5. State Oil & Gas Lease No.
OO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON OPOSALS TO DATLE OR TO DEELS ON TO DETLE OR TO DEEPEN OF PERMIT	WELLS ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)	
1.	7. Unit Agreement Name		
OIL GAS WELL	OTHER-		
2. Name of Operator	8. Farm or Lease Name		
Phillips Petroleum	Denton		
3. Address of Operator	9. Well No.		
Room 806, Phillips 1	17		
4. Location of Well	10. Field and Pool, or Wildcat		
UNIT LETTER G 2	Denton (Devonian)		
THE Cast LINE, SECT	ION <u>11</u> TOWNSHIP <u>15-S</u> 15. Elevation (Show whether		
	12. County		
	3794' Gro	und	Lea
16. Check	Appropriate Box To Indicate N	ature of Notice, Report or Ot	her Data
NOTICE OF I	T REPORT OF:		
PERFORM PEMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	F >
отневdevia	te to straighten hole	OTHER	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

Confirming telephone conversations of December 11, 1976, between Messrs. D. S. Nutler and W. C. Rodgers, and Messrs. Jerry Sexton and Gary Kreiger, we request an exception to Statewide No. 111(b) to allow deviation of this well bore based on the following: NMOCC Rule 111 requires well to be drilled with deviation of less than 5° . When deviations of 5° and greater were reported below 10,800', our decision was made to run a deviation survey at 11,734' to determine the actual inclination and location of the hole with respect to the rotary table and, hopefully, to avoid the necessity of plugging back and redrilling the hole. The results of the survey showed that the bottom of the hole was located 360' S 26° W from the rotary table with an inclination of 10° . Verbal approval was given to our proposal to plug back to 10,800' (at which point the hole is located 248' south and 78' west of the rotary table at an inclination of 5°), and to deviate the hole toward the vertical, and attempt to turn the hole in a west-north westerly direction.

cc: Offset operators--Atlantic Richfield Company, Box 1610, Midland, TX 79701 Gulf Energy and Minerals, Inc., Box 1150, Midland, TX 79701 Marathon Oil Company, Box 552, Midland, TX 79701

/	2				
18. I hereby cer	tify that the info	mattor above is	true and complet	te to the best of my knowledge and belief.	
SIGNE	fall	le_₩. J	. Mueller	Engineering Advisor	DATE <u>12-14-76</u>
\mathcal{O}	\mathcal{O}				
APPROVED BY	1		<u></u>	TITLE	DATE
CONDITIONS O	F APPROVAL.	FANYI			

OIL CONSLAVANTAN CONM. HOBBS, N. M