

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM-1351
7. Lease Name or Unit Agreement Name SNM-33-16-33
8. Well No. 2
9. Pool name or Wildcat Undesignated <i>Sanmal Penn</i>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Southern Union Exploration Co.

3. Address of Operator
1800 Renaissance Twr. Dallas, Tx. 75270

4. Well Location
Unit Letter J : 1650 Feet From The South Line and 1650 Feet From The East Line
Section 33 Township 16S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4204.4' Gr

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP w/35' cmt. on top @ 12,000' (Top Perfs @ 12,074')
Set 100' cmt. plug @ 9,000'
Cut and pull csg., Set 100' cmt. plug 50' in and 50' out of csg. stub & Tag
Set 100' cmt. plug 50' in and 50' out of 8-5/8" csg. shoe @ 4,300' & Tag
Set 100' cmt. plug @ 1,500' (Top of Salt)
Set 10 sx. cmt. plug @ surf. and install Dry Hole Marker

Est. to begin operations 3/13/89

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *David A. Dillaha* TITLE Agent DATE 3/8/89
TYPE OR PRINT NAME David A. Dillaha TELEPHONE NO. (214) 987-18

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

MAR 14 1989

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 14 1961

CCD
HOLLYWOOD