

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 1432
7. Unit Agreement Name
8. Farm or Lease Name Eidson Com
9. Well No. 1
10. Field and Pool, or Wildcat Shoebar Townsend Atoka
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Allen K. Trobaugh
3. Address of Operator 303 West Wall, Suite 1405, Midland, Texas 79701
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>16S</u> RANGE <u>35E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3994 GR, KB 4009

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed Plugging: Perfs 12,517, 12,521 - 10 holes

1. Set CIBP 12,417', cap w/35' cement
2. Load hole with 10# Salt Water Gel
3. Shoot & pull 4½" casing
4. Set 35sx plug (100'), 50' in 50' out stub
5. Set 65sx plug (100'), 50' in 50' out of 9-5/8" casing
6. Set 45sx plug, 2,168' top salt
7. Set 75sx plug, base of 13-3/8" 474' (13-3/8" set at 424')
8. Set 10sx plug at surface
9. Install dry hole marker

65 sx plug at top of the Glorietta

9-5/8" casing cement circ.
Top of cement temp survey 4½" casing 8,990'.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE WELLS TO BE ABANDONED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

HENRY CLINGMAN

SIGNED Henry Clingman

TITLE Superintendent

DATE 1/25/88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____

TITLE _____

MAR 17 1988

CONDITIONS OF APPROVAL, IF ANY: