Submit 3 Copies To Appropriate Dist				
Office		lew Mexico	FO: Revised Ma	rm C-10
District I		nd Natural Resources	WELL API NO.	aon 20, 19
1625 N. French Dr., Hobbs, NM 8824 District II				
811 South First, Artesia, NM 88210	OIL CONSERVA	ATION DIVISION	30-025-26561	<u> </u>
District III	1220 South \$	St. Francis Dr.	5. Indicate Type of Lease	2
1000 Rio Brazos Rd., Aztec, NM 874	Santa Fe.	NM 87505		X
District IV 1220 S. St. Francis Dr., Santa Fe, NM	,		6. State Oil & Gas Lease No.	
87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name	
	PPLICATION FOR PERMIT" (FORM		Peror	
PROPOSALS.)			Baer	
1. Type of Well: Oil Well Gas Well	X Other			
2. Name of Operator			7. Well No.	
Yates Petroleum Corporation 3. Address of Operator 105 S. 4th Street Artesia, NM 88210			#3 8. Pool name or Wildcat	
			4. Well Location	
Unit Letter P	: 660 feet from the Sc	outh line and 660	feet from the East lin	ıe
Section 32		Range 35E		inty
	10. Elevation (Show wh	iether DR, RKB, RT, GR, e	etc.)	
	en av ek Sad Kalena	3990' GR		
	ck Appropriate Box to Indi		-	·
NOTICE OF	F INTENTION TO:	SU	BSEQUENT REPORT OF:	, ,
PERFORM REMEDIAL WORK		REMEDIAL WOR		
····			0,000	
			PLUG AND	-
TEMPORARILY ABANDON	CHANGE PLANS		RILLING OPNS. X ABANDONN	IENT
TEMPORARILY ABANDON PULL OR ALTER CASING		CASING TEST A	RILLING OPNS. X ABANDONN	IENT
PULL OR ALTER CASING		CASING TEST A		
PULL OR ALTER CASING		CASING TEST A CEMENT JOB		[
PULL OR ALTER CASING OTHER: Describe proposed or complete	ted operations. (Clearly state al	CASING TEST A CEMENT JOB	AND	ed date o
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work).	ted operations. (Clearly state al	CASING TEST A CEMENT JOB		ed date o
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation.	ted operations. (Clearly state al SEE RULE 1103. For Multiple	CASING TEST A CEMENT JOB	AND	ed date o
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho	ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location.	CASING TEST A CEMENT JOB	AND	ed date o
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho 4/21/00 – Drill out surface	ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug.	CASING TEST A CEMENT JOB OTHER: Re-ent l pertinent details, and give Completions: Attach wel	AND AND ABANDONM	ed date o
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho 4/21/00 – Drill out surface 4/22-4/23/00 – Drill out plu	ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626	CASING TEST A CEMENT JOB OTHER: Re-ent l pertinent details, and give Completions: Attach wel	AND AND ABANDONM	ed date o
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho 4/21/00 – Drill out surface 4/22-4/23/00 – Drill out plu 4/26/00 – Run DST #1 – Ci	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 jsco 11,005-11,088'.	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel	AND AND ABANDONM	ed date o
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho 4/21/00 – Drill out surface 4/22-4/23/00 – Drill out plu 4/26/00 – Run DST #1 – Ci 5/6/00 – TIH with tools for	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST #2 – 12,347-12,451'. D	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel	AND AND ABANDONM	ed date o
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho 4/21/00 – Drill out surface 4/22-4/23/00 – Drill out plu 4/26/00 – Run DST #1 – Ci 5/6/00 – TIH with tools for 5/7/00 – Run DST #3 – Mo	MULTIPLE COMPLETION ted operations. (Clearly state all SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST #2 – 12,347-12,451'. D prrow 12,402-12,457'.	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun.	ABANDONM AND e pertinent dates, including estimate lbore diagram of proposed complet	ed date o ion or
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho 4/21/00 – Drill out surface 4/22-4/23/00 – Drill out surface 4/22-4/23/00 – Drill out plu 4/26/00 – Run DST #1 – Ci 5/6/00 – TIH with tools for 5/7/00 – Run DST #3 – Mo 5/13/00 – TD 7-7/8" hole of	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST #2 – 12,347-12,451'. D mrow 12,402-12,457'. at 13,030' at 4:15 PM. Run	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. open hole logs. Logg	AND AND AND ABANDONM AND AND AND AND AND AND AND AND AND AND	ed date o ion or
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho 4/21/00 – Drill out surface 4/22-4/23/00 – Drill out surface 4/22-4/23/00 – Drill out plu 4/26/00 – Run DST #1 – Ci 5/6/00 – TIH with tools for 5/7/00 – Run DST #3 – Mo 5/13/00 – TD 7-7/8" hole of	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST #2 – 12,347-12,451'. D rrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. open hole logs. Logg nk with OCD in Hobbs	AND AND AND ABANDONM AND AND AND AND AND AND AND AND AND AND	[ed date o ion or 'S.
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho 4/21/00 – Drill out surface 4/22-4/23/00 – Drill out plu 4/26/00 – Run DST #1 – Ci 5/6/00 – TIH with tools for 5/7/00 – Run DST #3 – Mo 5/13/00 – TD 7-7/8" hole of 5/15/00 – Received verbo	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST #2 – 12,347-12,451'. D prow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil - 50 sxs H + .2% HR7	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743	ABANDONM AND Try e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H Premium	[ed date o ion or 's. 7
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 – Remove dry ho 4/21/00 – Drill out surface 4/22-4/23/00 – Drill out plu 4/26/00 – Run DST #1 – Ci 5/6/00 – TIH with tools for 5/7/00 – Run DST #3 – Mo 5/13/00 – TD 7-7/8" hole of 5/15/00 – Received verbo Plug #1 – 13,014-12,914' –	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 sco 11,005-11,088'. DST #2 – 12,347-12,451'. D prrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil - 50 sxs H + .2% HR7 sxs H + .2% HR7	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743	ABANDONM AND Try e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 59 sxs'H + .2% HR	[ed date o ion or 's. 7
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 - Remove dry ho 4/21/00 - Drill out surface 4/22-4/23/00 - Drill out plu $4/26/00 - Run DST #1 - Ci5/6/00 - TIH with tools for5/7/00 - Run DST #3 - Mo5/13/00 - TD 7-7/8" hole of5/15/00 - Received verboodPlug #1 - 13,014-12,914' -Plug #3 - 9705-9605' - 50$	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Ugs to original TD at 10,626 sco 11,005-11,088'. DST #2 – 12,347-12,451'. D rrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil - 50 sxs H + .2% HR7 sxs H + .2% HR7 sxs H Premium	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205	ABANDONN AND Ty e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H Premium 1-4681' – 65 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu	Ed date o ion or 's. 7 Js Js
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 - Remove dry ho 4/21/00 - Drill out surface 4/22-4/23/00 - Drill out plu $4/26/00 - Run DST #1 - Ci5/6/00 - TIH with tools for5/7/00 - Run DST #3 - Mo5/13/00 - TD 7-7/8" hole of5/13/00 - Received verboodPlug #1 - 13,014-12,914' -Plug #3 - 9705-9605' - 50Plug #5 - 6200-6100' - 50TIH and tagged Plug #6 ofPlus #8 - 450-350' - 25 sxs$	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST #2 – 12,347-12,451'. D rrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil - 50 sxs H + .2% HR7 sxs H + .2% HR7 sxs H Premium at 4569' is C Premium Plus	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205	AND AND AND AND AND AND AND AND	Ed date o ion or 's. 7 Js Js
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 - Remove dry ho 4/21/00 - Drill out surface 4/22-4/23/00 - Drill out plu $4/26/00 - Run DST #1 - Ci5/6/00 - TIH with tools for5/7/00 - Run DST #3 - Mo5/13/00 - TD 7-7/8" hole of5/15/00 - Received verboodPlug #1 - 13,014-12,914' -Plug #3 - 9705-9605' - 50Plug #5 - 6200-6100' - 50TIH and tagged Plug #6 ofPlus #8 - 450-350' - 25 sxs5/16/00 - Rig released at$	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST #2 – 12,347-12,451'. D rrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil - 50 sxs H + .2% HR7 sxs H + .2% HR7 sxs H Premium at 4569' is C Premium Plus 11:45 PM.	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205 Plug #9 – 40'	ABANDONN AND Try e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H Premium 1-4681' – 65 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu to surface – 10 sxs'C Premium	Ed date o ion or 7 JS JS
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 - Remove dry ho 4/21/00 - Drill out surface 4/22-4/23/00 - Drill out plu $4/26/00 - Run DST #1 - Ci5/6/00 - TIH with tools for5/7/00 - Run DST #3 - Mo5/13/00 - TD 7-7/8" hole of5/15/00 - Received verboodPlug #1 - 13,014-12,914' -Plug #3 - 9705-9605' - 50Plug #5 - 6200-6100' - 50TIH and tagged Plug #6 ofPlus #8 - 450-350' - 25 sxs5/16/00 - Rig released at$	MULTIPLE COMPLETION ted operations. (Clearly state al SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST #2 – 12,347-12,451'. D rrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil - 50 sxs H + .2% HR7 sxs H + .2% HR7 sxs H Premium at 4569' is C Premium Plus	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205 Plug #9 – 40'	ABANDONN AND Try e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H Premium 1-4681' – 65 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu to surface – 10 sxs'C Premium	ed date of ion or 7 Js Js
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). The recompilation. 4/17/00 - Remove dry hoteon $4/21/00 - Drill out surface theA/22-4/23/00 - Drill out plutA/26/00 - Run DST #1 - Citeon5/6/00 - TIH with tools for5/7/00 - Run DST #3 - Moteon5/13/00 - TD 7-7/8" hole of5/13/00 - Received verbooPlug #1 - 13,014-12,914' -Plug #3 - 9705-9605' - 50Plug #5 - 6200-6100' - 50TIH and tagged Plug #6 ofPlus #8 - 450-350' - 25 sxs5/16/00 - Rig released atThereby certify that the inform$	MULTIPLE COMPLETION ted operations. (Clearly state all SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST $#2 - 12,347-12,451'$. D mrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil - 50 sxs H + .2% HR7 sxs H + .2% HR7 sxs H Premium at 4569' is C Premium Plus 11:45 PM. mation above is true and comple	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. Open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205 Plug #9 – 40' te to the best of my knowle	ABANDONN AND Ty e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H Premium 1-4681' – 65 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu to surface – 10 sxs'C Premium edge and belief.	Ed date o ion or 7 Js Js N Plus
PULL OR ALTER CASING OTHER: Describe proposed or complete starting any proposed work). The recompilation. 4/17/00 - Remove dry ho $4/21/00 - Drill out surface4/22-4/23/00 - Drill out plut 4/26/00 - Run DST #1 - Cit 5/6/00 - TIH with tools for5/7/00 - Run DST #3 - Mot 5/13/00 - TD 7-7/8" hole of5/13/00 - Received verbood Plug #1 - 13,014-12,914' - Plug #3 - 9705-9605' - 50 Plug #5 - 6200-6100' - 50 TIH and tagged Plug #6 of Plus #8 - 450-350' - 25 sxs 5/16/00 - Rig released atThereby certify that the informSIGNATURE$	MULTIPLE COMPLETIONImage: ted operations. (Clearly state all SEE RULE 1103. For Multiplele marker. Build location. plug. Jgs to original TD at 10,626sco 11,005-11,088'.DST $#2 - 12,347-12,451'.$ D rrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil- 50 sxs H + .2% HR7 sxs H Premium at 4569' s C Premium Plus 11:45 PM. nation above is true and compleImage: Complete Com	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. Open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205 Plug #9 – 40' te to the best of my knowle	ABANDONN AND Ty e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H Premium 1-4681' – 65 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu to surface – 10 sxs'C Premium edge and belief. chnician DATE March 8	s. 7 Js Plus , 2002
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). S recompilation. 4/17/00 - Remove dry ho 4/21/00 - Drill out surface 4/22-4/23/00 - Drill out plu $4/26/00 - Run DST #1 - Ci5/6/00 - TIH with tools for 5/7/00 - Run DST #3 - Mo5/13/00 - TD 7-7/8" hole of 5/13/00 - Received verbody Plug #1 - 13,014-12,914' - Plug #3 - 9705-9605' - 50 Plug #5 - 6200-6100' - 50 TIH and tagged Plug #6 of Plus #8 - 450-350' - 25 sxs 5/16/00 - Rig released atI hereby certify that the informSIGNATURE Mathinstrume Susar$	MULTIPLE COMPLETION ted operations. (Clearly state all SEE RULE 1103. For Multiple le marker. Build location. plug. Jgs to original TD at 10,626 isco 11,005-11,088'. DST $#2 - 12,347-12,451'$. D mrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil - 50 sxs H + .2% HR7 sxs H + .2% HR7 sxs H Premium at 4569' is C Premium Plus 11:45 PM. mation above is true and comple	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. Open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205 Plug #9 – 40' te to the best of my knowle	ABANDONN AND Ty e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H Premium 1-4681' – 65 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu to surface – 10 sxs'C Premium edge and belief.	s. 7 Js Plus , 2002
PULL OR ALTER CASING OTHER: Describe proposed or complete starting any proposed work). The recompilation. 4/17/00 - Remove dry ho $4/21/00 - Drill out surface4/22-4/23/00 - Drill out plut 4/26/00 - Run DST #1 - Cit 5/6/00 - TIH with tools for5/7/00 - Run DST #3 - Mot 5/13/00 - TD 7-7/8" hole of5/13/00 - Received verbood Plug #1 - 13,014-12,914' - Plug #3 - 9705-9605' - 50 Plug #5 - 6200-6100' - 50 TIH and tagged Plug #6 of Plus #8 - 450-350' - 25 sxs 5/16/00 - Rig released atThereby certify that the informSIGNATURE$	MULTIPLE COMPLETIONImage: ted operations. (Clearly state all SEE RULE 1103. For Multiplele marker. Build location. plug. Jgs to original TD at 10,626sco 11,005-11,088'.DST $#2 - 12,347-12,451'.$ D rrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wil- 50 sxs H + .2% HR7 sxs H Premium at 4569' s C Premium Plus 11:45 PM. nation above is true and compleImage: Complete Com	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. Open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205 Plug #9 – 40' te to the best of my knowle	ABANDONM AND Try e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs' C Premium 1-4681' – 65 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu to surface – 10 sxs' C Premium edge and belief. <u>chnician</u> DATE <u>March 8</u> Telephone No. 505-7	Ed date o ion or 7 Js Js N Plus , 2002 48-147
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). Since 4/17/00 - Remove dry ho $4/21/00 - Drill out surface4/22-4/23/00 - Drill out plut 4/26/00 - Run DST #1 - Ci5/6/00 - TIH with tools for 5/7/00 - Run DST #3 - Mo5/13/00 - TD 7-7/8" hole co 5/13/00 - Received verbod Plug #1 - 13,014-12,914' - Plug #3 - 9705-9605' - 50 Plug #5 - 6200-6100' - 50 TIH and tagged Plug #6 co Plus #8 - 450-350' - 25 sxs 5/16/00 - Rig released atThereby certify that the informSIGNATURE M + C + C + NType or print name Susar(This space for State use)APPPROVED BY M = M + M + M$	MULTIPLE COMPLETIONImage: MULTIPLE COMPLETIONted operations. (Clearly state all SEE RULE 1103. For Multiplele marker. Build location. plug. Ugs to original TD at 10,626sco 11,005-11,088'. DST #2 – 12,347-12,451'. D prrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wile- 50 sxs H + .2% HR7 sxs H + .2% HR7 sxs H Premium at 4569' is C Premium Plus 11:45 PM. nation above is true and comple $Mup = Mup =$	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. Open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205 Plug #9 – 40' te to the best of my knowles Engineering Tee	ABANDONM AND Try e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs' C Premium 1-4681' – 65 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu to surface – 10 sxs' C Premium edge and belief. <u>Chnician</u> DATE <u>March 8</u> <u>Telephone No.</u> 505-7	Ed date o ion or 7 Js Js N Plus , 2002 48-147
PULL OR ALTER CASING OTHER: Describe proposed or complet starting any proposed work). Since recompilation. 4/17/00 - Remove dry ho $4/21/00 - Drill out surface4/22-4/23/00 - Drill out plut 4/26/00 - Run DST #1 - Cit 5/6/00 - TIH with tools for5/7/00 - Run DST #3 - Mot 5/13/00 - TD 7-7/8" hole of5/13/00 - Received verbox Plug #1 - 13,014-12,914' - Plug #3 - 9705-9605' - 50 Plug #5 - 6200-6100' - 50 TIH and tagged Plug #6 of Plus #8 - 450-350' - 25 sxs 5/16/00 - Rig released atThereby certify that the informSIGNATURE Suscer(This space for State use)$	MULTIPLE COMPLETIONImage: MULTIPLE COMPLETIONted operations. (Clearly state all SEE RULE 1103. For Multiplele marker. Build location. plug. Ugs to original TD at 10,626sco 11,005-11,088'. DST #2 – 12,347-12,451'. D prrow 12,402-12,457'. at 13,030' at 4:15 PM. Run al permission from Gary Wile- 50 sxs H + .2% HR7 sxs H + .2% HR7 sxs H Premium at 4569' is C Premium Plus 11:45 PM. nation above is true and comple $Mup = Mup =$	CASING TEST A CEMENT JOB OTHER: Re-ent I pertinent details, and give Completions: Attach wel '. Begin drilling new f ST #2 – misrun. Open hole logs. Logg nk with OCD in Hobbs Plug #2 – 11,6 Plug #4 – 743 Plug #6 – 478 Plug #7 – 205 Plug #9 – 40' te to the best of my knowle	ABANDONM AND Try e pertinent dates, including estimate lbore diagram of proposed complet formation. ers TD 13,030'. Wait on order to set plugs. 528-11,528' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs'H + .2% HR 2-7332' – 50 sxs' C Premium 1-4681' – 65 sxs C Premium Plu 0-1950' – 25 sxs C Premium Plu to surface – 10 sxs' C Premium edge and belief. <u>Chnician</u> DATE <u>March 8</u> <u>Telephone No.</u> 505-7	Ed date of ion or 7 Js Js N Plus , 2002 48-147