## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 07 COPIES SECEIVED	
POITUBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	 <u> </u>
OPERATOR	

## OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE. NEW MEXICO 87501

Form C-103 . Revised 10-1-78

SANTA FE, NEW MEXICO 8/501	
FILE	5a. Indicate Type of Lease
U.S.O.S.	State XX Fee
LAND OFFICE	5. State Oil & Gas Lease No.
OPERATOR	LG 3819
THE PROPERTY OF THE PROPERTY O	
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DECEN OR PLUG BACK TO DETECTION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1.	
WELL Y WELL OTHER-	8. Farm or Lease Name
2. Name of Operator	l l
Yates Petroleum Corporation	Sombrero MS State
J. Address of Operator	9. Well No.
105 South 4th St., Artesia, NM 88210	1
4. Location of Well	10. Field and Pool, or Wildcat
4. Location of well	Kemnitz Lower Wolfcamp
UNIT LETTER J 1650 FEET FROM THE SOUTH LINE AND 1650 FEET FROM	
1.00 220	Allillillillilli
THE East LINE, SECTION 22 TOWNSHIP 16S RANGE 33E NMPM	
	ATTITUTE HEALTH
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
(i)	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or O	her Data
	T REPORT OF:
NOTICE OF INTENTION TO:	
	ALTERING CASING
PERFORM REMEDIAL WORK X PLUE AND ABANDON REMEDIAL WORK	PLUG AND ABANDONMENT
TEMPORARILY ABANDON COMMENCE DRILLING OPHS.	PENS YND YBYNDONWENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	——————————————————————————————————————
OTHER	
OTHER	•
	i line of marine any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	g estimated date of starting dity proposed
work) SEE RULE 1103.	
WORK) SEE NUCE 1103.	
Set RRP approx 10950' and pressure test. Set packer approx 106	
Set RBP approx. 10950' and pressure test. Set packer approx 106 Acidize existing Kemnitz perforations 10772-10794' as follows:	
Set RBP approx. 10950' and pressure test. Set packer approx 106 Acidize existing Kemnitz perforations 10772-10794' as follows:	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush  Pull packer and RBP and return well to pumping.	
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush	
Set RBP approx. 10950' and pressure test. Set packer approx 106' Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush  Pull packer and RBP and return well to pumping.	00'.
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush  Pull packer and RBP and return well to pumping.	
Set RBP approx. 10950' and pressure test. Set packer approx 106' Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush  Pull packer and RBP and return well to pumping.	00'. 8-7-86
Set RBP approx. 10950' and pressure test. Set packer approx 1060 Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush  Pull packer and RBP and return well to pumping.  18. Thereby certify that the information above is true and complete to the best of my knowledge and belief.  18. Thereby certify that the information above is true and complete to the best of my knowledge and belief.	00'. 8-7-86
Set RBP approx. 10950' and pressure test. Set packer approx 106' Acidize existing Kemnitz perforations 10772-10794' as follows:  1) 1000 gals 15% NEFE acid 2) 7500 gals pad 3) 20000 gals 20% CRA w/additives 4) 8000 gals flush  Pull packer and RBP and return well to pumping.	00'.

ACCELLED 1986