Submit 3 Copies to Appropriate	E			-		
District Office	(OIL CONSE	ERVATIO	ON DIVISION		······································
P.O. Box 1980, Hob			2040 Pacheco		WELL API NO.	
DISTRICT II P.O. Drawer DD, Ar	tesia NM 89710	Sar	nta Fe, NM	87505	<u>30-025-27</u> 5. Indicate Type of Lease	0/2
P.O. Drawer DD, AI	(5514, 1919) 0021U					
1000 Rio Brazos Rd.	, Aztec, NM 87410				6. State Oil & Gas Lease 1	No.
	SUNDRY NOTIC	ES AND REPOF	TS ON WEL	LS	21359A	
	IS FORM FOR PROP	OSALS TO DRILL C	R TO DEEPEN	OR PLUG BACK TO A	7. Lease Name or Unit Ap	reement Name
	DIFFERENT RESERV	OIR. USE "APPLICA D1) FOR SUCH PRO			Monteith "A"	
1. Type of Well: OIL	GAS —					
		0	THER			
2. Name of Operator					8. Well No.	
3. Address of Operat	<u>es Production Co</u> ^{tor})			9. Pool name or Wildcat	
P.O. Box 2760	Midland, TX 79	702-2760			Lovington, NE (Per	<u>ווו)</u>
4. Well Location	H : 1980'	Paat From The	North	Line and E1	0' Feet From The	East Line
Unit Letter_					Feet From The	Last Line
Section	13	Township	16S Ra	nge 36E	<u>ммрм Lea</u>	a County
		10. Elevatio	on (Show whethe	er DF, RKB, RT, GR, etc	e.)	
//////////////////////////////////////	Check App	ronriate Roy +	o Indicato	Natura of Nation	Report, or Other	//////////////////////////////////////
		-		1	SEQUENT REP	
			- - - -			
						UNI UF:
		PLUG AND ABA		REMEDIAL WORK		ING CASING
ERFORM REMEDIAL						
		PLUG AND ABA		REMEDIAL WORK		
EMPORARILY ABAN		PLUG AND ABA CHANGE PLANS		REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE		ING CASING
EMPORARILY ABAN		PLUG AND ABA CHANGE PLANS		REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE		ING CASING
EMPORARILY ABAN JLL OR ALTER CAS THER:	NDON	PLUG AND ABA CHANGE PLANS	NDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER:		ING CASING
EMPORARILY ABAN JLL OR ALTER CAS THER:	NDON	PLUG AND ABA CHANGE PLANS	NDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER:		ING CASING
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a P @ 11,250'. cement on top	NDON s all pertinent deta	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER:	ALTERI OPNS. D PLUG A MENT JOB tes, including estimated date . Circulate hole w	ING CASING AND ABANDONMENT of starting any proposed
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a P @ 11,250'. cement on top 25# salt gel p	NDON s all pertinent deta	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER:	ALTERI OPNS. PLUG A MENT JOB	ING CASING AND ABANDONMENT of starting any proposed
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a P @ 11,250'. cement on top 25# salt gel p rom 6380-6019'	NDON s all pertinent deta o of CIBP fr per bb1. Sp .	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: wils, and give pertinent dat from 11,250-11,028' not 40 sx "H" ceme	ALTERI OPNS. DPLUG A MENT JOB	ING CASING AND ABANDONMENT of starting any proposed
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a P @ 11,250'. cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50'	NDON s all pertinent deta o of CIBP fr per bb1. Sp ee point @ 4 in 5-1/2"st	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: ils, and give pertinent dat for 11,250-11,028' fot 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. W	ALTERI OPNS. PLUG A MENT JOB . . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842'	ING CASING AND ABANDONMENT of starting any proposed / 260 bb1s Spot 40
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2	NDON s all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: iis, and give pertinent dat form 11,250-11,028' not 40 sx "H" ceme 980'. POOH, LD C. ub from 5047'. We Spot 75 sx "C" ce	ALTERI OPNS. DPLUG A MENT JOB	ING CASING AND ABANDONMENT of starting any proposed / 260 bb1s Spot 40
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3	NDON NDON S all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 0' to surfa	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: atis, and give pertinent dat from 11,250-11,028' ot 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. We Spot 75 sx "C" co	ALTERI OPNS. PLUG A MENT JOB . tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC,	ING CASING AND ABANDONMENT of starting any proposed / 260 bb1s Spot 40
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3	NDON NDON S all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 0' to surfa	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: iis, and give pertinent dat form 11,250-11,028' not 40 sx "H" ceme 980'. POOH, LD C. ub from 5047'. We Spot 75 sx "C" ce	ALTERI OPNS. PLUG A MENT JOB . tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC,	ING CASING AND ABANDONMENT of starting any proposed / 260 bb1s Spot 40
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3	NDON NDON S all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 0' to surfa	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: atis, and give pertinent dat from 11,250-11,028' ot 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. We Spot 75 sx "C" co	ALTERI OPNS. PLUG A MENT JOB . tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC,	ING CASING AND ABANDONMENT of starting any proposed / 260 bb1s Spot 40
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99 9/22/99	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3 ad 4' below gr	NDON NDON S all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 0' to surfa	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: atis, and give pertinent dat from 11,250-11,028' ot 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. We Spot 75 sx "C" co	ALTERI OPNS. PLUG A MENT JOB . tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC,	ING CASING AND ABANDONMENT of starting any proposed / 260 bb1s Spot 40
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99 9/22/99	NDON	PLUG AND ABA CHANGE PLANS CHANGE PLANS ions (Clearly state a P @ 11,250'. cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3 ad 4' below gr	ANDON S all pertinent deta o of CIBP fr ber bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 0' to surfa round level	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: is, and give pertinent dat for 11,250-11,028' tot 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. W Spot 75 sx "C" co ce. and install dry he	ALTERI OPNS. PLUG A MENT JOB . tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC,	ING CASING AND ABANDONMENT of starting any proposed / 260 bb1s Spot 40
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99 9/22/99 9/22/99	NDON	PLUG AND ABA CHANGE PLANS CHANGE PLANS ions (Clearly state a P @ 11,250'. cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3 ad 4' below gr	NDON s all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 00' to surfa ound level	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: ils, and give pertinent dat for 11,250-11,028' not 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. We Spot 75 sx "C" co ce. and install dry he	ALTERI OPNS. PLUG A MENT JOB tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC, ole marker.	ING CASING ND ABANDONMENT of starting any proposed / 260 bbls Spot 40 tag TOC @ 315'.
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99 9/22/99	NDON	PLUG AND ABA CHANGE PLANS CHANGE PLANS ions (Clearly state a P @ 11,250'. cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3 ad 4' below gr	NDON s all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 00' to surfa ound level	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: ils, and give pertinent dat for 11,250-11,028' not 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. We Spot 75 sx "C" co ce. and install dry he	ALTERI OPNS. PLUG A MENT JOB . tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC,	ING CASING ND ABANDONMENT of starting any proposed / 260 bbls Spot 40 tag TOC @ 315'.
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99 9/22/99 9/22/99	NDON SING d or Completed Operation LE 1103. Set 5-1/2" CIB Spot 25 sx "H" 10# plug mud, sx "H cement f Cut off 5-1/2" Spot 60 sx "C" Spot 60 sx "C" Spot 45 sx "C" Spot 10 sx "C" Cut off wellhed P 973 833 Information above is true a Cut off set the set of	PLUG AND ABA CHANGE PLANS CHANGE PLANS ions (Clearly state a P @ 11,250'. cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3 ad 4' below gr	NDON s all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 00' to surfa ound level	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: ils, and give pertinent dat for 11,250-11,028' not 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. We Spot 75 sx "C" co ce. and install dry he	ALTERI OPNS. PLUG A MENT JOB tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC, ole marker.	ING CASING ND ABANDONMENT of starting any proposed / 260 bbls Spot 40 tag TOC @ 315'.
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99 9/22/99 9/22/99 LITUTUA hereby certify that the hereby certify that the	NDON SING d or Completed Operation LE 1103. Set 5-1/2" CIB Spot 25 sx "H" 10# plug mud, sx "H cement f Cut off 5-1/2" Spot 60 sx "C" Spot 60 sx "C" Spot 45 sx "C" Spot 10 sx "C" Cut off wellhed P 973 833 Information above is true a Cut off set the set of	PLUG AND ABA CHANGE PLANS ions (Clearly state a p @ 11,250'. cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3 ad 4' below gr	NDON s all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 00' to surfa ound level	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: ils, and give pertinent dat for 11,250-11,028' not 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. We Spot 75 sx "C" co ce. and install dry he	ALTERI OPNS. PLUG A MENT JOB tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC, ole marker.	ING CASING AND ABANDONMENT of starting any proposed / 260 bb1s Spot 40 tag TOC @ 315'. E
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99 9/22/99 9/22/99 LITUTUA hereby certify that the hereby certify that the	NDON SING d or Completed Operation LE 1103. Set 5-1/2" CIB Spot 25 sx "H" 10# plug mud, sx "H cement f Cut off 5-1/2" Spot 60 sx "C" Spot 60 sx "C" Spot 45 sx "C" Spot 10 sx "C" Cut off wellhed P 973 823 Information above is true of Keith E. Bucy	PLUG AND ABA CHANGE PLANS ions (Clearly state a p @ 11,250'. cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3 ad 4' below gr	NDON s all pertinent deta o of CIBP fr per bbl. Sp ee point @ 4 in 5-1/2"st 2240-2071'. 00' to surfa ound level	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: ils, and give pertinent dat for 11,250-11,028' not 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. We Spot 75 sx "C" co ce. and install dry he	ALTERI OPNS. PLUG A MENT JOB tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC, ole marker.	ING CASING ND ABANDONMENT of starting any proposed / 260 bbls Spot 40 tag TOC @ 315'. E
EMPORARILY ABAN JLL OR ALTER CAS THER: 2. Describe Propose work) SEE RU 9/16/99 9/17/99 9/20/99 9/21/99 9/22/99 9/22/99 LITUTUA hereby certify that the hereby certify that the	NDON	PLUG AND ABA CHANGE PLANS ions (Clearly state a p @ 11,250'. cement on top 25# salt gel p rom 6380-6019' casing at fre cement @ 50' cement from 2 cement from 3 ad 4' below gr	NDON s all pertinent deta o of CIBP fr ber bb1. Sp 	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: ils, and give pertinent dat for 11,250-11,028' not 40 sx "H" ceme 980'. POOH, LD C ub from 5047'. We Spot 75 sx "C" co ce. and install dry he	ALTERI OPNS. PLUG A MENT JOB tes, including estimated date . Circulate hole w nt from 8371-8010'. asing. DC, tag TOC @ 4842' ement @ 431'. WOC, ole marker. tion Supt. DAT TELEPHON	ING CASING ND ABANDONMENT of starting any proposed / 260 bb1s Spot 40 tag TOC @ 315'. E