

STATE OF NEW MEXICO
AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Carr Well Service Inc	8. Farm or Lease Name Tilley 47-758
3. Address of Operator P.O. Box 69090 Odessa, Texas 79769	9. Well No. 1
4. Location of Well UNIT LETTER C, 330 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 16S RANGE 35E NMPM.	10. Field and Pool, or Wildcat Shoebar Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3980 G.L.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attached abandonment procedure and borehole sketch..

1. Set CIBP 12490', capwith 35' cement
2. Load hole with 10# salt water gel
3. Shoot and pull 5½" casing above freepoint
4. Set 100' plug at casing cutoff(50' in 50'out of stub)
5. Set 100' plug at 8500'
6. Set 100' plug at top of Glorieta (6258')
7. Set 100' plug at 85/8" casing shoe(50'in 50'out)
8. Set 100' plug at top of salt (2100')
9. Set 10 sk. surface plug
10. Install dry hole marker and clean location

THIS NOTICE OF INTENTION TO PLUG BACK TO A DIFFERENT RESERVOIR OR TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Agent DATE 1 December 1988

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE DEC 14 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 13 1968

OCD
HOBBS OFFICE