

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator C&K Petroleum, Inc.	8. Farm or Lease Name Shipp 28
3. Address of Operator P. O. Drawer 3546, Midland, TX 79702	9. Well No. 28-1
4. Location of Well UNIT LETTER P 660 FEET FROM THE South 660 FEET FROM THE East LINE, SECTION 28 TOWNSHIP 16-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Lovington Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3783' GL	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well is no longer economical to produce. Intend to plug & abandon as follows (24-Hour notification will be given):

1. Set CIBP @ 8500± and dump 35' cmt, (Abo perforations are 8579' - 8584'). Load hole with Mud-Laden water.
2. Cut 5-1/2" csg @ 7400± (estimated TOC 7410'). Pull and LD csg.
3. Spot 35 sx cmt plug, 50' inside and 50' outside 5-1/2" csg stub.
4. Spot 35 sx cmt plug 4390 - 4290' (8-5/8" csg set @ 4340').
5. Spot 35 sx cmt plug @ 1500'.
6. Cut csg off below ground level. Set 10 sx surface plug.
7. Erect marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bill M. Pugh TITLE Operations Manager DATE Sept. 16, 1983

ORIGINAL SIGNED BY EDDIE SEAY

APPROVED BY OIL & GAS INSPECTOR

CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

SEP 22 1983