ERGY AND MINERALS DE	EPARTMENT
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	

N

	TIL CONSERV	ATION DIVISIO.	
DISTRIBUTION	P. O. Bo	OX 2088	•
SANTA PE	SANTA FE, NE	Form C-103 . Revised 19-1-	
FILE		W MEXICO 87501	welliged thele
U.S.G.S.			Sa. Indicate Type of Lease
LAND OFFICE			
OPERATOR		•	
			5. State Oil & Gas Lease No.
211112			
SUNDRY NO SUNDRY NO PROPOSAL USE "APPLICATION FO	TICES AND REPORTS OF	WELLS	
		(,E)AEDQUAY HJC	
	THER-		7. Unit Agreement Name
Chevron U.S.A. Inc.			8. Farm or Lease Name
dress of Operator			Lea L. State
P.O. Box 670 Hobbs, i	NM 88240		9. Well No.
cation of Well			2
E 1980	Nort)	660	10. Field and Pool, or Wildcat
INIT LETTER E 1980 FEET FROM THE NORTH 660		Maljamar Grayburg	
West 3	2	32E .	MINITED TO THE PARTY OF THE PAR
LINE, SECTION	TOWNSHIP	RANGE	MAN ()
	15. Elevation (Show whether	DE PT CP	
		Dr. RI. GR. etc.)	12. County
	3885		Lea
Check Appro	priate Box To Indicate 1	Nature of Notice, Report of	or Other Days
NOTICE OF INTEN	TION TO:	Super-	of Other Data
		SUBSEQ	UENT REPORT OF:
MAN REMEDIAL WORK	[1.	-
Ħ	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
DRAFILY ASANDON		COMMENCE ORILLING OPHS.	7
OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOS	PLUG AND ABANDONMENT
			٠ .
ner	<u></u>	OTHER	
scribe Proposed or Completed Operation	s (Clearly sees all a		luding estimated date of starting any proposed
rk) SEZ RULE 1103.	a foremry state all pertinent det	ails, and give pertinent dates, inc	luding estimated date of starting any proposed
			•
It is proposed to	P&A the wellbore	due to parted cas	ina
Procedure as follow	We. DOOH W/numn =	and rode fich /	2 2 / 0 !!
and the as now	ws. room w/pump a	ind rods, rish/rec	over 2 3/8"
prod. tog as per re	ecommendations.	Set cement retain	er ±3500'. Squeeze
200sx Cl C neat be	low retainer. Ca	p retainer w/ 10s	x cement Circ
hole w/abandonment	mud Set cmt pl	ligg ag follows:	1) 20001 20001
2) 1500! - 1700!	2) 2001 5001	ags as lollows:	1). 2000 - 3000
2). 1500' - 1700'	, 3) 300 - 300 ,	4). surface - 10	U', POOH, LD
prod. tbg while se	tting plugs. Cut	off WH 3' below	GLE, install dry
hole marker. RDMO,	clean location.		•
		•	•
•			
	•		
eby certify that the information above is	true and complete to the best of	my knowledge and belief.	
m 5 01	•		
M. E. ah	Tirus St	aff Drlg. Engr.	July 17 1000
Orig. Sig	mod ha		July 17, 1988

Paul J			
	Elaf rive		DATE
IONS OF APPROVAL, IF ANV.			