STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT  O. CONSERVATION DIVISION  P. O. BOX 2088	Form C-103 Revised 10-1-7
SANTA FE, NEW MEXICO 87501	State X Foe
CHERATOR CHERATOR	5. State Oil 6 Gas Lease No. LG 5603
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT NESERVOIR.  USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL CAS OTHER- P&A	B. Farm or Lease Name
Name of Operator Yates Petroleum Corporation	Hawk XO State
Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No.
. Location of Well K 2310 FEET FROM THE South LINE AND 1980 FEET FROM	10. Field and Pool, or Wildcat Saunders Permo Upper Pe
THE West LINE, SECTION 4 TOWNSHIP 158 RANGE 33E NMPI	
15. Elevation (Show whether DF, RT, GR, etc.) 4205.5 GR	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or O	
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOS	PLUG AND ABANDONMENT
OTHER	L_
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includitional) SEE RULE 1103.	ng estimated date of starting any propos
Propose to plug and abandon well as follows:  Set a CIBP at 4700' w/35' cement on top.  Cut off 5-1/2" casing at about 3750' and pull.  Set plug across stub - 100' plug or 25 sx cement.  Set plug at 1550-1450' - 100' or 25 sx cement.  Set plug at 20' to surface w/10 sx cement.	
Clean location, install P&A marker.	
Tag stus plug	
Load hole w/ 10# Salt Gel	- es Notten 21
Food hole W 10 Salt Gel  TO COMMISSION M HOURS STUDE TO PRUCCING UPERATE PRUCCING UPERATE TO BE ASPROYED.	UST PROBLEM OF CHES
8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Production Supervisor	DATE 2-27-84

FEB 29 1984

Eddie W. Seay