

NO. OF COPIES RECEIVED		
DISTRIBUTION		
STAFF		
E		
G.S.		
ND OFFICE		
ERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-63

30-025-28646

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Maralo, Inc.

Address of Operator

P.O. Box 832, Midland, Tx 79702-0832

Location of Well

UNIT LETTER J 1980 East 1980
South 10 15-S 33-E
THE LINE, SECTION TOWNSHIP RANGE NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

State "10"

9. Well No.

2

10. Field and Pool, or Wildcat
Saunders (Bough "G")

12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
4180.9 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK ☐

PERMANENTLY ABANDON ☐

DRILL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

1. Notify NMOCC prior to operations.
2. RUPU. TOH w/pumping equipment.
3. RU wireline. TIH w/5 1/2" CIBP and set @ $\pm$ 9800'. Can w/35' amt (5 sx).
4. TIH w/tbg open ended to PBTD and load hole w/9.5#/gal mud-laden fluid.
5. Spot 100' amt plug (25 sx) from 8882-8982- (across DV tool).
6. Spot 100' amt plug (25 sx) from 5735-5835' (across Glorieta).
7. RU csg cutters and cut 5 1/2" acg @ $\pm$ 4,000' (inside 8 5/8" csg). Pull and lay down scg.
8. TIH w/tbg. Spot 100' amt plug (30 sx) from 3950' to 4050' (across csg stub).
9. Spot 100' plug (35 sx) from 1500' to 1600' (across Rustler).
10. Spot 100' plug (35 sx) from 350' to 450'.
11. Spot 10' plug (5 sx) at surface.
12. Cut off wellhead, weld on P&A plate, and clean up location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Brenda Coffman

Agent

DATE 6-26-90

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

SIGNED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 29 1990

MOBIL 111114