Day a ded

	State of Nev	w Mexico		-1M	nend	~~~	
TRICT I	Energy, Minerals and Natura	al Resources De	epartment	IWELL APLINO			
OIL CONSERVATION DIVISION			NEED AN ONE	30-025-28994			
Drawer DD, Artesia NM 88210 P.O. Box 2088							
FRICT III	Santa Fe, New Mexico	87504-2088		5. Indicate Type	of Lease		
Rio Brazos Rd., Aztec NM 87410				State	Fee	X	
(DO NOT USE THIS FORM FO	ES AND REPORTS ON WELLS OR PROPOSALS TO DRILL OR T SERVOIR. USE "APPLICATION		PLUG BACK TO A	7. Lease Name	or Unit Agreeme		
GAS LL X WELL OTI	HER				SHIPP	ZI	
	etroleum Corporation			8. Well No.	2		
Address of Operator 105 South 4th., Artesia, NM 88210					9. Pool Name or Wildcat Lovington Penn Northeast		
rit Letter D # 660 Fed	et From The NORTH	Line and	1100	Feet From The	WE	ST Line	
ection 27 Township	16S Range 37E	NMPM			LEA	COUNTY	
10. Eleva	ition (Show whether DF, R		c.)				
Check Appropriate Bo	ox to Indicate Nature of		ort, or Other Data	a		Little State of Consideration College State State College State State College State	
PORARILY ABANDON CH	IANGE PLANS		E DRILLING OPNS. ST AND CEMENT JOB	PLOG AND	ABANDONMEN	''	
PORARILY ABANDON CH OR ALTER CASING CH ER Describe Proposed or Completed ate of starting any proposed work	d Operations (Clearly state as) SEE RULE 1103. OSES TO PLUG & AB	OTHER all pertient details	ST AND CEMENT JOB	et dates, includ	ting estimate	ed	
Describe Proposed or Completed late of starting any proposed work ATES PETROLEUM PROPIRU PU & safety equipment	d Operations (Clearly state at Section 2) SEE RULE 1103. OSES TO PLUG & AB	OTHER all pertient detail BANDON AS & 2-7/8" work	ST AND CEMENT JOB Ils, and give pertinent FOLLOWS: k string. TIH to to	et dates, includ	ting estimate	ed ull ip one jt.	
Describe Proposed or Completed date of starting any proposed work ATES PETROLEUM PROPIRU PU & safety equipment and set packer. Pump 100 gar H - fish junk in hole. RIH w/0114-10014' to isolate Wolfd	Operations (Clearly state at SEE RULE 1103. OSES TO PLUG & AB at Pick up 5-1/2" packer als xylene & 500 gals 15 CIBP & set @ 11400'.	CASING TES OTHER all pertient detail BANDON AS & 2-7/8" wor 5% HCL - dis Dump 35' ce	FOLLOWS: k string. TIH to to place acid to 107	op of fish @722'; let sit I	8087'. Pu hour, flusl	ull ip one jt. In to perfs w/ water	
Describe Proposed or Completed late of starting any proposed work ATES PETROLEUM PROPIRU PU & safety equipment and set packer. Pump 100 gard H - fish junk in hole. RIH w/0114-10014' to isolate Wolfd U wireline, cut casing @ 836 oo' cement plug to isolate All H w/ tubing to 6151'; spot 1 intermediate shoe. WOC &	Operations (Clearly state at SEE RULE 1103. OSES TO PLUG & AB at Pick up 5-1/2" packer als xylene & 500 gals 150 CIBP & set @ 11400'. Camp. TOH w/ tubing. Oo'. RU casing pullers, to work at a glug. Oo' cement plug 6151-60 at ag. Spot 100' cement	CASING TEST OTHER all pertient detail SANDON AS & 2-7/8" work 5% HCL - dis Dump 35' ce TAG pull & lay do 6051' to isolat plug 3306-3	FOLLOWS: "k string. TIH to to place acid to 107 ment on plug. TI wn 5-1/2" casing. te Glorieta. WOC 206' over Yates.	op of fish @ 722'; let sit I H w/ tubing TIH w/ tubing C & tag plug. Spot 100' ce	8087'. Puthour, flushed spot 100 mg to 835	all ip one jt. In to perfs w/ water O' cement plug O' & spot	
Describe Proposed or Completed late of starting any proposed work ATES PETROLEUM PROPIEW Packer. Pump 100 gas H - fish junk in hole. RIH w/ 10114-10014' to isolate Wolfd J wireline, cut casing @ 836 DO' cement plug to isolate All H w/ tubing to 6151'; spot 1 intermediate shoe. WOC & 200' cement plug 505-405' according to 100' cement plug 505' cemen	d Operations (Clearly state at SEE RULE 1103. OSES TO PLUG & AB d. Pick up 5-1/2" packer als xylene & 500 gals 15 CIBP & set @ 11400'. camp. TOH w/ tubing. 00'. RU casing pullers, ploo. WOC & tag plug. 00' cement plug 6151-6 a tag. Spot 100' cement cross surface shoel Spot	CASING TEST OTHER all pertient detail BANDON AS & 2-7/8" work 5% HCL - dis Dump 35' ce TAG pull & lay do 6051' to isolate plug 3306-30 ot 60' cement move off.	FOLLOWS: "k string. TIH to to place acid to 107 ment on plug. TI wn 5-1/2" casing. te Glorieta. WOC 206' over Yates.	et dates, included pop of fish @ 722'; let sit I !! H w/ tubing . TIH w/ tubing . TIH w/ tubing . Spot 100' ce	8087'. Puhour, flush & spot 100 mg to 8350 ment plush SINOTERE	ord Ill ip one jt. In to perfs w/ water O' cement plug O' & spot O' plug 4369-426 g 2130-2230'; s	
MPORARILY ABANDON CHAPTER CASING THER Describe Proposed or Completed date of starting any proposed work of the ATES PETROLEUM PROPIRU PU & safety equipment and set packer. Pump 100 gas H - fish junk in hole. RIH w/0114-10014' to isolate Wolfd U wireline, cut casing @ 8300' cement plug to isolate All H w/ tubing to 6151'; spot 1 intermediate shoe. WOC & 100' cement plug 505-405' accept regulation abandonment is constructed by the control of the contro	d Operations (Clearly state at SEE RULE 1103. OSES TO PLUG & AB at Pick up 5-1/2" packer als xylene & 500 gals 15. CIBP & set @ 11400'. Camp. TOH w/ tubing. Oo'. RU casing pullers, bo. WOC & tag plug. Oo' cement plug 6151-6. A tag. Spot 100' cement cross surface shoet Spot marker, clean location,	CASING TEST OTHER all pertient detail BANDON AS & 2-7/8" work 5% HCL - dis Dump 35' ce TAG pull & lay do 6051' to isolate plug 3306-30 ot 60' cement move off.	FOLLOWS: "k string. TIH to to place acid to 107 ment on plug. TI win 5-1/2" casing te Glorieta. WOC 206' over Yates. It plug @ surface. HOURS PRIOR PLUGGING OPE	op of fish @ 722'; let sit I! H w/ tubing . TIH w/ tubing . TIH w/ tubing . Spot 100' ce . ON MUST BE TO THE REFRACION S FEED.	8087'. Puhour, flush & spot 100 mg to 8350 ment plush SINOTERE	ord Ill ip one jt. In to perfs w/ water O' cement plug O' & spot O' plug 4369-426 g 2130-2230'; s	
ATES PETROLEUM PROPING A set packer. Pump 100 gallow wireline, cut casing @ 8300' cement plug to isolate Allow tubing to 6151'; spot 1 intermediate shoe. WOC & 00' cement plug 505-405' acet regulation abandonment with the state of the state of starting and proposed work at the	d Operations (Clearly state at SEE RULE 1103. OSES TO PLUG & AB at Pick up 5-1/2" packer als xylene & 500 gals 15. CIBP & set @ 11400'. Camp. TOH w/ tubing. Oo'. RU casing pullers, bo. WOC & tag plug. Oo' cement plug 6151-6. A tag. Spot 100' cement cross surface shoet Spot marker, clean location,	casing terms of the results of the results and pertient details and pert	FOLLOWS: "k string. TIH to to place acid to 107 ment on plug. TI win 5-1/2" casing te Glorieta. WOC 206' over Yates. to plug @ surface. THE COMM'SSIC HOURS PRICE PLUGGING OPE APPROVE	op of fish @ 722'; let sit I! H w/ tubing . TIH w/ tubing . TIH w/ tubing . Spot 100' ce . ON MUST BE TO THE REFRACION S FEED.	8087'. Puthour, flush & spot 100 ag to 835. Spot 100 ament plush GHNNING OR THE CONTRELEGION CON	all ip one jt. In to perfs w/ water O' cement plug O' & spot O' plug 4369-426 g 2130-2230'; s	
ATES PETROLEUM PROPIEW In June 100 June	d Operations (Clearly state at SEE RULE 1103. OSES TO PLUG & AB t. Pick up 5-1/2" packer als xylene & 500 gals 15 CIBP & set @ 11400'. camp. TOH w/ tubing. 00'. RU casing pullers, ploo. WOC & tag plug. 00' cement plug 6151-6 tag. Spot 100' cement cross surface shoel Spot marker, clean location, TAG TAGE TOM CLACK	casing terms of the results of the results and pertient details and pert	FOLLOWS: "k string. TIH to to place acid to 107 ment on plug. TI with 5-1/2" casing te Glorieta. WOC 206' over Yates. It plug @ surface. THE COMMISSIONED PRIOR PLUGGING OPETO BE APPROVE	op of fish @ 722'; let sit I! H w/ tubing . TIH w/ tubing . TIH w/ tubing . Spot 100' ce . ON MUST BE TO THE REFRACION S FEED.	8087'. Puthour, flush & spot 100 mg to 8350 ment plush GANNING OR THE COLOR	od all ip one jt. In to perfs w/ water O' cement plug O' & spot O' plug 4369-426 g 2130-2230'; s	