

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-101160	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry		7. Unit Agreement Name ---
2. Name of Operator Exxon Corp.		8. Form or Lease Name New Mexico EJ State
3. Address of Operator P. O. Box 1600, Midland, TX 79702		9. Well No. 1
4. Location of Well UNIT LETTER 0 660 FEET FROM THE South LINE AND 2280 FEET FROM THE East LINE, SECTION 22 TOWNSHIP 16S RANGE 34E NMPM.		10. Field and Pool, or Whidcat Undesig. Kemnitz/Morro
15. Elevation (Show whether DF, RT, GR, etc.) KB-4105, DF-4104, GL-4081.2		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1702.

The above well will be plugged and abandoned as follows:

Set plug #1 at 6650 w/ 30 sx cmt.  
Set plug #2 at 6020 w/ 30 sx cmt.  
Set plug #3 at 4918 w/ 30 sx cmt.  
Set plug #4 at 1700 w/ 35 sx cmt.  
Set plug #5 at 100' w/ 35 sx cmt.

Cut off wellhead and install dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jersey Sexton</u>	TITLE <u>Unit Head</u>	DATE <u>6-18-85</u>
ORIGINAL SIGNED BY JERSEY SEXTON DISTRICT SUPERVISOR		JUN 20 1985
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUN 19 1985

O.C.D.  
HOBBS OFFICE