

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATION	

3a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEMENT OR PLUG BACK TO A DIFFERENT RESERVOIR.
(SEE APPLICATION FOR PERMIT - C-103 FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER-	7. Unit Agreement Name
2. Name of Operator Santa Fe Energy Company	8. Farm or Lease Name Rustler 8 State
3. Address of Operator 500 W. Illinois, Suite 500, Midland, TX 79701	9. Well No. 1
4. Location of well UNIT LETTER 0 1650 FEET FROM THE East LINE AND 660 FEET FROM THE South LINE, SECTION 8 TOWNSHIP 15S RANGE 32E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether Dr, RT, GR, etc.) 4321.5 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PBTD @ 12,162. Load hole w/9.5 ppg mud. Spot 100' cmt plug @ 11,688-11,788' @ Atoka top. Spot 100' cmt plug @ 10,653-10,753' @ Canyon top. Spot 100' cmt plug @ 10,011-10,111' @ Cisco top. Spot 100' cmt plug @ 9838-9938' @ Bough "C" top. Spot 100' cmt plug @ 8970-9070' @ Wolfcamp top. Shoot & POOH w/5½" csg. Spot 100' cmt plug across 5½" csg stub. Tag plug. Spot 100' cmt plug @ 7600-7700' @ ABO top. Spot 100' cmt plug @ 5528-5628' @ Glorieta top. Spot 100' cmt plug @ 4000-4100' @ 8-5/8" csg shoe. Tag plug. Spot 100' cmt plug @ 402-502' @ 13-3/8" csg shoe, set 10 sx plug @ surface. Cut off wellhead. Install dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED P. J. Gaume TITLE Sr. Production Engineer DATE 6-28-85
P. J. Gaume
ORIGINAL SIGNATURE
APPROVED BY INSTRUCT TITLE DATE JUL - 2 1985
CONDITIONS OF APPROVAL, IF ANY: