

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

3a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. A-1320	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Dry		7. Unit Agreement Name --
2. Name of Operator Exxon Corporation		8. Farm or Lease Name New Mexico EQ State
3. Address of Operator P. O. Box 1600, Midland, TX 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>16S</u> RANGE <u>35E</u> NMPM.		10. Field and Pool, or Whicat Townsend - Morrow
15. Elevation (Show whether DF, RT, GR, etc.) KB-4027'; DF-4026'; GL-4003.5'		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1702.

The above well will be plugged and abandoned as follows:

12558 - 12259; 11772 - 11473; 10392 - 10093; 9732 - 9433; 8286 - 7987; 6351 - 6052;
5010 - 4733 w/ 100 sx ClH Neat on each interval; and 562 - 427 w/ 50 sx ClH Neat.
Surface plug will be set with 10 sx ClH. Set dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Melba Knippling</u>	TITLE <u>Unit Head</u>	DATE <u>6-11-85</u>
ORIGINAL SIGNED BY JERRY SEXTON		
APPROVED BY <u>DISTRICT SUPERVISOR</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

JUN 13 1985

RECEIVED

JUN 12 1985

HOBBS OFFICE