Submit 3 Copies

TEMPORARILY ABANDON

PULL OR ALTER CASING

11.

OTHER:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

to Appropriate
District Office

OIL	CONSER	VATION	DIVISIO	N

to Appropriate District Office	E	nergy, Minerals and Na	iurai Ke	Sources Department		Kevised 1-	1-07
OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			WELL API NO.				
Santa Fe, New Mexico 87504-2088 O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE  FEE  6. State Oil & Gas Lease No. V-496				
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410							
SUN	IDRY NOTICE	S AND REPORTS O	N WEL	LS			
( DO NOT USE THIS FO	RM FOR PROPORTION	SALS TO DRILL OR TO D HR. USE "APPLICATION I ) FOR SUCH PROPOSAL	DEEPEN FOR PEF	OR PLUG BACK TO A	7. Lease Name of	or Unit Agreement Name	
Type of Well:	GAS WELL	OTHER			State H	1-1	
2. Name of Operator					8. Well No.		
Mewbourne Oi.  3. Address of Operator	1 Company				9. Pool name or	Wildcat	
•	O Hobbs.	New Mexico 882	40		Hume Wo	lfcamp	
4. Well Location							
Unit LetterA	<u> </u>	Feet From The No.	rth	Line and1040	Feet Fro	m The <u>East</u>	Line
7				245	NMPM	Lea	County
Section /	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Township 16S 10. Elevation (Show	Ka whether	nge 34E. DF, RKB, RT, GR, etc.)	141411 141	77/////////////////////////////////////	
						<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	
11.	Check Ap	propriate Box to Inc	dicate l	Nature of Notice, R	eport, or Othe	er Data	
	E OF INTE			SUE	SEQUENT	REPORT OF:	
ERFORM REMEDIAL WO		PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	
EMPORARILY ABANDON	N $\square$	CHANGE PLANS		COMMENCE DRILLIN	GOPNS.	PLUG AND ABANDO	ONMENT L
ULL OR ALTER CASING	. 🗆			CASING TEST AND C	EMENT JOB 🔲		-
OTHER:			_ 🗆	OTHER: Plug b	ack to Wolf	camp	
12. Describe Proposed or Co work) SEE RULE 1103	ompleted Operation	8 (Clearly state all pertinent	details, ar	nd give pertinent dates, incli	uding estimated date	of starting any proposed	
3/02/94 Perf 3/03/94 Acid 3/05/94 Set	orate Wolf lize with l retrievabl	P at 12,340'. camp from 10,38 200 gallons 15% e bridge plug a 10,028' and 99	0' - HCL a t 10,	10,388'. Spot acid. Swab & t 267'. `Dump 2	2 bbls. 109 test. sx. sand. 1	% acetic acid. Perforate Wolf acetic acid.	
3/08/94 Acid	lize with 2	.200 gallon <b>s</b> 15%	HCL	acid. Swab & t	est.		
		o evaluate.					
							•
I hereby certify that the inform	ation above is true and	d complete to the best of my kno	owledge and	ibele. Engineer		3/16,	/94

hereby certify that the inform	nation above is true and complete to the best of my	y knowledge and belief.	
6 /	//// 21/1	Engineer	PATE3/16/94
SIGNATURE 7		INLE	(505)
	- 4 1 17 37 1		те <b>лерноме мо.</b> 393–5905
TYPE OR PRINT NAME  I	Frick W. Nelson		

This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR DATE

MAR 22 199

VPROVED BY -