

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|                                                                                                     |
|-----------------------------------------------------------------------------------------------------|
| WELL API NO.<br>30-025-29566                                                                        |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>K-5187                                                              |
| 7. Lease Name or Unit Agreement Name<br>State "17"                                                  |
| 8. Well No.<br>2                                                                                    |
| 9. Pool name or Wildcat<br>Lovington, N.E. (Penn)                                                   |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br>3844 GL, 3862 KB                              |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                   |                                                                                                                                                          |
|-----------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 2. Name of Operator<br>Pennzoil Exploration And Prod. Co.                                                                                                |
| 3. Address of Operator<br>P.O. Drawer 1828 Midland, Texas 79702                                                                   | 4. Well Location<br>Unit Letter L : 1400 Feet From The South Line and 660 Feet From The West Line<br>Section 17 Township 16-S Range 37-E NMPM Lea County |

|                                                                               |                                                     |
|-------------------------------------------------------------------------------|-----------------------------------------------------|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data |                                                     |
| NOTICE OF INTENTION TO:                                                       | SUBSEQUENT REPORT OF:                               |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                                | REMEDIAL WORK <input type="checkbox"/>              |
| TEMPORARILY ABANDON <input type="checkbox"/>                                  | ALTERING CASING <input type="checkbox"/>            |
| PULL OR ALTER CASING <input type="checkbox"/>                                 | COMMENCE DRILLING OPNS. <input type="checkbox"/>    |
| OTHER: <input type="checkbox"/>                                               | PLUG AND ABANDONMENT <input type="checkbox"/>       |
|                                                                               | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
|                                                                               | OTHER: <input type="checkbox"/>                     |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P & A well per the attached wellbore diagrams.

- 1) Set CIBP w/35' cmt @ 11,300'.
- 2) Load hole w/10#/gal brine mud.
- 3) Cut & pull 5 1/2" casing @ 8000'.
- 4) Set 100' (50sk) plug 50' in & out of stub - tag -
- 5) Set remaining plugs as follows.  
6313'-6413' (35 sacks)  
4143'-4243' (50 sacks) - tag -  
2037'-2137' (35 sacks)  
10' surface plug.
- 6) Install surface marker & clean up location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy M. Hodgins TITLE Engineer DATE 05-04-92  
TYPE OR PRINT NAME Randy M. Hodgins TELEPHONE NO. 915/682-7316

(This space for State Use)

APPROVED BY Orig. Signed by Paul Kautz TITLE Geologist DATE MAY 07 '92  
CONDITIONS OF APPROVAL, IF ANY: