

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-02529764
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-4717
7. Lease Name or Unit Agreement Name  Chevron State
8. Well No. #1
9. Pool name or Wildcat North Sanmal Penn

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Hondo Drilling Company
3. Address of Operator P.O. Drawer 2516 Midland, TX 79702-2516
4. Well Location Unit Letter <u>E</u> : <u>1,980'</u> Feet From The <u>North</u> Line and <u>660'</u> Feet From The <u>West</u> Line Section <u>8</u> Township <u>16-S</u> Range <u>33-E</u> NMPM <u>Lea</u> County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>abandon</u> <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

03-07-91	Pull 2 3/8" tubing and Baker Packer out of hole. Set cast iron bridge. Plug at 10,775'. Dump 40' of cement on top of bridge plug.
03-08-91	Perforate Wolfcamp zone from 10,646' to 10,654'. Total of 8'-two shots per foot. Pressure test 2 3/8" tubing in hole, set Guiberson packer at 10,575'. Swab tested well and acidized with 2,000 gal. 7 1/2% acid.
03-09-91	Swabbing well recovered 47 bbl. of fluid (38 bbls. of water & 9 bbls. of oil).

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>[Signature]</u>	TITLE <u>President</u>	DATE <u>6/14/91</u>
TYPE OR PRINT NAME		TELEPHONE NO.

(This space for State Use)

APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		