Submit 3 Copies S to Appropriate Env , Minerals	itate of New Mexico s and Natural Resources Department	Form C-103
District Office		Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbe, NM 88240 DISTRICT II DISTRICT II Santa Fe, New Mexico 87504-2088		WELL API NO. 30-025-30987
P.O. Drawer DD, Artesia, NM 88210	New Mexico 8/504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lease No. VB-0364
SUNDRY NOTICES AND REPO	ORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL DIFFERENT RESERVOIR. USE *APPLIC (FORM C-101) FOR SUCH PRO	CATION FOR PERMIT"	7. Lease Name or Unit Agreement Name WESTERN 17F STATE
I. Type of Well: OIL OAS WELL X WELL O)THER	
2. Name of Operator NEARBURG PRODUCING COMPANY		& Well No. 1
3. Address of Operator P.O. BOX 823085, DALLAS, TEXAS	75382-3085	9. Pool name or Wildcat LOVINGTON-PENNSYLVANIAN, NORTHEAST
4. Well Location		•
Unit Letter _ F _ : 2,130 Feet From The _	NORTH Line and 2,13	0 Feet From The WEST L
Section 17 Township 16		NMPM LEA County
///////////////////////////////////////	on (Show whether DF, RKB, RT, GR, etc.) 3,837' GR	
	to Indicate Nature of Notice, I	Report, or Other Data
NOTICE OF INTENTION TO:	SU	BSEQUENT REPORT OF:
		ALTERING CASING
—		
EMPORARILY ABANDON		
EMPORARILY ABANDON CHANGE PLAN	IS COMMENCE DRILLIN CASING TEST AND C	
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER:	AS COMMENCE DRILLIN CASING TEST AND C OTHER: ACTIV	IG OPNS. PLUG AND ABANDONMENT
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER:	AS COMMENCE DRILLIN CASING TEST AND C OTHER: ACTIV	IG OPNS. PLUG AND ABANDONMENT
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 12. Describe Proposed or Completed Operations (Clearly state all per work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole	e w/250 bb1s. 2% KCL.	IG OPNS. PLUG AND ABANDONMENT EMENT JOB . ity uding estimated date of starting any proposed
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operations (Clearly state all per work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole log from 11,520' to 9,4 03/15/91: Perforated Strawn from	AS COMMENCE DRILLIN CASING TEST AND C OTHER: ACTIV ertinent details, and give pertinent dates, incl e w/250 bb1s. 2% KCL. 1 445'. 11,442' to 11.448'. 11	IG OPNS. PLUG AND ABANDONMENT EMENT JOB . ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/(452' to 11.458', 11.462' to
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operations (Clearly state all po work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to	AS COMMENCE DRILLIN CASING TEST AND C OTHER: ACTIV ertinent details, and give pertinent dates, incl e w/250 bb1s. 2% KCL. 1 445'. 11,442' to 11.448'. 11	IG OPNS. PLUG AND ABANDONMENT EMENT JOB . ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/(452' to 11.458', 11.462' to
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 22 Describe Proposed or Completed Operations (Clearly state all pa work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1	COMMENCE DRILLIN CASING TEST AND C OTHER: Activity entinent details, and give pertinent dates, incl e w/250 bb1s. 2% KCL. 1 445'. 11,442' to 11,448', 11 11,474' w/4 JSPF (105 k	AG OPNS. PLUG AND ABANDONMENT CEMENT JOB . ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/(,452' to 11,458', 11,462' to noles) using 3-3/8" casing gur
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operations (Clearly state all per work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1 03/21/91: Swab testing.	COMMENCE DRILLIN CASING TEST AND C OTHER: Activ errinent details, and give pertinent dates, incl e w/250 bbls. 2% KCL. I 445'. 11,442' to 11,448', 11 11,474' w/4 JSPF (105 f 15% HCL NEFE acid, swabb	AG OPNS. PLUG AND ABANDONMENT EMENT JOB ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/(,452' to 11,458', 11,462' to holes) using 3-3/8" casing gur ping back load.
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operations (Clearly state all per work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hold log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1 03/22/91: Acidized w/7,500 gal. 9	COMMENCE DRILLIN CASING TEST AND C OTHER: Activ errinent details, and give pertinent dates, incl e w/250 bbls. 2% KCL. I 445'. 11,442' to 11,448', 11 11,474' w/4 JSPF (105 H 15% HCL NEFE acid, swabb gelled acid and 75 ball	AG OPNS. PLUG AND ABANDONMENT EMENT JOB ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/(,452' to 11,458', 11,462' to holes) using 3-3/8" casing gur ping back load.
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operations (Clearly state all per work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1 03/22/91: Swab testing. 03/22/91: Acidized w/7,500 gal. 9 04/03/91: Swab and flow testing f	COMMENCE DRILLIN CASING TEST AND C OTHER: Activ entiment details, and give pertiment dates, incl e w/250 bbls. 2% KCL. F 445'. 11,442' to 11,448', 11 11,474' w/4 JSPF (105 F 15% HCL NEFE acid, swabt gelled acid and 75 ball for 10 days.	AG OPNS. PLUG AND ABANDONMENT EMENT JOB ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/(452' to 11,458', 11,462' to holes) using 3-3/8" casing gur bing back load. sealers.
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 2 Describe Proposed or Completed Operations (Clearly state all pa work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1 03/22/91: Acidized w/7,500 gal. 9 04/03/91: Swab and flow testing f 04/04/91: Acidized w/15,000 gal. 04/07/91: Flow to clean up for 3	COMMENCE DRILLIN CASING TEST AND C OTHER: Activ entirent details, and give pertinent dates, incl e w/250 bbls. 2% KCL. If 445'. 11,442' to 11,448', 11, 11,474' w/4 JSPF (105 f 15% HCL NEFE acid, swabt gelled acid and 75 ball for 10 days. 20% HCL and 15,000 gal.	AG OPNS. PLUG AND ABANDONMENT EMENT JOB ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/(452' to 11,458', 11,462' to holes) using 3-3/8" casing gur bing back load. sealers.
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Operations (Clearly state all privork) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1 03/22/91: Acidized w/7,500 gal. 0 04/03/91: Swab and flow testing for the strained flow testing for the strained flow flow flow for the strained flow flow flow flow flow flow flow flow	COMMENCE DRILLIN CASING TEST AND C OTHER: Activ entirent details, and give pertinent dates, incl e w/250 bbls. 2% KCL. If 445'. 11,442' to 11,448', 11, 11,474' w/4 JSPF (105 f 15% HCL NEFE acid, swabt gelled acid and 75 ball for 10 days. 20% HCL and 15,000 gal.	AG OPNS. PLUG AND ABANDONMENT EMENT JOB ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/(452' to 11,458', 11,462' to holes) using 3-3/8" casing gur bing back load. sealers.
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operations (Clearly state all perform) work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1 03/22/91: Acidized w/7,500 gal. 9 04/03/91: Swab and flow testing for 3 04/07/91: Flow to clean up for 3 04/08/91: Flow test.	AS COMMENCE DRILLIN CASING TEST AND CONTER: Activ OTHER: Activ entiment details, and give pertiment dates, incl e w/250 bbls. 2% KCL. If 445'. 11,442' to 11,448', 11, 11,474' w/4 JSPF (105 H 15% HCL NEFE acid, swabt gelled acid and 75 ball for 10 days. 20% HCL and 15,000 gal. days.	AG OPNS. PLUG AND ABANDONMENT EMENT JOB ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/(452' to 11,458', 11,462' to holes) using 3-3/8" casing gur bing back load. sealers.
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 12. Describe Proposed or Completed Operations (Clearly state all per- work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hold log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1 03/21/91: Swab testing. 03/22/91: Acidized w/7,500 gal. 0 04/03/91: Swab and flow testing flow 04/04/91: Acidized w/15,000 gal. 04/07/91: Flow to clean up for 3 04/08/91: Flow test.	COMMENCE DRILLIN CASING TEST AND C OTHER: Activ errinent details, and give pertinent dates, incl e w/250 bbls. 2% KCL. If 445'. 11,442' to 11,448', 11 11,474' w/4 JSPF (105 H 15% HCL NEFE acid, swabt gelled acid and 75 ball for 10 days. 20% HCL and 15,000 gal. days.	AG OPNS. PLUG AND ABANDONMENT EMENT JOB ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/O A52' to 11,458', 11,462' to holes) using 3-3/8" casing gur bing back load. Sealers. CO2. Flowed well back.
EMPORARILY ABANDON CHANGE PLAN ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operations (Clearly state all per- work) SEE RULE 1103. 03/14/91: Ran tubing, loaded hole log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1 03/21/91: Swab testing. 03/22/91: Acidized w/7,500 gal. 9 04/03/91: Swab and flow testing for 3 04/07/91: Flow to clean up for 3 04/08/91: Flow test.	COMMENCE DRILLIN CASING TEST AND C OTHER: Activ errinent details, and give pertinent dates, incl e w/250 bbls. 2% KCL. If 445'. 11,442' to 11,448', 11 11,474' w/4 JSPF (105 H 15% HCL NEFE acid, swabt gelled acid and 75 ball for 10 days. 20% HCL and 15,000 gal. days.	AG OPNS. PLUG AND ABANDONMENT EMENT JOB ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/O ,452' to 11,458', 11,462' to holes) using 3-3/8" casing gun bing back load. Sealers.
EMPORARILY ABANDON CHANGE PLAN PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Operations (Clearly state all perwork) SEE RULE 1103. 03/14/91: Ran tubing, loaded hold log from 11,520' to 9,4 03/14/91: Ran tubing, loaded hold log from 11,520' to 9,4 03/15/91: Perforated Strawn from 11,468' and 11,470' to 03/16/91: Swabbed well down. 03/18/91: Acidized w/1,000 gal. 1 03/22/91: Acidized w/1,000 gal. 1 03/22/91: Acidized w/7,500 gal. 0 04/03/91: Swab and flow testing flow testing flow testing flow testing flow testing flow testing flow test. I bereby certify that the information above is true and complete to the best of SKONATURE Mathematical above is true and complete to the best of skonature	COMMENCE DRILLIN CASING TEST AND C OTHER: Activ errinent details, and give pertinent dates, incl e w/250 bbls. 2% KCL. If 445'. 11,442' to 11,448', 11 11,474' w/4 JSPF (105 H 15% HCL NEFE acid, swabt gelled acid and 75 ball for 10 days. 20% HCL and 15,000 gal. days.	AG OPNS. PLUG AND ABANDONMENT EMENT JOB ity wding estimated date of starting any proposed Pulled tubing, ran Gamma Ray/O ,452' to 11,458', 11,462' to holes) using 3-3/8" casing gun bing back load. Sealers. CO2. Flowed well back.