ibmit 3 Copies	State of New Mexico Energy, and Natural Resources Department		Form C-103 Revised 1-1-89	
) Appropriate District Office	0.0			
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II DISTRICT II OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.		
		30-025-31272		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic	0 8/304-2088	5. Indicate Type of Lease STATE	X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. V-3273	
SUNDRY NOT	ICES AND REPORTS ON W	ELLS		
(DO NOT USE THIS FORM FOR PR DIFFERENT RESE (FORM C	OPOSALS TO DRILL OR TO DEEP RVOIR. USE "APPLICATION FOR F C-101) FOR SUCH PROPOSALS.)	EN OR PLUG BACK TO A	7. Lease Name or Unit Agreemen	nt Name
1. Type of Well: OL GAS WELL X WELL	OTHER	· ·	Eidson Ranch Un	it
WELL X WELL			8. Well No.	
YATES PETROLEUM CORPO	RATION	· · · · · · · · · · · · · · · · · · ·	1	
3. Address of Operator			9. Pool name or Wildcat	C
	et - Artesia, NM 8821	0	San Andres Arab	<u> </u>
4. Well Location Unit Letter :201	80 Feet From The South	Line and 660	Feet From TheEas	t Line
Section 5	Township 16S	Range 33E	NMPM Lea	County
	10. Elevation (Show whet	her DF, RKB, RT, GR, etc.)		
////////////////////////////////////</td <td></td> <td>218' GR</td> <td></td> <td></td>		218' GR		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF IN	ITENTION TO:	SUI	BSEQUENT REPORT	
	CHANGE PLANS			
		CASING TEST AND CEMENT		
OTHER:				
12 Describe Proposed or Completed One	erations (Clearly state all pertinent detai	ls, and give pertinent dates, inc	luding estimated date of starting any	proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
Verbal permission was received by Rex Gates with Yates Petroleum Corporation from Paul Kautz with the Oil Conservation Division on June 27, 1994, to plug and abandon well as				
follows:				
1. Set CIBP at 5600'	and cap with 35' of ce	ment.	" casing shoe at 447	2',
 Set CIBF at 5000° and cap with 55° of bencher 2. Cut and pull 5-1/2" casing. If unable to cut below 8-5/8" casing shoe at 4472', set a 100' cement plug across shoe (50' above and below). 3. If able to cut and pull 5-1/2" casing below 4472', then set a 100' cement plug across 				
r 1/01				
 5-1/2" casing stub. 4. Set 100' cement plug across 8-5/8" casing shoe at 4472' (50' above and below). 5. Set 100' cement plug across the top of the Rustler at 1420' (50' above and below). 				
5. Set 100' cement pl	lug across the top of t	he Rustler at 142	0' (50' above and be	1ow)
6. Set a 10 sack surf	face plug.			
	n abandonment marker.			
NOTIFY OCD (393-6161)	24 HOURS PRIOR TO COMM	MENCING PLUGGING.C	PERATIONS.	
I hereby certify that the information above is	s true and complete to the best of my knowled			()7 0/
SIGNATURE Kusty	Hein	_ mre Production	Clerk DATE	6-27-94
TYPE OR PRINT NAME RUSTY KIE:	in		505 TELEPT	-748-1471 HONTE NO.
(This space for State Use)		ORIGINAL SIGNE DISTRICT I	D BY JERRY SEXTON SUPERV.SOR	
APTROVED BY		TTTLE	DATE	
Construction TASY				