Submit 3 popies o Appi priate			State of Energy, N ^{er} Prais	of New Mexico s and Natural Res	sources Department		Form C-103 Revised 1-1-89
District Office		01	L CONSEF	VATION	DIVISION		
		U		ta Fe Trail, Room			WELL API NO.
<u>DISTRICT I</u> 10. Box 1980, F	Hobbs, NM 8824)		New Mexico 87			30-025-32731
			,				5 Indicate Turns of Lance
<u>ISTRICT</u> II O. Box Drawer	r DD, Artesia, NN	1 88210					5. Indicate Type of Lease STATE X FEE
ISTRICT III							6. State Oil & Gas Lease No. B-2148
000 Rio Brazos	Rd., Aztec, NM	87410					D-2146
(DO	NOT USE TH	HIS FORM FO		O DRILL OR TO	S ON WELLS DEEPEN OR PLUG I ATION FOR PERMIT		7 Lease Name or Unit Agreement Name
			RM C-101) FOR S				
Type of Well Oil Well			OTHER				Caprock Maljamar Unit
Name of Op	erator						8. Well No.
Address of C		The Wiser Oil	Company	· · · · · · · · · · · · · · · · · · ·			67 9. Pool name or Wildcat
. Address of C	•	115 Preston H	Road, Suite 400, D	Dallas, TX 7522	5		Maljamar Grayburg San Andres
Well Locatio		I : 1945	East East The	South Line and	734	Feet From The	East Line
ι	Unit Letter	<u> </u>	Feet From The	Line and		_ rearrant from the	Line
	Section	19 то	wnship	Range 17S		33E	County Lea
				ow whetther DF RKB, G			
1		TIOT OF DIT		Appropriate Box to I	ndicate Nature of Notice		Data JENT REPORT OF:
1		THUE OF INT	ENTION TO:			SUBSEQU	
1	NO						
	NO EMEDIAL WO		PLUG AND ABA	ANDON	REMEDIAL WORK		ALTERING CASING
ERFORM RI		PRK	PLUG AND ABA CHANGE PLAN		REMEDIAL WORK		ALTERING CASING PLUG AND ABANDONMENT
ERFORM RI EMPORARI	EMEDIAL WO	PRK			COMMENCE DRIL	LING OPNS.	
ERFORM RI EMPORARI	EMEDIAL WO	PRK				LING OPNS.	
ERFORM RI EMPORARI ULL OR AL 'THER:	EMEDIAL WO	N	CHANGE PLAN	s	COMMENCE DRIL CASING TEST ANI OTHER:	LING OPNS. D CEMENT JOB Convert to wate	PLUG AND ABANDONMENT er injection well x
ERFORM RI EMPORARI ULL OR AL VTHER:	EMEDIAL WC LY ABANDOL TER CASING	PRK	CHANGE PLAN	S	COMMENCE DRIL CASING TEST ANI OTHER:	LING OPNS. O CEMENT JOB Convert to wate of starting any propos	PLUG AND ABANDONMENT er injection well x
ERFORM RI EMPORARI ULL OR AL VTHER:	EMEDIAL WC LY ABANDOL TER CASING oposed or Comple E 1103. 07/10/96 1	VRK	CHANGE PLAN rly state all pertinent det WS #20. Work st	S	COMMENCE DRIL CASING TEST ANI OTHER:	LING OPNS. O CEMENT JOB Convert to wate of starting any propose rater down tbg. 1	PLUG AND ABANDONMENT PLUG AND ABANDONMENT ref injection well x
ERFORM RI EMPORARI ULL OR AL DTHER:	EMEDIAL WC LY ABANDOI TER CASING oposed or Comple E 1103. 07/10/96 1 	VRK	CHANGE PLAN rly state all pertinent det WS #20. Work st 8-7/8" rods, 2' x 7 rH w/4-3/4" bit &	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date	LING OPNS. D CEMENT JOB Convert to wate of starting any propose rater down tbg. I & NU BOP. SIV RU HLS. Ran cs	PLUG AND ABANDONMENT
ERFORM RI EMPORARI ULL OR AL THER:	EMEDIAL WC LY ABANDON TER CASING Oposed or Comple E 1103. 07/10/96 1 07/11/96 1 07/11/96 1	PRK	CHANGE PLAN rly state all pertinent det WS #20. Work st 8-7/8" rods, 2' x 7 HI w/4-3/4" bit & 450' w/10' cmt du	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date d 2 rods & put hot w mp. Released TAC of the to 4500'. POH. R D HLS. SIW & SDFT	LING OPNS. D CEMENT JOB Convert to wate of starting any propose rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N.	PLUG AND ABANDONMENT
ERFORM RI EMPORARI ULL OR AL VTHER:	EMEDIAL WC LY ABANDOL TER CASING oposed or Comple E 1103. 07/10/96 1 9 07/11/96 1 9 07/12/96 0	VRK	CHANGE PLAN rly state all pertinent det WS #20. Work si 8-7/8" rods, 2' x 7 HW w/4-3/4" bit & 450' w/10' cmt du to 3977'. Loaded on Perma-Latch p	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date d 2 rods & put hot w mp. Released TAC of the to 4500'. POH. R D HLS. SIW & SDFT	LING OPNS. D CEMENT JOB Convert to wate of starting any propose rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N. k string. GIH hy	PLUG AND ABANDONMENT
PERFORM RI TEMPORARI PULL OR AL DTHER:	EMEDIAL WC LY ABANDON TER CASING oposed or Comple E 1103. 07/10/96 1 07/11/96 1 07/12/96 0 1 07/15/96 1	VRK	CHANGE PLAN rly state all pertinent det WS #20. Work st 8-7/8" rods, 2' x 7 H w/4-3/4" bit & 450' w/10' cmt du to 3977'. Loaded on Perma-Latch p	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date of 2 rods & put hot w imp. Released TAC of her to 4500'. POH. R D HLS. SIW & SDFN 600#. LD 2-7/8" wor W.	LING OPNS. D CEMENT JOB Convert to wate of starting any propose rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N. k string. GIH hy	PLUG AND ABANDONMENT
PERFORM RI TEMPORARI PULL OR AL DTHER:	EMEDIAL WC LY ABANDON TER CASING oposed or Comple E 1103. 07/10/96 1 07/11/96 1 07/12/96 0 1 07/15/96 1	PRK	CHANGE PLAN rly state all pertinent det WS #20. Work st 8-7/8" rods, 2' x 7 H w/4-3/4" bit & 450' w/10' cmt du to 3977'. Loaded on Perma-Latch p	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date of 2 rods & put hot w imp. Released TAC of her to 4500'. POH. R D HLS. SIW & SDFN 600#. LD 2-7/8" wor W.	LING OPNS. D CEMENT JOB Convert to wate of starting any propose rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N. k string. GIH hy	PLUG AND ABANDONMENT
ERFORM RI EMPORARI ULL OR AL DTHER:	EMEDIAL WC LY ABANDON TER CASING oposed or Comple E 1103. 07/10/96 1 07/11/96 1 07/12/96 0 1 07/15/96 1	PRK	CHANGE PLAN rly state all pertinent det WS #20. Work st 8-7/8" rods, 2' x 7 H w/4-3/4" bit & 450' w/10' cmt du to 3977'. Loaded on Perma-Latch p	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date of 2 rods & put hot w imp. Released TAC of her to 4500'. POH. R D HLS. SIW & SDFN 600#. LD 2-7/8" wor W.	LING OPNS. D CEMENT JOB Convert to wate convert to wate rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N. k string. GIH hy	PLUG AND ABANDONMENT
PERFORM RI TEMPORARI PULL OR AL DTHER: 12. Descibe Pro SEE RULH	EMEDIAL WC LY ABANDON TER CASING oposed or Comple E 1103. 07/10/96 1 9 07/11/96 1 9 07/12/96 1 07/15/96 1 07/15/96 1	VRK	CHANGE PLAN rly state all pertinent det WS #20. Work st 8-7/8" rods, 2' x 7 H w/4-3/4" bit & 450' w/10' cmt du to 3977'. Loaded on Perma-Latch p	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date of 2 rods & put hot w imp. Released TAC of her to 4500'. POH. R D HLS. SIW & SDFN 600#. LD 2-7/8" wor W. 0 300#. RD & moved	LING OPNS. D CEMENT JOB Convert to wate convert to wate rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N. k string. GIH hy	PLUG AND ABANDONMENT
PERFORM RI TEMPORARI PULL OR AL DTHER: 12. Descibe Pro SEE RULH	EMEDIAL WC LY ABANDON TER CASING oposed or Comple E 1103. 07/10/96 1 9 07/11/96 1 9 07/12/96 1 07/15/96 1 07/15/96 1	VRK	CHANGE PLAN rly state all pertinent det WS #20. Work si 8-7/8" rods, 2' x 7 HH w/4-3/4" bit & 450' w/10' cmt du to 3977'. Loaded on Perma-Latch p WH. Circ pkr fly g into well.	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date of 2 rods & put hot w imp. Released TAC of her to 4500'. POH. R D HLS. SIW & SDFN 600#. LD 2-7/8" wor W. 0 300#. RD & moved	LING OPNS. D CEMENT JOB Convert to wate of starting any propose rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N. k string. GIH hy d off location.	PLUG AND ABANDONMENT
PERFORM RI TEMPORARI PULL OR AL DTHER: 12. Descibe Pro SEE RULH	EMEDIAL WC LY ABANDON TER CASING oposed or Comple E 1103. 07/10/96 1 9 07/11/96 1 9 07/12/96 0 1 07/15/96 1 07/15/96 1 07/15/96 1 07/15/96 1	VRK	CHANGE PLAN rly state all pertinent det WS #20. Work si 8-7/8" rods, 2' x 7 HH w/4-3/4" bit & 450' w/10' cmt du to 3977'. Loaded on Perma-Latch p WH. Circ pkr fly g into well.	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date of 2 rods & put hot w mp. Released TAC of the ro 4500'. POH. R D HLS. SIW & SDFN 500#. LD 2-7/8" wor W. 50 300#. RD & moved	LING OPNS. D CEMENT JOB Convert to wate of starting any propose rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N. k string. GIH hy d off location.	PLUG AND ABANDONMENT
PERFORM RI TEMPORARI PULL OR AL DTHER: 12. Descibe Pro SEE RULH	EMEDIAL WC LY ABANDON TER CASING oposed or Comple E 1103. 07/10/96 1 9 07/11/96 1 9 07/12/96 0 1 07/15/96 1 07/15/96 1 07/15/96 1 07/15/96 1	PRK	CHANGE PLAN rly state all pertinent det WS #20. Work si 8-7/8" rods, 2' x 7 HH w/4-3/4" bit & 450' w/10' cmt du to 3977'. Loaded on Perma-Latch p WH. Circ pkr fly g into well.	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date of 2 rods & put hot w mp. Released TAC of the ro 4500'. POH. R D HLS. SIW & SDFN 500#. LD 2-7/8" wor W. 50 300#. RD & moved	LING OPNS. D CEMENT JOB Convert to wate of starting any propose rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N. k string. GIH hy d off location.	PLUG AND ABANDONMENT er injection well x er injection well x er work) LD 30' x 1" pony rods, W & SDFN. sg Inspection log. ydrotesting 128 jts. 2-3/8" . DATE 9/12/96 (214)265-0080
TEMPORARI PULL OR AL OTHER: 12. Descibe Pro SEE RULH I hereby certify t SIGNATURE TYPE OR PRIN	EMEDIAL WC LY ABANDON TER CASING oposed or Comple E 1103. 07/10/96 1 07/11/96 1 07/12/96 0 1 07/15/96 1 07/15/96 1 07/15/96 1 07/15/96 1 07/15/96 1 07/15/96 1 Constant the information	PRK	CHANGE PLAN rly state all pertinent det WS #20. Work si 8-7/8" rods, 2' x 7 HH w/4-3/4" bit & 450' w/10' cmt du to 3977'. Loaded on Perma-Latch p WH. Circ pkr fly g into well.	s	COMMENCE DRIL CASING TEST ANI OTHER: ates, including estimated date d 2 rods & put hot w mp. Released TAC of our to 4500'. POH. R D HLS. SIW & SDFN 000#. LD 2-7/8" wor W. D 300#. RD & moved Production Admin	LING OPNS. D CEMENT JOB Convert to wate of starting any propose rater down tbg. I & NU BOP. SIV RU HLS. Ran cs N. k string. GIH hy d off location.	PLUG AND ABANDONMENT er injection well x ed work) LD 30' x 1" pony rods, W & SDFN. g Inspection log. ydrotesting 128 jts. 2-3/8" . DATE 9/12/96



