Form 3160-5 (June 1990)		5.1 KB	
	JNITED STATES DEPARTMENT OF THE INT		OIL COL. DIVICION OX 1980 Budget Bureau No. 1004-0135
	BUREAU OF LAND MANAGE	MENT P.U.L	S, NM 8824Lease Designation and Serial No.
		Hopps	5, IVIVI OOGHUbase Designation and Serial No. LC 029405A
	SUNDRY NOTICES AND REPORT	S ON WELLS	6. If Indian, Allottee or Tribe Name
	posals to drill or to deepen or reentry to IN FOR PERMIT for such proposals	a different reservoir.	
	SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well			i
	INJECTION Other		a vivame or lease & well
2. Name of Operator			Elvis Well #2
CONOCO, INC.           3. Address and Telephone No.           10 Desta Dr., Suite 100W, Midland, Texas 79705-4500,915 686-5424           915 684-6381           4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			api well #
			30 025 33854 10. Field and Pool, or Exploratory Area
			Maljamar, Devonian, W 90662
Surface: 770' FSL & 2306' FI TD: "	EL, SEC 17, TITS, R 32E		Maljamar (Sisco) 49270 11. County or Pansh, State
			Lea, NM
2 CHECK APPROPRI	ATE BOX(s) TO INDICATE NATU	JRE OF NOTICE, RE	PORT, OR OTHER DATA
TYPE OF SUBMIS	SION		ACTION
Notice of Intent		Abandonment	Change of Plans
		X Recompletion	New Construction
X Subsequent Repo	ort i	Plugging Back	Non-Routine Fracturing
j Finat Abandonme	mt Notice	Casing Repair Attering Casing	Water Shut-Off
			Conversion to Injection Dispose Water
			(Note: Report results of multiple completion on Well
3. Describe Proposed or Completed C	Operations (Clearly state all pertinent details, and give	a participant datas including acti-	Completion or Recompletion Report and Log form.)
6-15-98: MIRU, unset	rrace locations and measured and true vertical depth	s for all markers and zones pertir	nent to this work.)*
6-I5-98: MIRU, unset 6-I6-98: Rigged up w rig down wire 6-I7-98: Cont POOH to I3,770', SI 6-I8-98: Hot oiled, sp 6-I9-98: Con't POOH 6-20-98: Set pkr @ I3 6-22-98: Ran fluid levels 6-23-98: Fluid levels 6-24/25-98: Fluid levels	race locations and measured and true vertical depth is pkr, POOH w/pkr, SION. irreline, RIH w/RBP set down @ 2nd eline, ran in hole w/casing scraper, w/scraper, rig up wireline, RIH w/R ON. botted w/acid @ I3,700-I3,770', pulle perf @I3,763'-I3,773' (40 holes), r 3,600', rig up swab & RIH tag fluid. vels and swabbed. SION. and swabbed. SION. els and swabbed. SION. bwn, tagged fluid, rigged down swal	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION.	nent to this work.)* nable to get through, POOH w/RBP, to I3,935', puil out, SION. down wireline, go in hole w/tbg. nlew well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION.
6-I5-98: MIRU, unset 6-I6-98: Rigged up w rig down wire 6-I7-98: Cont POOH to I3,770', SH 6-I8-98: Hot oiled, sp 6-I9-98: Con't POOH 6-20-98: Set pkr @ I3 6-22-98: Ran fluid lev 6-23-98: Fluid levels 6-24/25-98: Fluid levels 6-26-98: Bled well do	race locations and measured and true vertical depth is pkr, POOH w/pkr, SION. irreline, RIH w/RBP set down @ 2nd eline, ran in hole w/casing scraper, w/scraper, rig up wireline, RIH w/R ON. botted w/acid @ I3,700-I3,770', pulle perf @I3,763'-I3,773' (40 holes), r 3,600', rig up swab & RIH tag fluid. vels and swabbed. SION. and swabbed. SION. els and swabbed. SION. bwn, tagged fluid, rigged down swal	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION.	nent to this work.)* able to get through, POOH w/RBP, to I3,935', pull out, SION. down wireline, go in hole w/tbg. new well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION.
6-I5-98: MIRU, unset 6-I6-98: Rigged up w rig down wire 6-I7-98: Cont POOH to I3,770', SH 6-I8-98: Hot oiled, sp 6-I9-98: Con't POOH 6-20-98: Set pkr @ I3 6-22-98: Ran fluid lev 6-23-98: Fluid levels 6-24/25-98: Fluid levels 6-26-98: Bled well do	race locations and measured and true vertical depth is pkr, POOH w/pkr, SION. irreline, RIH w/RBP set down @ 2nd eline, ran in hole w/casing scraper, w/scraper, rig up wireline, RIH w/R ON. botted w/acid @ I3,700-I3,770', pulle perf @I3,763'-I3,773' (40 holes), r 3,600', rig up swab & RIH tag fluid. vels and swabbed. SION. and swabbed. SION. els and swabbed. SION. bwn, tagged fluid, rigged down swal	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION.	nent to this work.)* nable to get through, POOH w/RBP, to I3,935', puil out, SION. down wireline, go in hole w/tbg. nlew well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION.
6-I5-98: MIRU, unset 6-I6-98: Rigged up w rig down wire 6-I7-98: Cont POOH to I3,770', SH 6-I8-98: Hot oiled, sp 6-I9-98: Con't POOH 6-20-98: Set pkr @ I3 6-22-98: Ran fluid level 6-23-98: Fluid levels 6-24/25-98: Fluid levels 6-26-98: Bled well do Prep to test v	race locations and measured and true vertical depth is pkr, POOH w/pkr, SION. irreline, RIH w/RBP set down @ 2nd eline, ran in hole w/casing scraper, w/scraper, rig up wireline, RIH w/R ON. botted w/acid @ I3,700-I3,770', pulle perf @I3,763'-I3,773' (40 holes), r 3,600', rig up swab & RIH tag fluid. vels and swabbed. SION. and swabbed. SION. els and swabbed. SION. bwn, tagged fluid, rigged down swal	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION.	nent to this work.)* able to get through, POOH w/RBP, to I3,935', pull out, SION. down wireline, go in hole w/tbg. new well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION.
6-I5-98: MIRU, unset 6-I6-98: Rigged up w rig down wire 6-I7-98: Cont POOH to I3,770', SH 6-I8-98: Hot oiled, sp 6-I9-98: Con't POOH 6-20-98: Set pkr @ I3 6-22-98: Ran fluid level 6-23-98: Fluid levels 6-24/25-98: Fluid levels 6-26-98: Bled well do Prep to test v	rive and swabbed. SION. and swabbed. SION. a	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION.	nent to this work.)* nable to get through, POOH w/RBP, to I3,935', puil out, SION. down wireline, go in hole w/tbg. nlew well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION.
6-I5-98: MIRU, unset 6-I6-98: Rigged up w rig down wire 6-I7-98: Cont POOH to I3,770', SI 6-I8-98: Hot oiled, sp 6-I9-98: Con't POOH 6-20-98: Set pkr @ I3 6-22-98: Ran fluid lev 6-23-98: Fluid levels 6-24/25-98: Fluid levels 6-26-98: Bled well do Prep to test w	race locations and measured and true vertical depth is pkr, POOH w/pkr, SION. irreline, RIH w/RBP set down @ 2nd eline, ran in hole w/casing scraper, w/scraper, rig up wireline, RIH w/R ON. botted w/acid @ 13,700-13,770', pulled perf @13,763'-13,773' (40 holes), r 3,600', rig up swab & RIH tag fluid. vels and swabbed. SION. and swabbed. SION. els and swabbed. SION. els and swabbed. SION. wwn, tagged fluid, rigged down swal well. Ann E. Ritchie Title REGULATOR	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION.	nent to this work.)* nable to get through, POOH w/RBP, to I3,935', puil out, SION. down wireline, go in hole w/tbg. nlew well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION.
6-I5-98: MIRU, unset 6-I6-98: Rigged up w rig down wire 6-I7-98: Cont POOH to I3,770', SI 6-I8-98: Hot oiled, sp 6-I9-98: Con't POOH 6-20-98: Set pkr @ I3 6-22-98: Ran fluid lev 6-23-98: Fluid levels 6-24/25-98: Fluid levels 6-26-98: Bled well do Prep to test w	race locations and measured and true vertical depth is pkr, POOH w/pkr, SION. irreline, RIH w/RBP set down @ 2nd eline, ran in hole w/casing scraper, w/scraper, rig up wireline, RIH w/R ON. botted w/acid @ 13,700-13,770', pulled by perf @13,763'-13,773' (40 holes), r 3,600', rig up swab & RIH tag fluid. vels and swabbed. SION. and swabbed. SION. els and swabbed. SION. wwn, tagged fluid, rigged down swal well. Ann E. Ritchie Title REGULATOR Ce use)	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION.	nent to this work.)* nable to get through, POOH w/RBP, to I3,935', pull out, SION. down wireline, go in hole w/tbg. new well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION. talled wellhead, tbg @ I3,600'.
6-I5-98: MIRU, unset 6-I6-98: Rigged up w rig down wire 6-I7-98: Cont POOH to I3,770', SI 6-I8-98: Hot oiled, sp 6-I9-98: Con't POOH 6-20-98: Set pkr @ I3 6-22-98: Ran fluid lev 6-23-98: Fluid levels 6-24/25-98: Fluid levels 6-26-98: Bled well do Prep to test w	race locations and measured and true vertical depth is pkr, POOH w/pkr, SION. irreline, RIH w/RBP set down @ 2nd eline, ran in hole w/casing scraper, w/scraper, rig up wireline, RIH w/R ON. botted w/acid @ 13,700-13,770', pulled perf @13,763'-13,773' (40 holes), r 3,600', rig up swab & RIH tag fluid. vels and swabbed. SION. and swabbed. SION. els and swabbed. SION. els and swabbed. SION. wwn, tagged fluid, rigged down swal well. Ann E. Ritchie Title REGULATOR	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION.	nent to this work.)* nable to get through, POOH w/RBP, to I3,935', pull out, SION. down wireline, go in hole w/tbg. nlew well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION. talled wellhead, tbg @ I3,600'.
<ul> <li>6-I5-98: MIRU, unset</li> <li>6-I5-98: Rigged up w rig down wire</li> <li>6-I7-98: Cont POOH to I3,770', SH</li> <li>6-I8-98: Hot oiled, sp</li> <li>6-I9-98: Con't POOH</li> <li>6-20-98: Set pkr @ I3</li> <li>6-22-98: Ran fluid levels</li> <li>6-23-98: Fluid levels</li> <li>6-24/25-98: Fluid levels</li> <li>6-26-98: Bled well do Prep to test v</li> </ul>	Trace locations and measured and true vertical depth is pkr, POOH w/pkr, SION. irreline, RIH w/RBP set down @ 2nd eline, ran in hole w/casing scraper, w/scraper, rig up wireline, RIH w/R ON. botted w/acid @ 13,700-13,770', pulled is perf @13,763'-13,773' (40 holes), r 3,600', rig up swab & RIH tag fluid. vels and swabbed. SION. and swabbed. SION. els and swabbed. SION. wwn, tagged fluid, rigged down swal well. Ann E. Ritchie REGULATOR true True True True True	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION. b, spaced out well, inst b, spaced out well, inst	hent to this work.)* Pable to get through, POOH w/RBP, to I3,935', pull out, SION. down wireline, go in hole w/tbg. Poet well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION. talled wellhead, tbg @ I3,600'.  Date 12-14-98 Date
<ul> <li>6-I5-98: MIRU, unset</li> <li>6-I5-98: Rigged up w rig down wire</li> <li>6-I7-98: Cont POOH to I3,770', SH</li> <li>6-I8-98: Hot oiled, sp</li> <li>6-I9-98: Con't POOH</li> <li>6-20-98: Set pkr @ I3</li> <li>6-22-98: Ran fluid levels</li> <li>6-23-98: Fluid levels</li> <li>6-24/25-98: Fluid levels</li> <li>6-26-98: Bled well do Prep to test v</li> </ul>	Ann E. Ritchie Title Ann E. Ritchie Ann E. Ritchie Ann E. Ritchie Ann E. Ritchie Title Title Title Title	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig d ed up hole to I2,000, b ig down wireline, RIH SION. b, spaced out well, inst b, spaced out well, inst	hent to this work.)* Pable to get through, POOH w/RBP, to I3,935', pull out, SION. down wireline, go in hole w/tbg. Poet well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION. talled wellhead, tbg @ I3,600'.  Date 12-14-98 Date
<ul> <li>6-I5-98: MIRU, unset</li> <li>6-I5-98: Rigged up w rig down wire</li> <li>6-I7-98: Cont POOH to I3,770', SH</li> <li>6-I8-98: Hot oiled, sp</li> <li>6-I9-98: Con't POOH</li> <li>6-20-98: Set pkr @ K</li> <li>6-22-98: Ran fluid levels</li> <li>6-23-98: Fluid levels</li> <li>6-24/25-98: Fluid levels</li> <li>6-26-98: Bled well do Prep to test v</li> </ul>	Ann E. Ritchie Title Ann E. Ritchie Ann E. Ritchie Ann E. Ritchie Ann E. Ritchie Title Title Title Title	s for all markers and zones pertir d DV tool @ II,825, un worked through, RIH t BP set @ I3,782', rig ( ed up hole to I2,000, b ig down wireline, RIH SION. b, spaced out well, inst b, spaced out well, inst ty AGENT	hent to this work.)* Pable to get through, POOH w/RBP, to I3,935', pull out, SION. down wireline, go in hole w/tbg. Poet well dry, POOH w/tbg. SION. w/pkr, I55 jts. SION. talled wellhead, tbg @ I3,600'.  Date 12-14-98 Date