	*			- Y			
Submit 3 Copies To Appropriate District	State of	New Mexico				For	m C-1
Office	Energy, Minerals		sources			Revised Mar	
District I 1625 N. French Dr., Hobbs, NM 87240				WELL AP			
District II	OIL CONSER	VATION DIV	/ISION	1	30-025-3428		
811 South First, Artesia, NM 87210 District III		outh Pacheco		5. Indicate	Type of Lea	se	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa F	Fe, NM 87505		STA	TEX	FEE 🗌	
District IV 2040 South Pacheco, Santa Fe, NM 87505				6. State Oi 22371	l & Gas Leas	se No.	
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.) 1. Type of Well: Oil Well X Gas Well	CES AND REPORTS OSALS TO DRILL OR TO CATION FOR PERMIT" (F Other	DEEPEN OR PLU	IG BACK TO A SUCH	7. Lease N Monteith	ame or Unit	Agreement	Name:
2. Name of Operator	Oulci			8. Well No	<u>,</u>		
Bass Enterprises Production	<u>Co</u>).		
3. Address of Operator	<u> </u>			9 Pool nat	me or Wildca		
P.O. Box 2760 Midland, TX	79702-2760			1	(Wolfcamp)		
4. Well Location	<u></u>		··· ·	1 LOV INGCON	(HOTT Comp)		
Unit LetterB:	660' feet from th	e North	line and	1830'	feet from the	East	li:
Section 13	Township	16S Range		NMPM	Co	ounty	Lea
	10. Elevation (Show	v whether DR, R	KB, RT, GR, el	tc.)			
	GL - 3857.	9', RF 3874.2	', KB - 3476	.2'			
	PLUG AND ABANDO	ON IN REM	EDIAL WORK			TERING C	ASING
	CHANGE PLANS		MENCE DRILL	ING OPNS.		UG AND	
	CHANGE PLANS MULTIPLE COMPLETION						ENT
PULL OR ALTER CASING	MULTIPLE		MENCE DRILL NG TEST AND ENT JOB			UG AND	ENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		MENCE DRILL NG TEST AND ENT JOB ER:			UG AND BANDONME	
DTHER: 12. Describe Proposed or Complete	MULTIPLE COMPLETION ed Operations (Clearly	COM CASI CEMI	MENCE DRILL NG TEST AND ENT JOB ER: t details, and g	ive pertinent	D PL AE	UG AND BANDONME	ed date
PULL OR ALTER CASING	MULTIPLE COMPLETION ed Operations (Clearly	COM CASI CEMI	MENCE DRILL NG TEST AND ENT JOB ER: t details, and g	ive pertinent wellbore dia	dates, includ	IUG AND BANDONME ing estimate oosed comp	ed date letion
PULL OR ALTER CASING	MULTIPLE COMPLETION ed Operations (Clearly	COM CASI CEMI	MENCE DRILL NG TEST AND ENT JOB ER: t details, and g	ive pertinent wellbore dia THE COM HOURS F	dates, includ agram of prop MISSION M PRIOR TO T	UG AND BANDONME ing estimate posed comp UST BE NC HE BEGIN	ed date letion DTIFIED
PULL OR ALTER CASING	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For	COM CASI CEMI OTHE state all pertiner r Multiple Comp	MENCE DRILL NG TEST AND ENT JOB ER: nt details, and g letions: Attach	ive pertinent wellbore dia THE COM HOURS F PLUGGIN	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO	UG AND BANDONME ing estimate posed comp UST BE NC HE BEGIN	ed date letion DTIFIED
PULL OR ALTER CASING	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW	COM CASI CEMI OTHI state all pertiner r Multiple Comp	MENCE DRILL NG TEST AND ENT JOB ER: nt details, and g letions: Attack	ive pertinent wellbore dia THE COM HOURS F	dates, includ agram of prop MISSICN M PRIOR TO T G OPERATIO PROVED.	IUG AND BANDONME ing estimate oosed comp UST BE NO HE BEGIN ONS FOR	ed date letion DTIFIED
 PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. 	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s	COM CASI CEMI OTHE state all pertiner r Multiple Comp displacing wass same cement	MENCE DRILL NG TEST AND ENT JOB ER: nt details, and g letions: Attack / brine mud. :. Tag TOC	ive pertinent wellbore dia THE COM HOURS F FLUGGIN TO BE AP	dates, includ agram of prop MISSICN M PRIOR TO T G OPERATIO PROVED.	IUG AND BANDONME ing estimate oosed comp UST BE NO HE BEGIN ONS FOR	ed date letion DTIFIED
 PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. 	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s	COM CASI CEMI CEMI OTHE state all pertinen r Multiple Comp displacing was sx same cement sx Class C nea	MENCE DRILL NG TEST AND ENT JOB ER: It details, and g letions: Attack brine mud. Tag TOC at cement. Ta	ive pertinent wellbore dia THE COM HOURS F FLUGGIN TO BE AP	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED.	ING AND BANDONME ing estimate osed comp UST BE NC HE BEGIN ONS FOR	ed date letion DTIFIED
 PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl 	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co.	COM CASI CEMI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu	MENCE DRILL NG TEST AND ENT JOB ER: at details, and g letions: Attack brine mud. Tag TOC at cement. Ta utter to 3000	ive pertinent wellbore dia THE COM HOURS F PLUGGIN TO BE AP ag TOC	dates, includ agram of prop MISSICN M PROVED. PROVED.	ing estimate osed comp UST BE NO HE BEGIN ONS FOR	ed date letion DTIFIEC INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg	COM CASI CEMI CEMI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below	MENCE DRILL NG TEST AND ENT JOB ER: nt details, and g letions: Attack / brine mud. :. Tag TOC at cement. Ta utter to 3000 / csg stub. N	ive pertinent wellbore dia THE COM HOURS F PLUGGIN TO BE AP ag TOC '. (TOC P fix & spote	dates, includ agram of prop MISSICN M PRIOR TO T G OPERATIO PROVED.	ing estimate osed comp UST BE NC HE BEGIN ONS FOR	ed date letion DTIFIEE INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH	COM CASI CEMI CEMI oTHE state all pertiner r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below I to 2200'. Re	MENCE DRILL NG TEST AND ENT JOB ER: nt details, and g letions: Attack / brine mud. :. Tag TOC at cement. Ta utter to 3000 / csg stub. N	ive pertinent wellbore dia THE COM HOURS F FLUGGIN TO BE AP ag TOC O'. (TOC P fix & spot og. WOC. RT	dates, includ agram of prop MISSICN M PRIOR TO T G OPERATIO PROVED. 50 sx Class H tag TBC	UG AND BANDONME ing estimate oosed comp UST BE NO HE BEGIN ONS FOR 13 14 15 15 ONS FOR	ed date letion DTIFIEC INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10.520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm LD tbg to 2262'. Spot 50	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag	COM CASI CEMI CEMI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below I to 2200'. Re g TOC	MENCE DRILL NG TEST AND ENT JOB ER: nt details, and g letions: Attack / brine mud. :. Tag TOC at cement. Ta utter to 3000 / csg stub. N	ive pertinent wellbore dia THE COM HOURS F PLUGGIN TO BE AP ag TOC '. (TOC P fix & spote	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED. 2011121 50 sx Class H tag Tech	UG AND BANDONME ing estimate osed comp UST BE NC HE BEGIN ONS FOR IST 4 15 ONS FOR IST 4 15 ONS FOR	ed date letion DTIFIEC INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm LD tbg to 2262'. Spot 50 LD tbg to 450'. Spot 50 s	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag x Class C cmt. Tag	COM CASI CEMI CEMI CEMI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below t to 2200'. Re g TOC TOC	MENCE DRILL NG TEST AND ENT JOB ER: Int details, and g letions: Attack (brine mud. C. Tag TOC at cement. Ta utter to 3000 (csg stub. N everse out th	ive pertinent wellbore dia THE COM HOURS F FLUGGIN TO BE AP ag TOC O'. (TOC P tix & spot og. WOC. RT	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED. 9280 BTS)/ 50 sx Class H tag Tecu hc	UG AND BANDONME ing estimate osed comp UST BE NC HE BEGIN ONS FOR INS FOR INS FOR INS FOR INS C neat	ed date letion DTIFIEC INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10.520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm LD tbg to 2262'. Spot 50	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag x Class C cmt. Tag	COM CASI CEMI CEMI CEMI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below t to 2200'. Re g TOC TOC	MENCE DRILL NG TEST AND ENT JOB ER: Int details, and g letions: Attack (brine mud. C. Tag TOC at cement. Ta utter to 3000 (csg stub. N everse out th	ive pertinent wellbore dia THE COM HOURS F FLUGGIN TO BE AP ag TOC O'. (TOC P tix & spot og. WOC. RT	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED. 9280 BTS)/ 50 sx Class H tag Tecu hc	UG AND BANDONME ing estimate osed comp UST BE NC HE BEGIN ONS FOR INS FOR INS FOR INS FOR INS C neat	ed date letion DTIFIEC INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm LD tbg to 2262'. Spot 50 LD tbg to 450'. Spot 50 s	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag x Class C cmt. Tag	COM CASI CEMI CEMI CEMI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below t to 2200'. Re g TOC TOC	MENCE DRILL NG TEST AND ENT JOB ER: Int details, and g letions: Attack (brine mud. C. Tag TOC at cement. Ta utter to 3000 (csg stub. N everse out th	ive pertinent wellbore dia THE COM HOURS F FLUGGIN TO BE AP ag TOC O'. (TOC P tix & spot og. WOC. RT	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED. 9280 BTS)/ 50 sx Class H tag Tecu hc	UG AND BANDONME ing estimate osed comp UST BE NC HE BEGIN ONS FOR INS FOR INS FOR INS FOR INS C neat	ed date letion DTIFIEC INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm LD tbg to 2262'. Spot 50 LD tbg to 450'. Spot 50 s	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag x Class C cmt. Tag	COM CASI CEMI CEMI CEMI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below t to 2200'. Re g TOC TOC	MENCE DRILL NG TEST AND ENT JOB ER: Int details, and g letions: Attack (brine mud. C. Tag TOC at cement. Ta utter to 3000 (csg stub. N everse out th	ive pertinent wellbore dia THE COM HOURS F FLUGGIN TO BE AP ag TOC O'. (TOC P tix & spot og. WOC. RT	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED. 9280 BTS)/ 50 sx Class H tag Tecu hc	UG AND BANDONME ing estimate osed comp UST BE NC HE BEGIN ONS FOR INS FOR INS FOR INS FOR INS C neat	ed date letion DTIFIEE INING THE C-
 PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm LD tbg to 2262'. Spot 50 LD tbg to 450'. Spot 50 s RU welder, cut wellhead. 	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag X Class C cmt. Tag Place 10 sx Class	COM CASI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below H to 2200'. Re g TOC TOC C surface plu	MENCE DRILL NG TEST AND ENT JOB ER: at details, and g letions: Attach / brine mud. . Tag TOC at cement. Ta utter to 3000 / csg stub. N everse out th ug. Weld pla	ive pertinent wellbore dia THE COM HOURS F PLUGGIN TO BE AP ag TOC '. (TOC P tix & spot og. WOC. (TT constant) ate and ins	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED. 9280 BTS)/ 50 sx Class H tag Tecu hc	UG AND BANDONME ing estimate osed comp UST BE NC HE BEGIN ONS FOR INS FOR INS FOR INS FOR INS C neat	ed date letion DTIFIEE INING THE C-
PULL OR ALTER CASING	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag X Class C cmt. Tag Place 10 sx Class	COM CASI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below H to 2200'. Re g TOC TOC C surface plu	MENCE DRILL NG TEST AND ENT JOB ER: at details, and g letions: Attach / brine mud. . Tag TOC at cement. Ta utter to 3000 / csg stub. N everse out th ug. Weld pla	ive pertinent wellbore dia THE COM HOURS F PLUGGIN TO BE AP ag TOC '. (TOC P tix & spot og. WOC. (TT constant) ate and ins	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED. 9280 BTS)/ 50 sx Class H tag Tecu hc Hob	UG AND BANDONME ing estimate osed comp UST BE NC HE BEGIN ONS FOR INS FOR INS FOR INS FOR INS C neat	ed date letion DTIFIEE INING THE C-
PULL OR ALTER CASING	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag x Class C cmt. Tag Place 10 sx Class	COM CASI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg cu g to 50' below H to 2200'. Re g TOC TOC C surface plu	MENCE DRILL NG TEST AND ENT JOB ER: at details, and g letions: Attach (brine mud. . Tag TOC at cement. Ta at cement. Ta at ter to 3000 (csg stub. N everse out th ag. Weld pla	ive pertinent wellbore dia THE COM HOURS F PLUGGIN TO BE AP ag TOC '. (TOC P dix & spot og. WOC. (TT other and ins f.	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED. 9280 BTS)/ 50 sx Class H tag Tecu hc Hob	UG AND BANDONME ing estimate posed comp UST BE NC HE BEGIN ONS FOR IS 747575 Cut S C neat Cut S C neat D Ds Dmarker	ed date letion DTIFIEL INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10.520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm LD tbg to 2262'. Spot 50 LD tbg to 450'. Spot 50 s RU welder, cut wellhead. hereby certify that the information above GNATURE Qumi UUU	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag x Class C cmt. Tag Place 10 sx Class	COM CASI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg ct g to 50' below H to 2200'. Re g TOC TOC C surface plu	MENCE DRILL NG TEST AND ENT JOB ER: at details, and g letions: Attach (brine mud. . Tag TOC at cement. Ta at cement. Ta at ter to 3000 (csg stub. N everse out th ag. Weld pla	ive pertinent wellbore dia THE COM HOURS F FLUGGIN TO BE AP ag TOC 0'. (TOC p fix & spot of og. WOC. RT of ate and ins	dates, includ agram of prop MISSION M RIOR TO T G OPERATIO PROVED. 50 sx Class H tag Tecu hob tall P & OA	UG AND BANDONME ing estimate posed comp UST BE NC HE BEGIN ONS FOR IS 74 15 75 Cut s C neat bs Dmarker.	ed date letion DTIFIEE INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10.520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm LD tbg to 2262'. Spot 50 LD tbg to 450'. Spot 50 s RU welder, cut wellhead.	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag x Class C cmt. Tag Place 10 sx Class	COM CASI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg ct g to 50' below H to 2200'. Re g TOC TOC C surface plu	MENCE DRILL NG TEST AND ENT JOB ER: at details, and g letions: Attach / brine mud. . Tag TOC at cement. Tag tcer to 3000 / csg stub. N everse out th ug. Weld pla wledge and belie duction Cler	ive pertinent wellbore dia THE COM HOURS F PLUGGIN TO BE AP ag TOC '. (TOC P ix & spote og. WOC. (TT ate and ins f. k	dates, includ agram of prop MISSION M PRIOR TO T G OPERATIO PROVED. 3280'BTS)/ 50 sx Class H tag TUCU Hob tall P & OAT	UG AND BANDONME ing estimate posed comp UST BE NC HE BEGIN ONS FOR IS 74 15 75 Cut s C neat bs Dmarker.	ed date letion DTIFIED INING THE C-
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. Set CIBP @ 10,520' Spot 25 sx Class H cement PUH to 8400'. LD tubing. PUH to 4976'. LD tubing. Weld on 5-1/2" pull nippl csg. RD Wireline Co. POH w/5 BFW ahead & behind cm LD tbg to 2262'. Spot 50 LD tbg to 450'. Spot 50 s RU welder, cut wellhead. hereby certify that the information above transmitted to the start of the star	MULTIPLE COMPLETION ed Operations (Clearly SEE RULE 1103. For followed by 5 BFW Mix and spot 40 s Mix and spot 40 s e. RU Wireline Co. & LD csg. RIH w/tbg t. TOC @ 2805'. PUH sx Class C cmt. Tag x Class C cmt. Tag Place 10 sx Class	COM CASI CEMI OTHE state all pertinen r Multiple Comp displacing w/ sx same cement sx Class C nea . RIH w/csg ct g to 50' below H to 2200'. Re g TOC TOC C surface plu	MENCE DRILL NG TEST AND ENT JOB ER: at details, and g letions: Attach (brine mud. . Tag TOC at cement. Ta at cement. Ta at ter to 3000 (csg stub. N everse out th ag. Weld pla	ive pertinent wellbore dia THE COM HOURS F PLUGGIN TO BE AP ag TOC '. (TOC P ix & spote og. WOC. (TT ate and ins f. k	dates, includ agram of prop MISSION M PRIOR TO T G OPERATIO PROVED. 3280'BTS)/ 50 sx Class H tag TUCU Hob tall P & OAT	UG AND BANDONME ing estimate posed comp UST BE NC HE BEGIN ONS FOR IS 74 15 75 Cut s C neat bs Dmarker.	ed date letion DTIFIED INING THE C-