Submit 3 Copies State of New Mexi to Appropriate Energy, Minerals and Natural Reso Dignet Office	
DISTRICT I P.O. Box 1980, Hobba, NM 88240 P.O. Box 2088	30-025-34443
DISTRICT II Santa Fe, New Mexico 8' P.O. Drawer DD, Artesia, NM \$8210	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lesse No.
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM (FORM C-101) FOR SUCH PROPOSALS.)	R PLUG BACK TO A 7 Leade Name or Unit Agreement Name
1. Type of Well: OL GAS WELL VEL X OTHER	Durme 1 a ACD
well Well X OTHER 2. Name of Operator	Runnels ASP
YATES PETROLEUM CORPORATION	2
1. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool same or Wildcat Shoe Bar Strawn, North
4. Well Location	
Unit Letter : Feet From The South	Line and Feet From The Line
Section 11 Township 16S Range 10. Elevailon (Show whether DF 3997 '	, RKB, RT, GR, etc.)
	ture of Notice Report or Other Data
11. Check Appropriate Box to Indicate Na	
11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	SUBSEQUENT REPORT OF:
11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON I TEMPORARILY ABANDON	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING OTHER: OTHER: Perforate Strawn & dual produce	SUBSEQUENT REPORT OF:
11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON Change Plans PULL OR ALTER CASING	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB D DTHER:
 11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING OTHER: Perforate Strawn & dual produce Atoka & Strawn 12 Describe Proposed or Completed Operations (Clearly state all perimens details, and perimens details, and perimens at follows; 1. Slickline set blanking plug in 1.81" profix water to disengage on/off tool. TOOH with tul 2. Wireline set RBP at 11850'. Dump 30# 20-4 and casing to 1500 psi. Leave casing loaded. 3. Perforate 11508-11524' (Strawn). 4. TIH with packer, 1.875" profile, on/off as 11480'. Pressure test annulus with 2% KCL wat 5. Load tubing with 2% KCL. TOH with packer 	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING C OTHER: Perforate Strawn & dual produce Atoka & Strawn C 12. Describe Proposed or Completed Operations (Clearly state all periment details, and periment as follows: 1. Slickline set blanking plug in 1.81" profilework) SEB RULE 1103. Propose to perforate Strawn as follows, product Strawn as follows: 1. Slickline set blanking plug in 1.81" profilework details, and periment details. 2. Wireline set RBP at 11850'. Dump 30# 20-4 and casing to 1500 psi. Leave casing loaded. 3. Perforate 11508-11524' (Strawn). 4. TIH with packer, 1.875" profile, on/off as 11480'. 5. Load tubing with 2% KCL. 6. Perforate 11384-11464' (Strawn).	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB DTHER: Image: Comparison of the comp
11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS OTHER: Perforate Strawn & dual produce Atoka & Strawn X 12. Describe Proposed or Completed Operations (Clearly state all perimensi details, and perimensi SEB RULE 1103. Propose to perforate Strawn as follows, product Strawn as follows: 1. Slickline set blanking plug in 1.81" profixition of the set read of the set of the set read of the set of the s	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB DTHER: Image: Comparison of the comp
11. Check Appropriate Box to Indicate Nanovigation NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS OTHER: Perforate Strawn PULL OR ALTER CASING C OTHER: Perforate Strawn Atoka & Strawn C 12. Describe Proposed or Completed Operations (Clearly state all periment datails, and perforate Strawn as follows, product Strawn as follows: 1. Slickline set blanking plug in 1.81" prof: water to disengage on/off tool. TOOH with tul 2. Wireline set RBP at 11850'. Dump 30# 20-4 and casing to 1500 psi. Leave casing loaded. 3. Perforate 11508-11524' (Strawn). 4. TIH with packer, 1.875" profile, on/off as 11480'. Pressure test annulus with 2% KCL wates 5. Load tubing with 2% KCL. TOH with packer RBP at 11490'. TOOH with tubing. Load casing 6. Perforate 11384-11464' (Strawn). 7. TIH with packer, 1.875" profile nipple, or 1. TH with packer, 1.875" profile nipple, or	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB DTHER: Image: Comparison of the comp
11. Check Appropriate Box to Indicate Nanoveloge and the indocember of the bast of my browledge and bell 11. NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS OTHER: Perforate Strawn & dual produce Atoka & Strawn X 12. Describe Proposed or Completed Operations (Clearly state all perimensi details, and provide Strawn as follows; 12. Describe Proposed or Completed Operations (Clearly state all perimensi details, and provide Strawn as follows; 13. Propose to perforate Strawn as follows, product Strawn as follows; 14. 15. Slickline set blanking plug in 1.81" profile water to disengage on/off tool. TOOH with tul 2. Wireline set RBP at 11850'. Dump 30# 20-4 and casing to 1500 psi. Leave casing loaded. 3. Perforate 11508-11524' (Strawn). 4. TIH with packer, 1.875" profile, on/off as 11480'. Pressure test annulus with 2% KCL wat 5. Load tubing with 2% KCL. TOH with packer RBP at 11490'. TOOH with tubing. Load casing 6. Perforate 11384-11464' (Strawn). 7. TIH with packer, 1.875" profile nipple, or 1. The information above in two and complete to the bast of my browledge and bell	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB Image: Comparison of the co
11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING C OTHER: Perforate Strawn & dual produce 12. Describe Proposed or Completed Operations (Clearly state all perimens details, and g work) SEB RULE 1103. Propose to perforate Strawn as follows, product Strawn as follows: 1. Slickline set blanking plug in 1.81" prof. water to disengage on/off tool. TOOH with tul 2. Wireline set RBP at 11850'. 3. Perforate 11508-11524' (Strawn). 4. TH with packer, 1.875" profile, on/off as 11480'. 9. Load tubing with 2% KCL. 9. Load tubing with 2% KCL. 9. TH with packer, 1.875" profile nipple, or 7. TIH with packer, 1.875" profile nipple, or 7. TH with packer, 1.875" profile	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB Image: Comparison of the co
11. Check Appropriate Box to Indicate Na NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING C OTHER: Perforate Strawn & dual produce Atoka & Strawn C 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and perforate Strawn as follows, produce Strawn as follows: 1. Slickline set blanking plug in 1.81" prof: water to disengage on/off tool. TOOH with tul 2. Wireline set RBP at 11850'. Dump 30# 20-4 and casing to 1500 psi. Leave casing loaded. 3. Perforate 11508-11524' (Strawn). 4. TIH with packer, 1.875" profile, on/off as 11480'. Pressure test annulus with 2% KCL wal 5. Load tubing with 2% KCL. TOH with packer RBP at 11490'. TOOH with tubing. Load casing 6. Perforate 11384-11464' (Strawn). 7. TIH with packer, 1.875" profile nipple, or THE of maters 1.884 multiple of my browledge ad ball stonaruse Maters 1.1884 multiple of my browledge ad ball stonaruse	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CHER: Image: Comment datas, including estimated data of starting eny proposed Chine partiment datas, including estimated data of starting eny proposed Chine test and then dual produce Atoka and Altern datas, including estimated data of starting eny proposed Chine test and then dual produce Atoka and Altern datas, including estimated data of starting eny proposed Chine test and then dual produce Atoka and Altern datas, including estimated data of starting eny proposed Chine test and then dual produce Atoka and Altern datas, including estimated data of starting eny proposed Chine test and then dual produce Atoka and Altern data of the starting in the starting environment of RBP. Pressure test RBP Sesembly and 2–7/8" tubing. Set packer at contributed on NEXT PAGE: Operations Technician DATE March 26, 1999 TELEPHONE NO. 505/748–147

.

Ę