Form 3160- 5	UNITED S		l	FORM APPROVED		
(August 1999)	DEP/ MENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT <b>N.M. OIL C.</b>			OMB No. 1004- 0135		
St	JNDRY NOTICES AND	REPORTS ON WE	625 N. French Dr	NM-LC059576		
a	Do not use this form for propos abandoned well. Use Form 3160		10bbs, NM 88240	llottee, or Tribe Name		
	RIPL(C2TIS 2011A Inst.			CA. Agreement Designation		
1. Type of Well Oil Well Gas Well	Other		8. Well Name	e and No.		
2. Name of Operator				Federal 1		
Devon SFS Operating, Inc.		Maljamar 10 9. API Well 1				
3a. Address 3b. Phone No. (include area code)				30-025-35317		
20 North Broadway, Suite 1500, OKC, OK 73102       (405)228-7512         4. Location of Well (Footage, Sec., T, R, M, or Survey Description)       (405)228-7512				Pool, or Exploratory Area		
4. Location of well ( <i>rootage, Sec., 1., K., M., or Survey Description</i> )				Wildcat (Cisco Canyon) r Parish, State		
660'FSL& 1530'FEL 10 T-17S R-32E				NM		
12. CHECK APPROP	RIATE BOX(S) TO INDICA	TE NATURE OF NOT	ICE, REPORT, OR OTHER D	ATA		
TYPE OF SUBMISSION TYPE OF ACTION						
X Notice of Intent						
LA Produce of ment			Production (Start/Resume)	Water Shut-Off		
r	Alter Casing	Fracture Treat	Reclamation	Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete	Other		
	Change Plans	Plug and Abandon	Temporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	'ater Disposal		
testing has been completed. Final Ab- determined that the site is ready for fi	andonment Notice shall be filed only a inal inspection.)	fter all requirements, including	pletion in a new interval, a Form 3160-4 reclamantion, have been completed, and			
	e RBP & POOH w/tbg, pkr, & RE	3P				
RU WL. RIH w/CIBP to 10,400						
RIH w/4" csg gun & Perf Wolfc	amp 2 SPF from 9796' - 9802' &	9826' - 32 (24 shots) & 91	132'			
9148', 9132' - 40', 9071' - 76', 8						
RIW w/RBP, pkr, & 2 7/8" 6.5#	N-80 tbg to 9900', Set RBP & P	U to 9832'. Spot 2 bbls 15	% NeFe across perfs. PU to 9700'	*APPROVED)		
Acidize zone @ 3-5 BPM w/200	00 gal 15% NeFe dropping 36 bal	I sealers evenly spaced. S	I for 15 min and flow back well.	* have been		
RU Swab & swab test zone. If unproductive, continue with procedure.						
Rel pkr & RIH to RBP. Rel RBP & PU to 9300'. Set RBP & test to 3000 psi.						
PU to 9148'. Spot 4 bbls 15% NeFe across perfs. PU to 8900' & set pkr.						
Acidize zone @ 3-5 BPM w/400	0 gal 15% NeFe dropping 100 ba	all sealers evenly spaced.	SI for 15 min and flow back well.	GARY GOURLEY		
RU swab & swab test zone. Eva	aluate for additional testing or rec	ompletion to Paddock @	5600'	- CONCER		
7						
14. I hereby certify that the foregoing is tri Name (Printed/ Typed)	le and correct.	Title				
Karen Cotton Aren attm Engineering Technician			ician			
Signature Date				· · · · · · · · · · · · · · · · · · ·		
		2	16/02			
Approved by	THIS SPACE F	OR FEDERAL OR STA	TE OFFICE USE	Date		
Approved by		1 me		1 J		
Conditions of approval, if any are attached.						
certify that the applicant holds legal or equi which would entitle the applicant to conduc	ct operations thereon.	<u>l</u>		<u> </u>		
Title 18 U.S.C. Section 1001 AND Title 43 States any false, fictitiousor fraudulent state			willfully to make any department or age	ency of the United		

States any false, fictitiouse (Instructions on reverse)

5

(