

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-1571

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection Well	7. Unit Agreement Name
2. Name of Operator	North E. K. Queen Uni
3. Address of Operator	8. Farm or Lease Name
P. O. Box 2040 Midland, Texas 79702	Tract 1
4. Location of Well	9. Well No.
UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM	10. Field and Pool, or Wildcat
THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>17S</u> RANGE <u>33E</u> N.M.P.M.	EK Yates 7 Rivers Que
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4105' GL	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

* Commission will be notified 24 hrs. prior to commencing work.

1. Trip in hole with cast Iron bridge plug. Set CIBP @ 3850'.
2. Spot 35' of cement on top of CIBP.
3. Displace hole with mud-laden fluid. Close pipe rams. Test plug and casing to 500#'s.
4. Perforate 4 holes @ 1475' (Top of Anhydrite @ 1510') Circulate or squeeze 50 sks. or sufficient cement to isolate anhydrite section. WOC
5. Tag plug in casing and test to 500#'s.
6. Spot cement plug 50 ft. above and below surface casing shoe @ 867'. WOC
7. Tag and test plug to 500#'s. Cut bradenhead and weld steel plate on casing. Set P & A marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chuck Sledge TITLE Petroleum Engineer DATE 8-13-87

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE AUG 25 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 24 1987
HOBBS OFFICE