## State of New Mexico Energy, Minerals & Natural Resources Department

Form C-103 Revised 1-1-89

District Office	transfers of Natural	resources Department	Revised 1-1-89
DISTRICT I P. O. Box 1980, Hobbs, NM 88240  OIL CONSERVATION DIVISION P. O. Box 2088		WELL API NO.	
		30-025-01528	
<u>DISTRICT II</u>			5. Indicate Type of Lease
P. O. Drawer DD, Artesia, NM 88210		STATE FEE	
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410			B-2229
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			Caprock Maljamar Unit
1 Type of Well:	e tory rok ocen rkoros/us.)		
OIL GAS			
WELL WELL OTHER WIW			
2. Name of Operator The Wiser Oil Company			8. Well No.
3. Address of Operator			88
P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797			9. Pool name or Wildcat
4. Well Location			Maljamar Grayburg San Andrea
Unit Letter <u>D</u> : <u>330</u>	Feet From The North Li	ne and Fo	eet From The West Line
Section 28	170	225	
Section 28	Fownship 17S Range	33E N	MPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4186' GR			
VIIII III III III III III III III III I			
The propriet Box to male to Holice, Report, of Other Data			
AOTICE OF INTENTION TO 2082E			EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	01141105 51 4115		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CARING TEST AND SEA	
S. ISING 1251 AND SELIM		ENI JOB L	
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103.			
Wiser requests approval to Plug and Abandon the well by the procedure listed below.			
Surface Coning 9 5/07 and © 2502			
Surface Casing: 8-5/8" set @ 358' Production Casing: 5-1/2" @ 4565' Perfs: 4278'-4476'			
1 0100 1270 1170			
1. TIH w/tbg. and tag cmt. ret. @ 29			
<ol> <li>Spot 50' cmt. plug on cmt. retaine</li> <li>Tag cement.</li> </ol>	г.		
4. Circulate abandonment mud.			
5. Spot 50' cmt. plug @ 1600'.			
6. Tag cmt.		Ŧ ; ~	
<ul><li>7. Spot 50 cmt. plug @ 600'.</li><li>8. Perforate casing @ 360'. Circulat</li></ul>	A		는 (Might) PLA TERMOTER of
9. Spot 50' cmt. plug to surface.			A STOR TO THE POST OF THE
<ol><li>Install dry hole marker.</li></ol>		:	THE STARTENS FOR WEST 1888 AS THE
11. Clean location.			
I hereby certify that the information above is t	rue and complete to the best of my knowle	dge and belief	
. H.	•	_	
SIGNATURE W	TITLE St	perintendent	DATE January 3,2002
TYPE OR PRINT NAME Mike Yorks			
(This space for State Use)			
APPROVED BY			
	TITLE		DATE