

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-2439

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR APPLICATION TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL C-101 FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- **Water Injection Well**

2. Name of Operator
Murphy H. Baxter

3. Address of Operator
P. O. Box 2040 Midland, Texas 79702

4. Location of Well
UNIT LETTER **I** **2310** FEET FROM THE **South** LINE AND **660** FEET FROM THE **East** LINE, SECTION **1** TOWNSHIP **18S** RANGE **33E** NMPL.

15. Elevation (Show whether DF, RT, GR, etc.)
4100 DF

7. Unit Agreement Name
N. EK Queen Unit
8. Farm or Lease Name
Tract 2
9. Well No.
1
10. Field and Pool, or Wildcat
EK Yates 7 Rivers Queen
12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☒	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

* Commission will be notified 24 hrs. prior to commencing work.

1. Trip in hole with CIBP. Set CIBP. @ 4150'.
2. Spt 35' of cement on top of CIBP.
3. Displace hole with mud-laden fluid. Close pipe rams. Test plug and casing to 500#'s.
4. Perforate 4 holes @ 1675'. (top of anhydrite @ 1706'.) Circulate or squeeze 50 sks. or sufficient cement to isolate anhydrite section. WOC.
5. Tag plug in casing & test to 500#'s.
6. Spot cement plug 50' above and below surface casing shoe @ 1716'. WOC.
7. Tag and test plug to 500#'s. Cut bradenhead and weld steel plate on casing/ Set P & A marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chuck Sledge TITLE Petroleum Engineer DATE 8-13-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 25 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 24 1987
OCD
HOBBS OFFICE