Submit 3 Copies To Appropriate District Office	State of I tell Manager		Form C-103 Revised March 25, 199			
District I	Energy, Minerals and Natural Resources		ral Resources	WELL API NO.	Revised March	23, 1997
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERV	ATION	DIVISION	30-025-01610		
811 South First, Artesia, NM 88210 District III	Artesia, NM 88210 OIL CONSERVATION DIVISION 2040 South Pacheco			5. Indicate Type of		
000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505			FEDERAL S		E□	
<u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505	Santa 1 c	, 11111 07	303	6. State Oil & G 04591		
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL)	ES AND REPORTS ON LS TO DRILL OR TO DEEP	EN OR PLU	G BACK TO A	7. Lease Name or		t Name
DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.) 1. Type of Well:	TION FOR PERMIT" (FORM	C-101) FOF	SUCH	EK Queer	n Unit	
Oil Well Gas Well Other Water Injection						
2. Name of Operator Seely Oil Company				8. Well No. 614		
Seely Oil Company 3. Address of Operator 815 West 10 th Street, Fort Worth, Texas 76102			9. Pool name or Wildcat EK – Yates – Seven Rivers - Queen			
4. Well Location	. To Street, Total World	,				
Unit Letter <u>E</u> :	1980 feet from the	North	line and660	feet from the	West line	:
	Tananahin 190	Dono	. 22E	NMPM Le	a County	
Section 13	Township 18S 10. Elevation (Show was 3968')	hether Di	e 33E R, RKB, RT, GR, el		a County	
11. Check Appropriate Box to			Report or Other	Data		
NOTICE OF ANTENTION TO: PERFORM REMEDIAL WORK DLUG AND ABANDOL			SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING			ASING [
t to the second	CHANGE PLANS			ILLING OPNS.	PLUG AND	[
TEMPORARILY ABANDON \L	CHANGE FLANS		COMMENSE DI			
<u></u>	MULTIPLE		CASING TEST A		ABANDONME	INT -
						NT L
PULL OR ALTER CASING	MULTIPLE COMPLETION Detect operations. (O	☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1	ND details, and give	ABANDONME	es,
OTHER: 12. Describe proposed or compincluding estimated date of	MULTIPLE COMPLETION Deted operations. (Control of the starting any proposed for proposed completic	Clearly sied work)	CASING TEST A CEMENT JOB OTHER: tate all pertinent . SEE RULE 1 ompilation.	details, and give 103. For Multipl	ABANDONME pertinent date le Completion	es,
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company proposed	MULTIPLE COMPLETION Detect operations. (Control of starting any proposed for proposed completions to repair the well	Clearly sized work) on or reco	CASING TEST A CEMENT JOB OTHER: tate all pertinent . SEE RULE 1 ompilation.	details, and give 103. For Multipl	ABANDONME pertinent date le Completion	es,
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line	MULTIPLE COMPLETION Deted operations. (Control of starting any proposed for proposed completions to repair the well and tubing and packet	Clearly sized work) on or reco	CASING TEST A CEMENT JOB OTHER: tate all pertinent . SEE RULE 1 ompilation.	details, and give 103. For Multipl	ABANDONME pertinent date le Completion	es,
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te	MULTIPLE COMPLETION Deleted operations. (Constanting any proposed for proposed completions to repair the well set tubing and packet est casing.	Clearly sied work) on or recand resu	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 ompilation. me water injection	details, and give 103. For Multiplicion as set out below	ABANDONME pertinent date le Completion	es,
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP	MULTIPLE COMPLETION Detect operations. (Control of starting any proposed for proposed completions to repair the well end tubing and packet est casing.	Clearly sized work) on or recurrent and resurces.	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 ompilation. me water injection	details, and give 103. For Multiplicion as set out below	ABANDONME pertinent date le Completion	es,
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes	MULTIPLE COMPLETION Deted operations. (Control of starting any proposed for proposed completions to repair the well and tubing and packet st casing. Determine the starting and packet of the starting and packet of the starting and packet of the starting. Determine the starting and packet of the starting and packet	Clearly sized work) on or reconnected and results.	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 ompilation. me water injections	details, and give 103. For Multiplion as set out below ze cementing.	ABANDONME pertinent date le Completion	es,
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes 5. Clean out OH from 431	MULTIPLE COMPLETION Detected operations. (Control of starting any proposed for proposed completions to repair the well and tubing and packet est casing. Detected operations. (Control of starting any proposed completions) Detected operations. (Control of starting and packet casing.) Detected operations. (Control of starting and packet casing.) Detected operations. (Control of starting any proposed completions) Detected operations. (Control of startin	Clearly sized work) on or reconnected and results.	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 ompilation. me water injections	details, and give 103. For Multiplion as set out below ze cementing.	ABANDONME pertinent date le Completion	es,
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes 5. Clean out OH from 431 6. Acidize formation. PO	MULTIPLE COMPLETION Detect operations. (Control of starting any proposed for proposed completions to repair the well and tubing and packet casing. Detect to repair the well and the starting and packet casing. Detect to repair the well and the starting and packet casing. Detect to repair the well are the starting and reperted to t	Clearly sized work) on or recurrence and resurcasir casir casir cools. Corate from packer.	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 compilation. me water injection ag leak by squee om 4295'-4306'	details, and give 103. For Multiple ion as set out below ze cementing.	pertinent date le Completion	es, is:
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes 5. Clean out OH from 431 6. Acidize formation. POO 7. Run Salta lined tubing a	MULTIPLE COMPLETION Deted operations. (Control of starting any proposed for proposed completions of proposed completions of tubing and packets to repair the well above perfs and report casing. Recover the starting of the	Clearly sized work) on or recurrence and resurcasir casir casir cools. Corate from packer.	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 compilation. me water injection ag leak by squee om 4295'-4306'	details, and give 103. For Multiple ion as set out below ze cementing.	pertinent date le Completion	es, is:
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes 5. Clean out OH from 431 6. Acidize formation. PO	MULTIPLE COMPLETION Deted operations. (Control of starting any proposed for proposed completions of proposed completions of tubing and packets to repair the well above perfs and report casing. Recover the starting of the	Clearly sized work) on or recurrence and resurcasir casir casir cools. Corate from packer.	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 compilation. me water injection ag leak by squee om 4295'-4306'	details, and give 103. For Multiple ion as set out below ze cementing.	pertinent date le Completion	es, is:
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes 5. Clean out OH from 431 6. Acidize formation. POO 7. Run Salta lined tubing a 8. Return well to water in	MULTIPLE COMPLETION Detected operations. (Control of starting any proposed for proposed completion of the starting and packets the starting and packets the starting and packets the starting. The starting and starting and starting and plastic coated Adjection.	Clearly sized work) on or reconstruction and results. Corate from packer. DI packer	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 compilation. me water injection and leak by squee om 4295'-4306' er to 4250'±. To	details, and give 103. For Multiple ion as set out below ze cementing. with 2 SPF. est casing per OC	pertinent date le Completion	es, is:
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes 5. Clean out OH from 431 6. Acidize formation. POO 7. Run Salta lined tubing a 8. Return well to water in	MULTIPLE COMPLETION Detected operations. (Control of starting any proposed for proposed completion of the starting and packets the starting and packets the starting and packets the starting. The starting and starting and starting and plastic coated Adjection.	Clearly sized work) on or reconstruction and results. Corate from packer. DI packet	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 compilation. me water injection and leak by squee om 4295'-4306' er to 4250'±. To	details, and give 103. For Multiple ion as set out below ze cementing. with 2 SPF. est casing per OC	pertinent date le Completion	es, is:
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes 5. Clean out OH from 431 6. Acidize formation. POO 7. Run Salta lined tubing a 8. Return well to water in	MULTIPLE COMPLETION Deted operations. (Control of starting any proposed for proposed completions of proposed completions to repair the well and packets to asing. Proposed and repert of the well of	Clearly sized work) on or reconstruction and results. Corate from packer. DI packet	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 compilation. me water injection ag leak by squee om 4295'-4306' er to 4250'±. To best of my knowle	details, and give 103. For Multiple ion as set out below ze cementing. with 2 SPF. est casing per OC	pertinent date le Completion Dw: TE 12/4/00	es, is:
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes 5. Clean out OH from 431 6. Acidize formation. POO 7. Run Salta lined tubing a 8. Return well to water in	MULTIPLE COMPLETION Deted operations. (Control of starting any proposed for proposed completions of proposed completions to repair the well and packets to asing. Proposed and repert of the well of	Clearly sized work) on or reconstruction and results. Corate from packer. DI packet	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 compilation. me water injection ag leak by squee om 4295'-4306' er to 4250'±. To best of my knowle	details, and give 103. For Multiple ion as set out below the community of	pertinent date le Completion Dw: TE 12/4/00	es, is:
OTHER: 12. Describe proposed or compincluding estimated date of Attach wellbore diagram of Seely Oil Company propose 1. POOH with cement line 2. GIH with packer and te 3. If casing leaks, set RBP 4. Drill out cement and tes 5. Clean out OH from 431 6. Acidize formation. POO 7. Run Salta lined tubing a 8. Return well to water in	MULTIPLE COMPLETION Detected operations. (Or starting any proposed for proposed completion of proposed completion	Clearly sized work) on or reconstruction and results. Corate from packer. DI packer. TITLE	CASING TEST A CEMENT JOB OTHER: tate all pertinent SEE RULE 1 compilation. The water injection water injection are water inje	details, and give 103. For Multiple ion as set out below the community of	pertinent date le Completion Ow: TE 12/4/00 (817) 332-1377	es, is: