brait 3 Copies

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

District Office Revised 1-1-89 DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 2088 NA DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease STATE X DISTRICT III 1000 Rio Brazos Rd., Azzec, NIM 87410 FEE 6. State Oil & Gas Lease No. B-1520 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) **BRIDGES STATE** Type of Well: OEL WELL X OTHER 2. Name of Operator 8. Well No. Mobil Producing Tx. & N.M. Inc.* 54 3. Address of Operator *Mobil Exploration & Producing U.S. Inc., as Agent for 9. Pool name or Wildcat Mobil Producing TX. & N.M. Inc., P. O. Box 633, Midland, TX 79702 VACUUM GRAYBURG SAN ANDRES 4. Well Location Unit Letter P : 660 Feet From The SOUTH 660 Feet From The EAST Line and Township 17S Range 34E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4025 GL Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER:_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RU CMT SERV. SPOT A BALANCED PLUG OF 39 SX CMT FROM 1650-1550 ACROSS TOP OF SALT @ 1600 FT. DISPLACE TBG W/6 BBLS 10 PPG GELLED BRINE. PU TBG (400 FT AND WOC 8 HRS. TAG CMT PLUG TOP @ 1550. PU TBG TO 880 FT. 2. SPOT A BALANCED PLUG OF 43 SX CMT FROM 880-780 . DISPLACE TBG W/3 BBLS OF 10 PPG GELLED BRINE. PU TBG TO 50 FT. 3. SPOT 21 SX FROM 50 FT TO SURFACE. POH W/WS. WOC. MAKE SURE CMT IS TO TOP OF PIPE. 4. ND BOP. RD PU. CUT CSG 3' BELOW GROUND LEVEL. WELD A STEEL PLAT ON CSG STUB. ERECT P&A MARKER W/ WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION. true and complete to the best of my knowledge and belief. Engineering Technician (915)J. W. DIXON TYPE OR PRINT NAME 688-2452

CONDITIONS OF APPROVAL, IP ANY:

(This space for State Use)

APPROVED BY-