

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised March 25, 1999

DISTRICT I
1625 N. French Dr., Hobbs, NM 88240
DISTRICT II
811 South First, Artesia NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410
DISTRICT IV
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-02034

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-1520

7. Lease Name or Unit Agreement Name

Bridges State

8. Well No.

56

9. Pool name or Wildcat

Vacuum; Grayburg-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

Oil
Well ☐

Gas
Well ☐

Other ☐ **Injector**

2. Name of Operator

Exxon Mobil Corporation

3. Address of Operator **P.O. Box 4358**

Houston

TX 77210-4358

4. Well Location

Unit Letter **I** : **1980** Feet From The **South** Line and **660** Feet From The **East** Line

Section **14**

Township **17S**

Range **34E**

NMPH

Lea

County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
GR 4029'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE
COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion)

1. Move in and rig up well service unit. Kill well as needed.

2. Rig up BOP equipment.

3. Unseat packer and POH with tubing.

4. Rig up wireline unit and go in hole with CIBP and set at 4300', which is within 100' of the open hole zone. Dump ball no less than 35' of cement on top of plug. POH and rig down wireline unit.

5. Run in hole with tubing string to TOC. Circulate packer fluid

6. POH and lay down tubing leaving 1000' of kill string in wellbore.

7. Run Mechanical Integrity Test by pressuring the casing to 500 psi for no less than 30 minutes to demonstrate good casing integrity.

8. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *D. O. Howard*

TITLE **Regulatory Specialist** # 2914

DATE **11/30/2000**

TYPE OR PRINT NAME **Dolores O. Howard**

TELEPHONE NO. **(713) 431-1792**

(This space for State Use)

APPROVED BY *Harry W. Wink* TITLE

DATE

CONDITIONS OF APPROVAL IF ANY: