	· · · · · · · · · · · · · · · · · · ·	
NO. OF COMICS ACCEIVED		
DISTRIBUTION		Form C-103
SANTAFE	MEN MEN AND AND	Supersedes Old
FILE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
U.5.G.S.	-	-11-63
LAND OFFICE	-	5a. Indicute Type of Lease
OPERATOR	 -	1 - 157)
CHERATOR	_]	
		5. State Off & Gas Lease No.
SUND	REY NOTICES AND REPORTS ON WELLS	E-8714
100 NOT USE THE FORM FOR HE	TON FOR PLANTE OF TO CAPTURE OF THE GACK TO A DIFFERENCE DESCRIPTION FOR PLANTE OF THE CAPTURE O	
014	TO SOME CATOLITICAL SOCIA PACHOSALS.	
WELL WELL	OTHER. WATER INJECTION WELL	V. Unit Agreement Nume
Name of Operator	OTALL THOLOTION WELL	N.E.K. QUEEN Wint
	MIIDDUV II DAVTED	6. Ferm of Lease Name
Address of Operator	MURPHY H. BAXTER	Tract 4
P.O. BOX 2040	Midland TV 70700	9. Well No.
Lecution of Well	Midland, TX 79702	
Δ	220	6
UNIT LETTER	330 N 660	10. Field and Fool, or Wilden
· F	FEET FROM THE LINE AND FEET I	I LONG I ATES / KIVAYO IN
THE	7 18 S 424 F	W. C.
LINE, SECTION	ON TOWNSHIP	
	17.1.1.1	
	15. Elevetion (Show whether DF, RT, CR, etc.)	12, County
TITELLI TILLIANI	- XXXXXXXXXXXXX-	1 (69 ////////
Check /	Appropriate Box To Indicate Nature of Notice, Report or of TENTION TO:	
NOTICE OF IN	TENTION TO:	Other Data
	SUBSEQUE	NT REPORT OF:
REFORM REMEDIAL WORK		
APCRARILY ABANDON	PLUG AND ABANDON REMEDIAL WORK	ALTERING ALONG
L OR ALTER CASING	COMMENCE DRILLING OPHS.	ALTERING CASING
	CHANGE PLANS CASING TEST AND CEMENT JOS	PLUG AND ABANDONMENT
OTHER	O'HER	· _
Describe Proposed of Completed O	rations (Clearly state all pertinent details, and give pertinent dates, includi-	
work) SEE RULE 1103.	rations (Clearly state all pertinent details, and give pertinent dates, include	
1	The state of the s	ng estimated date of starting any propose.
. Move in . Rig up.	Pull well equipment.	
2. Run in hole and sp	oot 25 sks of coment a case.	
3. Tag @ 4000'.	oot 25 sks. of cement @ 4250'. Wait on cement.	
4. Rig up perfs and p	perforate a 1700!	
5. Run in hole and on	errorate 6 1/00.	•
6. No tag. Respot 50	oot 50 sks. of cement and squeeze.	
7 Tag 6 15001	sks. of cement and squeeze. sks. of cement and squeeze. Wait on cement.	
Spot	25 sks. of cement @ 370'.	
8. Cut well head and	set top hole plug and P & A marker.	
	res and r & A marker.	
Hay that the information about	ve is true and complete to the best of my knowledge and belief.	
flance Maclina	D. A. C.	
	ι α A Supervisor- Baber V	Well Servicing Co. 11-19-8
	TITLE	D 3 - 1 - 1 - 0
		UATE
		2
map 2	Colo VIIII Tra	
IONS OF APPROVAL, IF ANY	OIL & GAS INSPECTOR	DATE WAY 2 17 TORO
1 tarentelles	mulk	WILL PARTY