

COPIES RECEIVED		
DISTRIBUTION		
SAFE		
E		
S.G.S.		
AND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Re-entry		5. State Oil & Gas Lease No.
2. Name of Operator V. H. Westbrook		7. Unit Agreement Name
3. Address of Operator P. O. Box 2264, Hobbs, New Mexico 88240		8. Farm or Lease Name Quebedeaux
4. Location of Well UNIT LETTER A , 330 FEET FROM THE North LINE AND 990 FEET FROM East 2 18S 35E THE _____ LINE, SECTION _____ TOWNSHIP _____ RANGE _____ NMPM.		9. Well No. 1
10. Field and Pool, or Wildcat Vacuum San Andres		11. County Lea
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged in the following manner per telephone instructions from Mr. Lester Clements on January 6, 1975. Work performed by Halliburton.

1. Ran 2 7/8" tubing to 5200'. Circulated hole with 10# mud-laden fluid.
2. Pumped 100' plug - 30 sks. in 5 1/2 - 5100' to 5000'.
3. Pulled up and pumped 100' plug - 30 sks. in 5 1/2 - 4900' to 4800'.
4. Pulled up and pumped 100' plug - 40 sks. in 5 1/2 & 8 5/8 - 2900' to 2800'.
5. Set 10 sk plug in top of 8 5/8.
6. Erected 4" dry hole marker with required information and cut off anchors to ground level.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>V. H. Westbrook</u>	TITLE <u>Operator</u>	DATE <u>February 3, 1975</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>[Signature]</u>

CONDITIONS OF APPROVAL, IF ANY: