STATE OF NEW MEXICO			
ERGY AND MINERALS DEPARTMEN			
	OIL CONSERVA	TION DIVISION	
DISTRIBUTION	P. O. BO)	K 2088	Form C-103
SANTAFE	SANTA FE. NEW	MEXICO 87501	Revised 10-1-78
FILE			Sc. Indicate Type of Lease
U.L.G.S.			
LAND OFFICE			
OPENATOR			5. Stote Oil & Gas Lease No.
	API I	No. 30-025-03040	в-3140
SUNDRY LOS NOT USE THIS FORM FOR HAPPLICATIC	NOTICES AND REPORTS ON	WELLS ACA TO A DIFFERENT RESERVOIR. P PROPOSALS.	7. Unit Agreement Name
OIL CAB WELL	OTHER- · .		Vacuum Abo Unit
ame of Operator			8. Farm or Lease Name
Phillips Oil Company	•		Vacuum Abo Unit
idress of Operator			9. Well No. Tr. 13 Btry 2
- (01 (001 Dechard	- Street Odessa Texas	79762	9
Room 401, 4001 Pendidos	k Street, Odessa, Texas	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	10. Field and Pool, or Wildcon
	and north	660	Vacuum Abo Reef
UNIT LETTER	330 reet from the north	LINE AND	
	» <u>3</u> тоwнанія <u>18</u> -5		
	15. Elevation (Show whether 3945' RKB	DF, RT, CR, etc.j	12. County Lea
Check A	ppropriate Box To Indicate N	ature of Notice. Report or Ot	her Data
NOTICE OF IN			T REPORT OF:
PORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PORARILY ABANDON	_	COMMENCE DRILLING OPHS.	PLUS AND ABANDONMENT
L OR ALTER CASTNG	CHANGE PLANS	CABING TEST AND CEMENT JOB	_
		OTHER	
Drill out, perfora	te, acidize & convert X		
o water injection per N	MOCD Order R-3181-B		
Design of an Completed One	erations (Clearly state all pertinent dett	ails and rive pertinent dates, including	estimated date of starting any proposed

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

MI & RU DDU. Install BOP. Pull downhole equipment. GIH with drill bit on 2-7/8" work string. Establish circulation with fresh water containing Drispac and Flosal. Add CaCO3 if needed to control water loss. Drill out hydromite and cement plugs with reverse circulation to a TD of 9100'. Circulate the hole clean with fresh water. Spot 10 bbls 10% acetic acid. Run GR-CCL from PTD to 8700', correlate to previous logs run. Perforate Abo Reef using 4" OD casing gun lJSPF on spiral phasing 8800'-9084' 194' 194 shots. GIH w/RTTS-type packer, set @ 8750'. Swab perfs to clean up. Load tbg csg annulus with water. Pressure test casing and packer to 1000 psi. Acidize perfs with 18,700 gals 28% NEFE HCL acid containing 1 gal NE agent/1000 gals acid, 1 gal scale inhibitor/1000 gals acid, 5 gals inhibitor/1000 gals acid and 6 gals iron sequestering agent/1000 gals acid. Swab back load and acid water. COOH with tubing and packer. GIH with nickel-plated Baker model A-3 Loc-Set packer and nickle-plated on-off tool with 1.78" BFC "R" profile on 2-3/8" 4.7# J-55, N-80 & L-80 plastic coated tubing, set packer at 8750'. Set profile plug in packer. Load tubing and annulus from top with produced water. Test tubing to 1800 psi. Test tubing-casing annulus to 2000 psi.. Disconnect tubing from packer and raise tubing 10'. Circulate annulus with inhibited brine. Connect tubing to packer assembly and set tubing in 2000# tension. Retrieve profile plug. Connect to injection line and put on injection.

BOP EQUIP: Series 900, 3000 #WP, double w/l set blind rams, l set pipe rams, manually operated.

- Rey alle W. J. Mueller	Sr. Engineering Specialist	October 11, 1984
Oxectical and a second se		OCT 15 1964