|  |   | State of New  | Mexico  |   | Form C-103                      |
|--|---|---|---|---|---------------------------------|
| Submit 3 conies<br>to Appropriate<br>District Office   | En  | Minerals and Natural  | Resources Department  |   | Revised 1-1-89                  |
| DISTRICT I   | OII   | <b>CONSERVAT</b>  | ION DIVISION  | WELL API NO.                            |                                 |
| P.O. Box 1980, Hobbs, NM 88240<br>P.O. Box 2088  |   |   |   | 30-025-03085                            |                                 |
| DISTRICT II Santa Fe, New Mexico 87504-2088  |   |   |   | 5. Indicate Type of Lease               |                                 |
| P.O. Box Drawer DD, Artesia, NM 88210  |   |   |   | STATE                                   | FEE 🗌                           |
| DISTRICT III<br>1000 Rio Brazos Rd., Aztec, NM 87410   |   |   |   | 6. State Oil / Gas Lease No.<br>B-103   | 31                              |
| SUNDRY NOTICES AND REPORTS ON WELL   |   |   |   |   |                                 |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A<br>DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  |   |   |   | 7. Lease Name or Unit Agreeme           | nt Name                         |
| (FORM C-101) FOR SUCH PROPOSALS.)  |   |   |   | NEW MEXICO AB STATE                     |                                 |
| 1. Type of Well: OIL GAS WELL WELL OTHER   |   |   |   |   |                                 |
| 2. Name of Operator<br>TEXACO EXPLORATION & PRODUCTION INC.  |   |   |   | 8. Well No. 2                           |                                 |
| 3. Address of Operator 205 E. Bender, HOBBS, NM 88240  |   |   |   | 9. Pool Name or Wildcat<br>VACUUM ABO F |                                 |
| 4. Well Location   |   |   |   |   |                                 |
| Unit Letter  | P : 660   |   | UTH Line and <u>560</u>   | Feet From TheEAST                       | _Line                           |
| Section 6  |   | •   |   | 1PM LEA (                               | COUNTY                          |
| 10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3977 kb  |   |   |   |   |                                 |
| 11.  | Check Approp  | riate Box to Indicate N   | lature of Notice, Report  | t, or Other Data                        |                                 |
| NOTICE OF I  | NTENTION TO   | <b>)</b> :  | SU  | JBSEQUENT REPORT                        | OF:                             |
| PERFORM REMEDIAL WORK  |   | AND ABANDON   | REMEDIAL WORK   |   | ig 🗌                            |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPE   |   |   |   | RATION PLUG AND ABAN                    |                                 |
| PULL OR ALTER CASING CASING TEST AND CEMEN   |   |   |   | NT JOB                                  | _                               |
| OTHER: A   | dd Abo Reef perfs an  | d acid treat 📃 🗵  |   |   |                                 |
| <ol> <li>Describe Proposed or C<br/>any proposed work) SE</li> </ol>   |   | ns (Clearly state all pertine   | ent details, and give pertine   | nt dates, including estimated d         | ate of starting                 |
| notify DJC or PWM before p<br>2. Run in hole with casing s<br>3. Perforate Upper Abo Reef<br>8574'-8630', 8670'-8688' (74<br>4. TIH with RBP with ball ca<br>RBP/ball catcher @ approxit<br>5. Acid treat original perfora<br>6. Swab back load taking sa<br>7. Release RBP and treating<br>and test to 500 psi.<br>8. Acid treat Upper Abo Ree<br>9. Swab back load taking sa | proceeding with workd<br>craper and bit. Clear<br>f formation with 2 jsp<br>4' interval, 148 Holes<br>atcher and 10,000 ps<br>mately 8884'. Set tre<br>ations with 2500 galld<br>amples of PH, oil cut,<br>g packer and move u<br>ef perforations (8574<br>amples of PH, oil cut,<br>perforations with pack<br>ion tubing. Set seatir | over.<br>n out to PBTD @ 9020'.<br>f and 120° phasing as follow:<br>i differential treating packer of<br>ating packer @ 8695'.<br>ons 15% NEFE + 1250# rock<br>and swab volumes.<br>p hole. Set RBP with ball ca<br>-8688') with 4000 gallons 15<br>and swab volumes.<br>ker. Release RBP and TOH | s:<br>In 2-7/8" production tubing. To<br>I salt (Pmax=6000 psi).<br>tcher @ 8700' and treating pa<br>% NEFE + 111 ball sealers fo<br>with RBP, treating packer, & t |   | ng downhole. Set                |
| I hereby certify that the information abo<br>SIGNATURE Card<br>TYPE OR PRINT NAME  | / (j. p.~   | J. Carriger   | od. Engineer  | Telephone No.                           | 7/1/96<br>397-0426<br>UL 8 1996 |
| APPROVED BY  | elit <u>e i i i</u>   | TITLE   | <u>_</u>  | DATE                                    |                                 |

CONDITIONS OF APPROVAL, IF ANY: