

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	WELL API NO. 30-025-03086
2. Name of Operator Texaco Exploration & Production, Inc.	5. Indicate Type of Lease STATE ☐ FEE ☐
3. Address of Operator P. O. Box 3109, Midland, TX 79702	6. State Oil & Gas Lease No. B-1031
4. Well Location Unit Letter <u>O</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>6</u> Township <u>18S</u> Range <u>35E</u> NMPM Lea County	7. Lease Name or Unit Agreement Name: Central Vacuum Unit
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	8. Well No. 217
	9. Pool name or Wildcat Vacuum Grayburg - SA

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well, RIH w/WS, pull RBP set @ 4450'. L/D same RUWL, set 7 5/8" CIBP @ 4485'. (Grayburg - San Andres) Spot 40 Sx plug 4485'-4285'. WOC Tag 3. Spot 40 Sx plug 3906'-3700' (Queen) 4. Perf 6 holes @ 2800', Sqz 75 Sx plug 2800'-2500' (Yates, B-Salt) WOC Tag 5. Sqz 125 Sx plug 1700'-1400' (T-Salt, & bad Csg w/Wtr flow 1601'-1632') WOC Tag 6. Perf 6 holes @ 400', Sqz 125 Sx plug 400'-200' (10 3/4" shoe) WOC Tag 7. 10 Sx Surf, Install dry hole marker.	
THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.	

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbitt TITLE FACILITY ENGINEER DATE 9/24/01
Type or print name JAMES T. CORBITT Telephone No. 915 688-4438
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:


PLUGGING & ABANDONMENT WORKSHEET

(3 STRING CSNG)

OPERATOR TEXACO Exploration & Production
LEASENAME CENTRAL VACUUM UNIT

SECT 6 TWN 18S RNG 35 E
FROM 660 NSL 1980 EWL
TD: 8856
PBDT: 5274

WELL # 217
FORMATION @ TD ABO
FORMATION @ PBDT GRAYBURG - SA



	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	10 3/4	343	SURF	Circ	
INTMED 1					
INTMED 2					
PROD	7 5/8	5404	2500	CALC	
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1	4 1/2	5324	8856	Circ	
LINER 2					
CUT & PULL @			TOP - BOTTOM		
INTMED 1			PERFS	4589 - 4742	
INTMED 2			OPENHOLE	-	
PROD					

* REQUIRED PLUGS DISTRICT I

PLUG	TYPE	SACKS	DEPTH
EXAMPLES			
PLUG #1	OH	25 SXS	9850'
PLUG #2	SHOE	50 SXS	8700'-8800'
PLUG #3	CIBP/35'		5300'
PLUG #4	CIBP	25 SXS	5300'
PLUG #5	STUB	50 SXS	4600'-4700'
PLUG #6	REINR SQZ	200 SXS	400'
PLUG #7	SURF	10 SXS	0-10'
PLUG #8	CIBP	40 SX	4485-4285
PLUG #9	QUEEN	40 SX	3900-3700
PLUG #10	YATES	75 SX	2800-2500
PLUG #11	T-SALT	125 SX	1700-1400
PLUG #12	10 3/4 S	125 SX	400-200
PLUG #13	SURF	15 SX	10'-SURF
PLUG #14			
PLUG #15			
PLUG #16			
PLUG #17			
PLUG #18			
PLUG #19			
PLUG #20			
PLUG #21			
PLUG #22			
PLUG #23			
PLUG #24			
PLUG #25			
PLUG #26			
PLUG #27			
PLUG #28			
PLUG #29			
PLUG #30			
PLUG #31			
PLUG #32			
PLUG #33			
PLUG #34			
PLUG #35			
PLUG #36			
PLUG #37			
PLUG #38			
PLUG #39			
PLUG #40			
PLUG #41			
PLUG #42			
PLUG #43			
PLUG #44			
PLUG #45			
PLUG #46			
PLUG #47			
PLUG #48			
PLUG #49			
PLUG #50			
PLUG #51			
PLUG #52			
PLUG #53			
PLUG #54			
PLUG #55			
PLUG #56			
PLUG #57			
PLUG #58			
PLUG #59			
PLUG #60			
PLUG #61			
PLUG #62			
PLUG #63			
PLUG #64			
PLUG #65			
PLUG #66			
PLUG #67			
PLUG #68			
PLUG #69			
PLUG #70			
PLUG #71			
PLUG #72			
PLUG #73			
PLUG #74			
PLUG #75			
PLUG #76			
PLUG #77			
PLUG #78			
PLUG #79			
PLUG #80			
PLUG #81			
PLUG #82			
PLUG #83			
PLUG #84			
PLUG #85			
PLUG #86			
PLUG #87			
PLUG #88			
PLUG #89			
PLUG #90			
PLUG #91			
PLUG #92			
PLUG #93			
PLUG #94			
PLUG #95			
PLUG #96			
PLUG #97			
PLUG #98			
PLUG #99			
PLUG #100			

TD 8856