. OF COPIES RECEIVED		Form C-103 Supersedes Old
DISTRIBUTION		C-102 and C-103 Effective 1-1-65
ITA FE	NEW MEXICO OIL CONSERVATION COMMISSION	
.E		5a. Indicate Type of Lease
.G.S.		State X Fee
ND OFFICE		5. State Oil & Gas Lease No.
ERATOR		S. State Oil & Gas Lease No. State - B-1306-1
	SUNDRY NOTICES AND REPORTS ON WELLS orm for proposals to drill or to deepen or plug back to a different reservoir. e "application for permit -" (form C-101) for such proposals.)	
(DO NOT USE THIS F	E "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL X GAS		NONE
Name of Operator		8. Farm or Lease Name
Iteme of official	TEXACO Inc.	N. M. "R" State NCT-4
Address of Operator		9. Well No. 2
	P. O. Box 728 - Hobbs, New Mexico	10. Field and Pool, or Wildcat
Location of Well		Vacuum Abo Reef
D	913 FEET FROM THE West LINE AND 990 FEET FR	
UNIT LETTER		
North	LINE, SECTION 7 TOWNSHIP 18-S RANGE 35-E	•••• (/////////////////////////////////
THE		
mmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3985' (D. F.)	Lea
	Check Appropriate Box To Indicate Nature of Notice, Report or	Other Data
		INT REPORT OF:
NOT	TICE OF INTENTION TO:	
•	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON		
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND LEMENT 348	
OTHER		
Descette Despared of	Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu	ling estimated date of starting any proposed
work) SEE RULE 110	3.	•
	fallowing work on subject well:	
We pr	opose to do the following work on subject well:	
	Pull the pump equipment, and prepare to make additiona	l perforations
l. F	ull the pump equipment, and prepare to want and	-
	in the Vacuum Abo Reef Pool.	
	, a a for a sine with one set shot at 833/1. 83	551, 83631, 83691,
2. Perforate 2 7/8" Casing with one jet shot at 83341, 83551, 83631, 83691, 83781, 83921, 84141, 84281, 84371, 84451, 84591, 84661, and 84961.		
8	33781, 83921, 84141, 84261, 64371, 64451, 6457	,
3. 3	Set retrievable bridge plug at 8510', dump sand on tor	800 gallons 15% NE
	Pump 20 bbls. lease crude, and follow with 22,000 gal- three 7500 gallon stages with 6 ball sealers and 10 bb	ols. lease crude oll
	between stapes.	
		1
۲ ۲	Swab well, recover load oil, Test, and place well on p	production.
D •	Swab werry 1000001 Long ,	
18. I hereby certify that	the information above is true and complete to the best of my knowledge and belief.	
, [DATE October 3, 1966
11/	ancheller Assistant District	DATE
	Dan Gillett	
		DATE

į.