STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

MOT AND INTERMED CO		114.00
##. #* C#*(C\$ *(CE!#\$*		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE	Ti	1 1

OIL CONSERVATION DIVISION

SANTA PE				(2000		Form C-103	
	BUTION P O. BOX 2088					Revised 10-1-78	
<u></u>		SANIAF	E. NEW	MEXICO 87501			
FILE		0+5-NMOCD-Hobbs	1-JA		Sa. Indicate Type	— I	
U.S.G.S.		1-File	1-BW	1	State [X]	Fee	
OPERATOR	`	1-Engr. PWS		ura Richardson-Midland	5, State Oti & Gas	Lease No.	
0.5		1-Foreman EF	<u> </u>	ara Remarason Diarana			
			DTC OU	wet i c	111111111		
SUNDRY NOTICES AND REPORTS ON WELLS [DO NOT USE THIS FORM FOR PROPOSALS TO CRILL OR TO DECERT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "MAPPICEATION FOR PERMIT —" INCIDENT COLUMN CITOTIS FOR SUCH PROPOSALS."							
	USE "APPLICAT	ION FOR PERMIT -" IFORM C-10	DI) FOR SUC-	+ PROPOSALS.}	7. Unit Agreement	Name	
1.	· · · ·				7. Onk Agreement	Hank	
MEGF X	week L	OTHER-					
2. Name of Operator					8, Farm or Lease	j	
√Getty Oil	L Company				State AN		
3. Address of Opera	tor				9. Well No.		
	730, Hobbs	. NM 88240			4		
					10. Field and Poo	I. or Wildcat	
4. Location of Well	ŢŢ	1650!	Morth	990'	1		
NWIT 1 57758	n	16501	NOICH	LINE AND FEET FROM	Vacuum Abo	mmm	
			,		VIIIIII		
Ea	ast	7	129	RANGE 35E NMPM.		111111111	
THE	LINE, SECTION	OH TOWNSHIP		AANUE	VIIIIIII		
mm	mm	15. Elevation (Sho	ou whether	DF. RT. GR. etc.)	12. County	1111111	
		13. 5.6.0.0.0. (5.0.	3975'		Lea	VIIIIIII	
						7777777777	
16.	Check	Appropriate Box To In	dicate N	ature of Notice, Report or Ot	h er Data		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB				PLUG A	NG CASING		
	···• 🗀			Classed aut c 7		Ix l	
				OTHER Cleaned out & A	Acidized		
A+4F 8	···•			OTHER_ Cleaned out & A	Acidized	[A]	
OTHER							
-		perations (Clearly state all pe	ertinent deta				
-	sed or Completed O	perations (Clearly state all pe	ertinent deta	other <u>Cleaned Out & A</u>			
17. Describe Propo work) SEE RUI	sed or Completed O			nils, and give pertinent dates, including	estimated date of s	tarting any proposed	
17. Describe Propo work) SEE RUI 3/18/83	sed or Completed OLE 1103. Pull ODI an	d install beam pum	p. Rig	nils, and give pertinent dates, including	estimated date of s	tarting any proposed	
17. Describe Propo work) SEE RUI	eed or Completed O LE 1103. Pull ODI an Ran pkr to	d install beam pum 8996'. Pick up to	p. Rig	nils, and give pertinent dates, including g up. Pull ODI. Ran moo Dump 150 bbls fresh wa	estimated date of s del "R" Baker ater w/ soap.	tarting any proposed	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83	Pull ODI and Ran pkr to sulfide & t	d install beam pum 8996'. Pick up to rash. Spot 110 ga	p. Rig 8964'. Is scal	g up. Pull ODI. Ran mod Dump 150 bbls fresh wa e inhibitor across perfs	del "R" Baker ater w/ soap. 8 8617-8988.	pkr. Swab iron	
17. Describe Propo work) SEE RUI 3/18/83	Pull ODI an Ran pkr to sulfide & t Set pkr @ 8	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta	p. Rig 8964'. Is scal	oils, and give pertinent dates, including y up. Pull ODI. Ran mod Dump 150 bbls fresh wa e inhibitor across perfs id job @ 8:30 AM and pur	del "R" Baker ater w/ soap. 8 8617-8988. mped 7000 gal	pkr. Swab iron S DS-30 w/	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83	Pull ODI an Ran pkr to sulfide & t Set pkr @ 8	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta	p. Rig 8964'. Is scal	g up. Pull ODI. Ran mod Dump 150 bbls fresh wa e inhibitor across perfs	del "R" Baker ater w/ soap. 8 8617-8988. mped 7000 gal	pkr. Swab iron S DS-30 w/	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83	Pull ODI an Ran pkr to sulfide & t Set pkr @ 8	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls	p. Rig 8964'. Is scal rted ac	g up. Pull ODI. Ran mode Dump 150 bbls fresh water inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh.	del "R" Baker ater w/ soap. s 8617-8988. mped 7000 gal Treatment on	pkr. Swab iron SDS-30 w/ vac. Avergae	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin	p. Rig 8964'. Is scal rted ac Flus	g up. Pull ODI. Ran mode Dump 150 bbls fresh was e inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh.	del "R" Baker ater w/ soap. s 8617-8988. mped 7000 gal Treatment on s. End F.L.	pkr. Swab iron s DS-30 w/ vac. Avergae	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83	Pull ODI an Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works	ap. Rig 8964'. ls scal rted ac Flus F.L. @	g up. Pull ODI. Ran mode Dump 150 bbls fresh water inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh.	del "R" Baker ater w/ soap. s 8617-8988. mped 7000 gal Treatment on s. End F.L.	pkr. Swab iron s DS-30 w/ vac. Avergae	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works	ap. Ric 8964'. ls scal rted ac Flus F.L. @	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The world beauty of the control of	del "R" Baker ater w/ soap. s 8617-8988. mped 7000 gal Treatment on s. End F.L.	pkr. Swab iron s DS-30 w/ vac. Avergae	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83 3/22/83 3/23/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I Ran rods &	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works nstalled wellhead. pump. Placed on p	ap. Rig 8964'. Is scal rted ac F.L. @ tring.	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The water inhibitor across fresh. The without the state of the without the state of the without the state of the state of the without the state of the without the state of the state	del "R" Baker ater w/ soap. 8617-8988. mped 7000 gal Freatment on s. End F.L. g. SN @ 8889	r pkr. Swab iron s DS-30 w/ vac. Avergae 8400'.	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I Ran rods &	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works nstalled wellhead. pump. Placed on p	ap. Rig 8964'. Is scal rted ac F.L. @ tring.	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The world beauty of the control of	del "R" Baker ater w/ soap. 8617-8988. mped 7000 gal Freatment on s. End F.L. g. SN @ 8889	r pkr. Swab iron s DS-30 w/ vac. Avergae 8400'.	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83 3/22/83 3/23/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I Ran rods &	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works nstalled wellhead. pump. Placed on p	ap. Rig 8964'. Is scal rted ac F.L. @ tring.	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The water inhibitor across fresh. The without the state of the without the state of the without the state of the state of the without the state of the without the state of the state	del "R" Baker ater w/ soap. 8617-8988. mped 7000 gal Freatment on s. End F.L. g. SN @ 8889	r pkr. Swab iron s DS-30 w/ vac. Avergae 8400'.	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83 3/22/83 3/23/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I Ran rods &	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works nstalled wellhead. pump. Placed on p	ap. Rig 8964'. Is scal rted ac F.L. @ tring.	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The water inhibitor across fresh. The without the state of the without the state of the without the state of the state of the without the state of the without the state of the state	del "R" Baker ater w/ soap. 8617-8988. mped 7000 gal Freatment on s. End F.L. g. SN @ 8889	r pkr. Swab iron s DS-30 w/ vac. Avergae 8400'.	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83 3/22/83 3/23/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I Ran rods &	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works nstalled wellhead. pump. Placed on p	ap. Rig 8964'. Is scal rted ac F.L. @ tring.	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The water inhibitor across fresh. The without the state of the without the state of the without the state of the state of the without the state of the without the state of the state	del "R" Baker ater w/ soap. 8617-8988. mped 7000 gal Freatment on s. End F.L. g. SN @ 8889	r pkr. Swab iron s DS-30 w/ vac. Avergae 8400'.	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83 3/22/83 3/23/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I Ran rods &	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works nstalled wellhead. pump. Placed on p	ap. Rig 8964'. Is scal rted ac F.L. @ tring.	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The water inhibitor across fresh. The without the state of the without the state of the without the state of the state of the without the state of the without the state of the state	del "R" Baker ater w/ soap. 8617-8988. mped 7000 gal Freatment on s. End F.L. g. SN @ 8889	r pkr. Swab iron s DS-30 w/ vac. Avergae 8400'.	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83 3/22/83 3/23/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I Ran rods &	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works nstalled wellhead. pump. Placed on p	ap. Rig 8964'. Is scal rted ac F.L. @ tring.	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The water inhibitor across fresh. The without the state of the without the state of the without the state of the state of the without the state of the without the state of the state	del "R" Baker ater w/ soap. 8617-8988. mped 7000 gal Freatment on s. End F.L. g. SN @ 8889	r pkr. Swab iron s DS-30 w/ vac. Avergae 8400'.	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83 3/22/83 3/23/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I Ran rods &	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works nstalled wellhead. pump. Placed on p	ap. Rig 8964'. Is scal rted ac F.L. @ tring.	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The water inhibitor across fresh. The without the state of the without the state of the without the state of the state of the without the state of the without the state of the state	del "R" Baker ater w/ soap. 8617-8988. mped 7000 gal Freatment on s. End F.L. g. SN @ 8889	r pkr. Swab iron s DS-30 w/ vac. Avergae 8400'.	
17. Describe Propo work) SEE RUI 3/18/83 3/19/83 3/21/83 3/22/83 3/23/83	Pull ODI and Ran pkr to sulfide & t Set pkr @ 8 2000# rock rate 30 BPM POH w/ pkr @ 8889'. I Ran rods &	d install beam pum 8996'. Pick up to rash. Spot 110 ga 470'. Western sta salt and 200 balls . RU swab. Begin & layed down works nstalled wellhead. pump. Placed on p	ap. Rig 8964'. Is scal rted ac F.L. @ tring.	g up. Pull ODI. Ran mode Dump 150 bbls fresh water including the inhibitor across perfected job @ 8:30 AM and purshed w/ 32 bbls fresh. The water inhibitor across fresh. The without the state of the without the state of the without the state of the state of the without the state of the without the state of the state	del "R" Baker ater w/ soap. 8617-8988. mped 7000 gal Freatment on s. End F.L. g. SN @ 8889	r pkr. Swab iron s DS-30 w/ vac. Avergae 8400'.	

18. I hereby certify that the information above is true and complet	te to the best of my knowledge and belief.				
Day Day Coll Collet	Area Superintendent	DATE	March 28,	1983	
ORIGINAL SIGNED BY EDDIE SEAV	TITLE	DATE	MAR 30	1983	1

Mah 29 1983