NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.\$.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		E-1582
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1.		7. Unit Agreement Name
OIL X GAS WELL	OTHER-	
2. Name of Operator	field Company	8. Farm or Lease Name
Atlantic Richfield Company		Lea 403 State
P. O. Box 1978, Roswell, New Mexico 88201		9. Well No.
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER D 660 FEET FROM THE NORTH LINE AND 660 FEET FROM		Vacuum-Bone Sprin
THE West LINE, SECTION 22 TOWNSHIP 18-S RANGE 35-E NMPM.		
THE LINE, SECTIO	N TOWNSHIP RANGE NMPM	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	GR 3899'	Lea
16.		
	Appropriate Box To Indicate Nature of Notice, Report or Ot	
NOTICE OF IN	TENTION TO: SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	_
	OTHER	
OTHER	L	
17 Describe Proposed or Completed Op	erations (Clearly state all pertinent details, and give pertinent dates, including	r estimated date of starting any propose
work) SEE RULE 1103.	endicing to be any state and personality actions, and give personality actions, including	, costinuated date of statisting any propose
mbio wall boo bo	an abut in since Tule 1965 when produ	action from Bone
This well has been shut in since July, 1965, when production from Bone		
Spring perfs 8504-8514 was depleted. A 2000 gallon acid job in April,		
1966 failed to restore production. No recompletion possibilities exist		
and we propose to P & A as outlined below:		
Set 5km 17# CIRP	at 8470' and cap w/35' of cement.	
Load hole w/gel mud containing 25 sx/100 bbls.		
• •		
	cover 5½" csg from free point (TOC @ 75	75')
	cmt in & out of 5½" stub.	
Set 40 sx (100') cmt across 9-5/8" shoe at 4900'. Plug from 4950-4850'.		
	ver 9-5/8" from free point (TOC @ 1400'	
	cmt at 9-5/8" stub	-
	cmt across 13-3/8" shoe @ 330'. Plug	from 380-280!
		110m J00-200 .
Place 10 sx cmt	<del>-</del>	
Erect DHM. Clea	r and level location.	
	·	
18. I hereby certify that the information	above is true and complete to the best of my knowledge and belief.	
$n \wedge x \perp h$		
SIGNED C. W. SINOTCKE	Dist. Drlg. Supervisor	2/22/73
	ng Mirned b <b>y</b>	
J.	oe D. Ramey	DATE
	Dist. I, Supv.	
CONDITIONS OF APPROVAL, IF ANY:	10 7	
24 hi	- notice	
, and a second of the second o		