

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: State Section 27 Well No. 1
Field: Vacuum - South Devonian
County: Lea State: New Mexico

RECOMMENDED PROCEDURE:

- 1) Pull 2" tbg, Retrievable packer, and hydraulic pump from approx. 7000'
- 2) Pick up additional tbg and run cement retainer to top of Devonian perts.
- 3) Squeeze Devonian and cap retainer
- 4) Circulate hole to mud laden fluid and POH
- 5) Cut off and pull free 7 5/8" csg.
- 6) Run tbg 50' below cut off and spot 30 sk plug
- 7) Spot 10 sk plug @ surface
- 8) Cut off wellhead and install marker.

DMD 3/4/69