

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-125-13979
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Disposal		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Yale E. Key Inc.		6. State Oil & Gas Lease No.
3. Address of Operator P O Box 2040 Hobbs, NM		7. Lease Name or Unit Agreement Name: State "RA"
4. Well Location Unit Letter <u>K</u> : _____ feet from the _____ line and _____ feet from the _____ line Section <u>31</u> Township <u>18S</u> Range <u>36E</u> NMPM County <u>Lea</u>		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat San Andres Delaware

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:  
REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU pulling unit  
Release Baker lockset packer  
POH laying down tubing  
PU 2 7/8 work string RIH open ended to 4650'  
Circulate hole w/10# salt gel mud consisting of at least 9.5# brine and 25# of gel/bbl.  
Set cement plug from 4650'-4550' (1/2in 1/2out)  
POH 1000' WOC 6-8 hrs.  
RIH tag plug  
POH set plug @ 1950'-1850'  
POH set plug @ 400'-300'  
Cut off wellhead ; spot 10sk plug @ surface; Install dry hole marker: Clean locati

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Royce Crowell TITLE compliance specialist DATE 9/27/01

Type or print name Royce Crowell Telephone No. 393-9171

(This space for State use)  
APPROVED BY Harry W. Wink TITLE \_\_\_\_\_ DATE JAN 30 2003

Conditions of approval WINK  
OC FIELD REPRESENTATIVE II/STAFF MANAGER

GWW

