## STATE OF NEW MICKIGO ENERGY AND MINERALS DEPARTMENT

DO. OF COPIES ACCEIVED	7	
DISTRIBUTION	1	Ι
SANTA FE	+	
FILE	_	<b> </b>
U.1.G.1.		
LAND OFFICE	+	
OPERATOR	<del> </del>	

## OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

U.S.G.S.			5a. Indicate Type of Lease
OPERATOR			State Fee XX
			5, State Oil & Gas Lease No.
SUNDRY NOTI	CES AND REPORTS ON WELL OR TO DEEPEN OR PLUG BACK THE MIT - " (FORM C-101) FOR SUCH PRO	.LS	
··	HMIT -" (FORM C-101) FOR SUCH PRO	D A DIFFERENT RESERVOIR. POSALS.)	
OIL GAS WELL OTHER	· INJECTOR		7. Unit Agreement Name N. UODDS (C(CA)) UNIX
2. Name of Operator			N. HOBBS (G/SA) UNIT
SHELL WESTERN E&P INC.			SECTION 23
P. O. BOX 991, HOUSTON, TEXAS 77001		9. Well No.	
Location of well		· · · · · · · · · · · · · · · · · · ·	12] 10. Field and Pool, or Wildcot
UNIT LETTER E 1650	FEET FROM THE NORTH	NE AND 990	HOBBS (G/SA)
THE MLST LINE, SECTION 2	23 TOWNSHIP 18-S	RANGE37-F	_ NMPM. (())
	15. Elevation (Show whether DF, R	T, GR, etc.)	12. County
	3691' DF		LEA (((((()))))
Check Appropri	ate Box To Indicate Nature	of Notice, Report	or Other Data
NOTICE OF INTENTIO	יא דס:	SUBSEC	QUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON XX	IDIAL WORK	
TEMPORARILY ABANDON		VEHCE DRILLING OPNS.	ALTERING CASING
PULL OR ALTER CASING	[]	AD TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER	۰.	THER	
7. Describe Proposed or Completed Operations (C work) SEE RULE 1103.	learly state all pertinent details, ar	d give pertinent dates, in	cluding estimated date of starting any propose
·			
<ol> <li>Displace hole with mud</li> </ol>	laden fluid.		
2. Spot Class "C" neat ceme	ent plugs as follows:		•
Required			
Location of Plug	Base of Plug	Top of Plug	Approximate
Across Bowers	3685'	3450'	Cement Volume 43 sx
50' above & below base of salt	2830'	2730'	18 sx
UI Sail.			
300' above top of salt	1770'	14701	
300' above top of salt 10 sx at surface	1770' 58'	1470'	55 sx
300' above top of salt 10 sx at surface	58'	3'	10 sx
300' above top of salt 10 sx at surface	58'	3'	10 sx
300' above top of salt 10 sx at surface	58' surface, install P&A n	3' marker, clean and	10 sx d level location.
300' above top of salt 10 sx at surface	58' surface, install P&A n	3' marker, clean and in the contract of c	10 sx d level location. 24
300' above top of salt 10 sx at surface	58' surface, install P&A n	3' marker, clean and	10 sx d level location. 24
300' above top of salt 10 sx at surface 3. Cut casing off 3' below	58' surface, install P&A n	3' marker, clean and land second of C land second of C	10 sx d level location. 24
300' above top of salt 10 sx at surface 3. Cut casing off 3' below	58' surface, install P&A n	3' marker, clean and land second of C land second of C	10 sx d level location. 24
300' above top of salt 10 sx at surface  3. Cut casing off 3' below  Thereby certify that the information above is true.	58' Surface, install P&A n	3' narker, clean and	10 sx d level location. 24 37
300' above top of salt 10 sx at surface  3. Cut casing off 3' below  Thereby certify that the information above is true.	58' Surface, install P&A n	3' marker, clean and land second of C land second of C	10 sx d level location. 24 37

RECEIVED
JAN 9 1984

HOBBS OFFICE