

C.I.L CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name	
2. Name of Operator		N. HOBBS (G/SA) UNIT	
3. Address of Operator		8. Farm or Lease Name	
P. O. BOX 991, HOLSTON, TEXAS 77001		SECTION 23	
4. Location of Well		9. Well No.	
UNIT LETTER <u>B</u> <u>330</u> FEET FROM THE <u>NORTH</u> LINE AND <u>1650</u> FEET FROM		10. Field and Pool, or Wildcat	
THE <u>EAST</u> LINE, SECTION <u>23</u> TOWNSHIP <u>18-S</u> RANGE <u>37-E</u> NMPM.		HOBBS (G/SA)	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
3686' DF		LEA	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPMS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>PLUG BACK WITH HYDROMITE FOR WATER SHUT-OFF</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Place a 49' hydromite plug (45 gals) from 4265' to 4216'.
2. Wait for hydromite to gel. Tag new PBTD ( $\pm$  4220').
3. Install production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MARCH 15, 1984  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAR 20 1984  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
MAR 19 1984  
O.C.D.  
HOBBS UNIT